ENGINEERING BY
TRENCO
A MiTek Affiliate

Trenco
818 Soundside Rd
Edenton, NC 27932

Re: J0222-0517
Regency Homes/4 Avery Farm/Harnett

The truss drawing(s) referenced below have been prepared by Truss Engineering Co. under my direct supervision based on the parameters provided by Comtech, Inc - Fayetteville.

Pages or sheets covered by this seal: I50106913 thru I50106945

My license renewal date for the state of North Carolina is December 31, 2022.

North Carolina COA: C-0844


February 7,2022

Gilbert, Eric

**IMPORTANT NOTE:** The seal on these truss component designs is a certification that the engineer named is licensed in the jurisdiction(s) identified and that the designs comply with ANSI/TPI 1. These designs are based upon parameters shown (e.g., loads, supports, dimensions, shapes and design codes), which were given to MiTek or TRENCO. Any project specific information included is for MiTek's or TRENCO's customers file reference purpose only, and was not taken into account in the preparation of these designs. MiTek or TRENCO has not independently verified the applicability of the design parameters or the designs for any particular building. Before use, the building designer should verify applicability of design parameters and properly incorporate these designs into the overall building design per ANSI/TPI 1, Chapter 2.

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A1 | PIGGYBACK BASE | 5 | 1 | I50106913 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:01 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-8McAHil7WcLiLA1ICNZCTgIfQQj4YlXrl02fXznXPe

| -0-10-8 | 6-1-12 | 9-6-0 | 14-1-12 | 23-5-1 | 30-0-0 | 36-6-15 | 45-10-4 | 54-0-0 | 54-10-8 |
|---|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 6-1-12 | 3-4-4 | 4-7-12 | 9-3-5 | 6-6-15 | 6-6-15 | 9-3-5 | 8-1-12 | 0-10-8 |

Scale: 1/8"=1'




| 6-1-12 | 14-1-12 | 23-5-1 | 28-7-8 | 36-6-15 | 45-10-4 | 54-0-0 |
|---|---|---|---|---|---|---|
| 6-1-12 | 8-0-0 | 9-3-5 | 5-2-7 | 7-11-7 | 9-3-5 | 8-1-12 |

| **LOADING** (psf) | | **SPACING-** | 2-0-0 | **CSI.** | | **DEFL.** | in | (loc) | l/defl | L/d | **PLATES** | **GRIP** |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.84 | Vert(LL) | -0.13 | 19-21 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.60 | Vert(CT) | -0.29 | 19-21 | >928 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.42 | Horz(CT) | 0.09 | 12 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.10 | 19-21 | >999 | 240 | Weight: 391 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x6 SP No.1
WEBS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 4-4-7 oc purlins, except 2-0-0 oc purlins (5-9-15 max.): 4-22, 7-9.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing, Except: 6-0-0 oc bracing: 2-22.
WEBS 1 Row at midpt 5-19, 8-19, 8-16, 11-16

**REACTIONS.** (size) 22=0-3-8, 12=0-3-8, 18=0-3-8
Max Horz 22=255(LC 11)
Max Uplift 22=-168(LC 12), 12=-116(LC 13)
Max Grav 22=2292(LC 1), 12=1797(LC 1), 18=602(LC 18)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-748/770, 3-4=-683/741, 4-22=-3294/1075, 4-5=-2563/522, 5-7=-2084/591, 7-8=-1690/603, 8-9=-1748/609, 9-11=-2170/627, 11-12=-2899/655
BOT CHORD 2-22=-697/757, 21-22=-289/2121, 19-21=-289/2121, 18-19=-250/1831, 16-18=-250/1831, 14-16=-428/2357, 12-14=-428/2357
WEBS 5-21=0/356, 5-19=-691/180, 7-19=-37/507, 8-19=-430/218, 8-16=-333/229, 9-16=-81/561, 11-16=-826/271, 11-14=0/398, 3-22=-341/190

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) -0-6-3 to 4-10-10, Interior(1) 4-10-10 to 23-5-1, Exterior(2) 23-5-1 to 28-9-14, Interior(1) 28-9-14 to 36-6-15, Exterior(2) 36-6-15 to 41-11-12, Interior(1) 41-11-12 to 54-8-8 zone; cantilever left exposed ;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) All plates are 4x6 MT20 unless otherwise indicated.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) except (jt=lb) 22=168, 12=116.
8) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.


February 7,2022



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A1GE | GABLE | 1 | 1 | I50106914 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:03 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-4IjwiOmO2Dc0yfKQQdP1HulqlDEWYWTqI3V9kPznXPc

-0-10-8 9-6-0 23-5-1 36-6-15 54-0-0 54-10-8
0-10-8 9-6-0 13-11-1 13-1-14 17-5-1 0-10-8

Scale = 1:97.7




54-0-0
54-0-0

Plate Offsets (X,Y)-- [12:0-2-14,Edge], [16:0-3-0,0-3-12], [23:0-3-0,0-3-12], [27:0-2-14,Edge]

| LOADING (psf) | | SPACING- 2-0-0 | | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.10 | Vert(LL) | -0.00 | 34 | n/r | 120 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.07 | Vert(CT) | -0.00 | 34 | n/r | 120 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.15 | Horz(CT) | 0.01 | 34 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 511 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x6 SP No.1
WEBS 2x4 SP No.2
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins, except 2-0-0 oc purlins (6-0-0 max.): 7-62, 16-23.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing, Except: 6-0-0 oc bracing: 2-63,62-63.
WEBS T-Brace: 2x4 SPF No.2 - 18-51, 17-52, 15-53, 14-54 , 19-50, 20-48, 21-47, 22-46, 24-45, 25-44
Fasten (2X) T and I braces to narrow edge of web with 10d (0.131"x3") nails, 6in o.c.,with 3in minimum end distance.
Brace must cover 90% of web length.

**REACTIONS.** All bearings 54-0-0.
(lb) - Max Horz 2=326(LC 11)
Max Uplift All uplift 100 lb or less at joint(s) 2, 62, 34, 51, 52, 53, 54, 55, 56, 58, 59, 60, 61, 50, 48, 47, 46, 44, 43, 41, 40, 39, 38, 37 except 63=-136(LC 8), 36=-122(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 2, 62, 34, 51, 52, 53, 54, 55, 56, 58, 59, 60, 61, 50, 48, 47, 46, 45, 44, 43, 41, 40, 39, 38, 37, 36 except 63=459(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 13-14=-210/269, 14-15=-259/303, 15-16=-239/277, 16-17=-245/290, 17-18=-245/290, 18-19=-245/290, 19-20=-245/290, 20-21=-245/290, 21-22=-245/290, 22-23=-245/290, 23-24=-239/277, 24-25=-259/297, 33-34=-261/183
WEBS 3-63=-315/369

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) gable end zone and C-C Corner(3) -0-6-3 to 5-0-0, Exterior(2) 5-0-0 to 23-5-1, Corner(3) 23-5-1 to 29-0-0, Exterior(2) 29-0-0 to 36-6-15, Corner(3) 36-6-15 to 41-11-12, Exterior(2) 41-11-12 to 54-8-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Truss designed for wind loads in the plane of the truss only. For studs exposed to wind (normal to the face), see Standard Industry Gable End Details as applicable, or consult qualified building designer as per ANSI/TPI 1.
4) Provide adequate drainage to prevent water ponding.
5) All plates are 2x4 MT20 unless otherwise indicated.
6) Gable requires continuous bottom chord bearing.
7) Gable studs spaced at 2-0-0 oc.
8) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
9) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
10) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 2, 62, 34, 51, 52, 53, 54, 55, 56, 58, 59, 60, 61, 50, 48, 47, 46, 44, 43, 41, 40, 39, 38, 37 except (jt=lb) 63=136, 36=122.

NORTH CAROLINA PROFESSIONAL SEAL 036322 ENGINEER ERIC A. GILBERT

February 7,2022

Continued on page 2



ENGINEERING BY TRENCO A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

**NOTES-**

11) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
12) Warning: Additional permanent and stability bracing for truss system (not part of this component design) is always required.

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A2 | ROOF TRUSS | 1 | 1 | I50106915 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:05 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-07rg73oeZqskByUoX2RVNJq5O1n?0KD7mM_FolznXPa

| -0-10-8 | 9-6-0 | 14-1-12 | 23-5-1 | 30-0-0 | 36-6-15 | 45-10-4 | 54-0-0 | 54-10-8 |
|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 9-6-0 | 4-7-12 | 9-3-5 | 6-6-15 | 6-6-15 | 9-3-5 | 8-1-12 | 0-10-8 |

Scale: 1/8"=1'




| 6-0-0 | 14-1-12 | 21-1-12 | 28-5-12 | 38-4-4 | 45-10-4 | 54-0-0 |
|---|---|---|---|---|---|---|
| 6-0-0 | 8-1-12 | 7-0-0 | 7-4-0 | 9-10-8 | 7-6-0 | 8-1-12 |

| **LOADING** (psf) | | **SPACING-** | 2-0-0 | **CSI.** | | **DEFL.** | in | (loc) | l/defl | L/d | **PLATES** | **GRIP** |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.41 | Vert(LL) | -0.09 | 15-18 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.64 | Vert(CT) | -0.20 | 15-18 | >999 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.52 | Horz(CT) | 0.03 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.06 | 15-18 | >999 | 240 | Weight: 682 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x6 SP No.1 |
| BOT CHORD | 2x12 SP 2400F 2.0E *Except* |
| | 2-22: 2x8 SP No.1, 20-22: 2x12 SP No.1 |
| WEBS | 2x4 SP No.2 *Except* |
| | 6-21,10-18,10-24,6-24,8-27,19-27: 2x6 SP No.1 |
| OTHERS | 2x12 SP 2400F 2.0E |
| LBR SCAB | 16-19 2x12 SP 2400F 2.0E both sides |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 4-9-9 oc purlins, except 2-0-0 oc purlins (6-0-0 max.): 3-23, 7-9. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing, Except: 6-0-0 oc bracing: 2-23. |
| WEBS | 1 Row at midpt 12-18, 6-21, 10-27, 19-27 |
| JOINTS | 1 Brace at Jt(s): 25, 27 |

**REACTIONS.** All bearings 0-3-8.
(lb) - Max Horz 23=254(LC 11)
Max Uplift All uplift 100 lb or less at joint(s) except 21=-198(LC 9), 23=-135(LC 8)
Max Grav All reactions 250 lb or less at joint(s) except 21=496(LC 24), 19=2361(LC 2), 23=1839(LC 1), 13=1607(LC 21)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-869/1036, 3-23=-2667/751, 3-4=-1827/0, 4-6=-1618/86, 6-7=-460/55, 7-8=-348/45, 8-9=-348/45, 9-10=-490/67, 10-12=-1595/98, 12-13=-2574/135 |
| BOT CHORD | 2-23=-942/902, 22-23=0/1518, 21-22=0/1521, 19-21=0/1251, 18-19=0/1251, 15-18=0/2085, 13-15=0/2085 |
| WEBS | 4-21=-453/157, 12-18=-1039/250, 12-15=0/622, 6-21=-201/408, 10-18=-30/257, 6-25=-1090/169, 25-27=-1083/172, 26-27=-1083/172, 10-26=-1104/164, 8-27=-514/249, 19-27=-799/71 |


**NOTES-**

1) Attached 16-0-0 scab 16 to 19, both face(s) 2x12 SP 2400F 2.0E with 2 row(s) of 10d (0.131"x3") nails spaced 9" o.c.except : starting at 0-4-8 from end at joint 19, nail 2 row(s) at 4" o.c. for 2-0-0; starting at 14-0-0 from end at joint 19, nail 2 row(s) at 7" o.c. for 2-0-0.
2) Unbalanced roof live loads have been considered for this design.
3) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) -0-6-3 to 4-10-10, Interior(1) 4-10-10 to 23-5-1, Exterior(2) 23-5-1 to 28-8-8, Interior(1) 28-8-8 to 36-6-15, Exterior(2) 36-6-15 to 41-11-12, Interior(1) 41-11-12 to 54-8-8 zone; cantilever left exposed ;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
4) Provide adequate drainage to prevent water ponding.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
7) Ceiling dead load (10.0 psf) on member(s). 6-25, 25-27, 26-27, 10-26; Wall dead load (5.0psf) on member(s).6-21, 10-18, 19-27
8) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 19-21, 18-19
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 198 lb uplift at joint 21 and 135 lb uplift at joint 23.
10) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
11) Attic room checked for L/360 deflection.

February 7,2022




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A2X | ROOF TRUSS | 0 | 1 | I50106916 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:06 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-UKP3KPpGK8_bp62_5lykvXNC6R5YlmnG_0kpLkznXPZ

| -0-10-8 | 9-6-0 | 14-1-12 | 23-5-1 | 28-5-12 | 36-6-15 | 45-10-4 | 54-0-0 | 54-10-8 |
|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 9-6-0 | 4-7-12 | 9-3-5 | 5-0-11 | 8-1-3 | 9-3-5 | 8-1-12 | 0-10-8 |

Scale: 1/8"=1'




| 6-0-0 | 14-1-12 | 21-1-12 | 28-5-12 | 38-4-4 | 45-10-4 | 54-0-0 |
|---|---|---|---|---|---|---|
| 6-0-0 | 8-1-12 | 7-0-0 | 7-4-0 | 9-10-8 | 7-6-0 | 8-1-12 |

| **LOADING** (psf) | | **SPACING-** 2-0-0 | | **CSI.** | | **DEFL.** | in | (loc) | l/defl | L/d | **PLATES** | **GRIP** |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.60 | Vert(LL) | -0.26 | 18 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.81 | Vert(CT) | -0.57 | 15-18 | >531 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.63 | Horz(CT) | 0.32 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | Wind(LL) | 0.11 | 15-18 | >999 | 240 | Weight: 648 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x6 SP No.1 |
| BOT CHORD | 2x12 SP 2400F 2.0E *Except* 2-21: 2x8 SP No.1, 20-21: 2x12 SP No.1 |
| WEBS | 2x4 SP No.2 *Except* 6-20,10-18,10-23,6-23,8-26,19-26: 2x6 SP No.1 |
| OTHERS | 2x12 SP No.1 |
| LBR SCAB | 16-19 2x12 SP No.1 both sides |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 5-6-7 oc purlins, except 2-0-0 oc purlins (10-0-0 max.): 3-22, 7-9. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing, Except: 6-0-0 oc bracing: 2-22. |
| WEBS | 1 Row at midpt 12-18, 6-20, 10-18, 10-26, 19-26 |
| JOINTS | 1 Brace at Jt(s): 24, 26 |

**REACTIONS.** All bearings 0-3-8.
(lb) - Max Horz 22=254(LC 11)
Max Uplift All uplift 100 lb or less at joint(s) 13 except 20=-162(LC 9), 22=-310(LC 8)
Max Grav All reactions 250 lb or less at joint(s) except 20=714(LC 20), 19=2349(LC 27), 22=1202(LC 24), 13=1201(LC 21)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-857/1080, 3-22=-1527/974, 3-4=-654/263, 4-6=-330/340, 6-7=-23/447, 7-8=0/427, 8-9=0/427, 9-10=0/434, 10-12=-366/372, 12-13=-1945/282 |
| BOT CHORD | 2-22=-985/890, 21-22=-104/419, 20-21=-101/423, 15-18=-107/1550, 13-15=-107/1550 |
| WEBS | 4-20=-522/125, 12-18=-1846/127, 12-15=0/1385, 6-20=-419/155, 4-21=0/265, 10-18=-509/0, 6-24=-580/291, 24-26=-586/291, 25-26=-586/291, 10-25=-558/294, 8-26=-636/229, 19-26=-1109/22 |

**NOTES-**
1) Attached 16-0-0 scab 16 to 19, both face(s) 2x12 SP No.1 with 2 row(s) of 10d (0.131"x3") nails spaced 9" o.c.except : starting at 0-4-8 from end at joint 19, nail 2 row(s) at 4" o.c. for 2-0-0; starting at 14-0-0 from end at joint 19, nail 3 row(s) at 4" o.c. for 2-0-0.
2) Unbalanced roof live loads have been considered for this design.
3) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) -0-6-3 to 4-10-10, Interior(1) 4-10-10 to 23-5-1, Exterior(2) 23-5-1 to 28-8-8, Interior(1) 28-8-8 to 36-6-15, Exterior(2) 36-6-15 to 41-11-12, Interior(1) 41-11-12 to 54-8-8 zone; cantilever left exposed ;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
4) Provide adequate drainage to prevent water ponding.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
7) Ceiling dead load (10.0 psf) on member(s). 6-24, 24-26, 25-26, 10-25; Wall dead load (5.0psf) on member(s).10-18, 19-26
8) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 18-19
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 13 except (jt=lb) 20=162, 22=310.
10) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
11) Attic room checked for L/360 deflection.


February 7,2022



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A3 | ROOF TRUSS | 3 | 1 | I50106917 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:07 2022 Page 1
ID:mHVPtvPrlWfejLZnULY80lyxYfS-yWzRYlpu5S6RQGdBfTUzSkvQqqS?UE3QDgTMtAznXPY

| -0-10-8 | 9-6-0 | 14-1-12 | 23-5-1 | 30-0-0 | 36-6-15 | 38-4-4 | 45-10-4 | 54-0-0 | 54-10-8 |
|---|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 9-6-0 | 4-7-12 | 9-3-5 | 6-6-15 | 6-6-15 | 1-9-5 | 7-6-0 | 8-1-12 | 0-10-8 |

Scale: 1/8"=1'




| 6-0-0 | 14-1-12 | 21-1-12 | 28-5-12 | 38-4-4 | 45-10-4 | 46-0-0 | 54-0-0 |
|---|---|---|---|---|---|---|---|
| 6-0-0 | 8-1-12 | 7-0-0 | 7-4-0 | 9-10-8 | 7-6-0 | 0-1-12 | 8-0-0 |

| **LOADING** (psf) | | **SPACING-** 2-0-0 | | **CSI.** | | **DEFL.** | in | (loc) | l/defl | L/d | **PLATES** | **GRIP** |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.41 | Vert(LL) | -0.03 | 17-18 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.67 | Vert(CT) | -0.07 | 17-18 | >999 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.56 | Horz(CT) | 0.01 | 15 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | Wind(LL) | -0.02 | 21-22 | >999 | 240 | Weight: 529 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x12 SP 2400F 2.0E *Except*
2-21: 2x8 SP No.1, 19-21: 2x12 SP No.1
WEBS 2x4 SP No.2 *Except*
6-20,10-17,10-23,6-23,8-26,18-26: 2x6 SP No.1

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins, except 2-0-0 oc purlins (6-0-0 max.): 3-22, 7-9.
BOT CHORD Rigid ceiling directly applied or 6-0-0 oc bracing.
WEBS 1 Row at midpt 6-20, 10-17, 10-26, 18-26
JOINTS 1 Brace at Jt(s): 24, 26

**REACTIONS.** All bearings 0-3-8.
(lb) - Max Horz 22=254(LC 11)
Max Uplift All uplift 100 lb or less at joint(s) 20 except 22=-172(LC 8)
Max Grav All reactions 250 lb or less at joint(s) except 20=984(LC 20), 15=1902(LC 21), 18=1796(LC 27), 22=1408(LC 24)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-880/1057, 3-22=-1889/537, 3-4=-1033/0, 4-6=-811/20, 6-7=-493/15, 7-8=-362/4, 8-9=-362/4, 9-10=-477/19, 10-12=-793/0, 12-13=-469/617
BOT CHORD 2-22=-963/912, 21-22=0/905, 20-21=0/908, 18-20=0/610, 17-18=0/610, 15-17=-439/506, 13-15=-439/506
WEBS 4-20=-490/154, 12-17=-12/1079, 12-15=-1594/335, 6-20=-435/302, 10-17=-486/202, 6-24=-367/79, 24-26=-357/83, 25-26=-357/83, 10-25=-374/79, 8-26=-489/249, 18-26=-737/73

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) -0-6-3 to 4-10-10, Interior(1) 4-10-10 to 23-5-1, Exterior(2) 23-5-1 to 28-8-8, Interior(1) 28-8-8 to 36-6-15, Exterior(2) 36-6-15 to 41-11-12, Interior(1) 41-11-12 to 54-8-8 zone; cantilever left and right exposed ;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Ceiling dead load (10.0 psf) on member(s). 6-24, 24-26, 25-26, 10-25; Wall dead load (5.0psf) on member(s).6-20, 10-17, 18-26
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 18-20, 17-18
8) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 20 except (jt=lb) 22=172.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
10) Attic room checked for L/360 deflection.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A3X | ROOF TRUSS | 0 | 1 | I50106918 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:08 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-RiXpl5qWsIEI2QCNCA?C_ySbYEorDbxZSKDwPdznXPX

| -0-10-8 | 9-6-0 | 14-1-12 | 23-5-1 | 30-0-0 | 36-6-15 | 45-10-4 | 54-0-0 | 54-10-8 |
|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 9-6-0 | 4-7-12 | 9-3-5 | 6-6-15 | 6-6-15 | 9-3-5 | 8-1-12 | 0-10-8 |

Scale: 1/8"=1'




| 6-0-0 | 14-1-12 | 21-1-12 | 28-5-12 | 38-4-4 | 45-10-4 | 46-0-0 | 54-0-0 |
|---|---|---|---|---|---|---|---|
| 6-0-0 | 8-1-12 | 7-0-0 | 7-4-0 | 9-10-8 | 7-6-0 | 0-1-12 | 8-0-0 |

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.41 | Vert(LL) | -0.21 | 17-18 | >982 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.70 | Vert(CT) | -0.42 | 17-18 | >493 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.90 | Horz(CT) | 0.48 | 18 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | -0.09 | 17 | >999 | 240 | Weight: 495 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x6 SP No.1 |
| BOT CHORD | 2x12 SP 2400F 2.0E *Except* |
| | 2-21: 2x8 SP No.1, 20-21: 2x12 SP No.1 |
| WEBS | 2x4 SP No.2 *Except* |
| | 6-20,10-17,10-23,6-23,8-26,18-26: 2x6 SP No.1 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 6-0-0 oc purlins, except 2-0-0 oc purlins (6-0-0 max.): 3-22, 7-9. |
| BOT CHORD | Rigid ceiling directly applied or 6-0-0 oc bracing. |
| WEBS | 1 Row at midpt 6-20, 10-17, 10-26, 18-26 |
| JOINTS | 1 Brace at Jt(s): 24, 26 |

**REACTIONS.** All bearings 0-3-8.
(lb) - Max Horz 22=254(LC 11)
Max Uplift All uplift 100 lb or less at joint(s) except 20=-148(LC 9), 15=-145(LC 13), 22=-309(LC 8)
Max Grav All reactions 250 lb or less at joint(s) except 20=782(LC 20), 15=1672(LC 25), 18=1737(LC 23), 22=1203(LC 24)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-857/1078, 3-22=-1527/972, 3-4=-655/261, 4-6=-329/339, 6-7=-190/383, 7-8=-118/342, 8-9=-119/342, 9-10=-178/421, 10-12=-365/358, 12-13=-560/541 |
| BOT CHORD | 2-22=-983/890, 21-22=-103/421, 20-21=-100/425, 15-17=-403/588, 13-15=-403/588 |
| WEBS | 4-20=-528/124, 12-17=-700/480, 12-15=-1085/1002, 6-20=-463/156, 4-21=0/264, 10-17=-583/57, 6-24=-285/181, 24-26=-280/177, 25-26=-280/177, 10-25=-274/204, 8-26=-561/176, 18-26=-946/0 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) -0-6-3 to 4-10-10, Interior(1) 4-10-10 to 23-5-1, Exterior(2) 23-5-1 to 28-8-8, Interior(1) 28-8-8 to 36-6-15, Exterior(2) 36-6-15 to 41-11-12, Interior(1) 41-11-12 to 54-8-8 zone; cantilever left and right exposed ;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Ceiling dead load (10.0 psf) on member(s). 6-24, 24-26, 25-26, 10-25; Wall dead load (5.0psf) on member(s).10-17, 18-26
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 17-18
8) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 148 lb uplift at joint 20, 145 lb uplift at joint 15 and 309 lb uplift at joint 22.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
10) Attic room checked for L/360 deflection.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A4 | ROOF TRUSS | 3 | 1 | I50106919 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:09 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-vv4BzRr9d3M9ganZmuWRX9?mne3Ny4Hjh_yTy3znXPW

| -0-10-8 | 9-6-0 | 14-1-12 | 23-5-1 | 30-0-0 | 36-6-15 | 38-4-4 | 45-10-4 | 54-0-0 | 54-10-8 |
|---|---|---|---|---|---|---|---|---|---|
| 0-10-8 | 9-6-0 | 4-7-12 | 9-3-5 | 6-6-15 | 6-6-15 | 1-9-5 | 7-6-0 | 8-1-12 | 0-10-8 |

Scale = 1:97.2




| 6-0-0 | 14-1-12 | 21-1-12 | 28-5-12 | 38-4-4 | 45-10-4 | 46-0-0 | 54-0-0 |
|---|---|---|---|---|---|---|---|
| 6-0-0 | 8-1-12 | 7-0-0 | 7-4-0 | 9-10-8 | 7-6-0 | 0-1-12 | 8-0-0 |

| **LOADING** (psf) | | **SPACING-** | 2-0-0 | **CSI.** | | **DEFL.** | in | (loc) | l/defl | L/d | **PLATES** | **GRIP** |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.44 | Vert(LL) | -0.24 | 20-21 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 1.00 | Vert(CT) | -0.50 | 20-21 | >543 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.77 | Horz(CT) | 0.02 | 15 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.21 | 20-21 | >999 | 240 | Weight: 486 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x6 SP No.1 |
| BOT CHORD | 2x8 SP No.1 *Except* |
| | 16-19,19-21: 2x12 SP No.1 |
| WEBS | 2x4 SP No.2 *Except* |
| | 6-20,10-17,10-23,6-23,8-26: 2x6 SP No.1 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 5-5-7 oc purlins, except 2-0-0 oc purlins (5-8-1 max.): 3-22, 7-9. |
| BOT CHORD | Rigid ceiling directly applied or 2-2-0 oc bracing. |
| WEBS | 1 Row at midpt 4-20, 6-20, 10-17, 10-26 |
| JOINTS | 1 Brace at Jt(s): 24, 26 |

**REACTIONS.** (size) 15=0-3-8, 22=0-3-8, 18=0-3-8
Max Horz 22=255(LC 11)
Max Uplift 22=-76(LC 8)
Max Grav 15=2117(LC 25), 22=1831(LC 1), 18=2021(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 2-3=-877/1037, 3-22=-2743/654, 3-4=-1770/0, 4-6=-1081/12, 6-7=-1587/296, 7-8=-1386/254, 8-9=-1386/254, 9-10=-1586/289, 10-12=-1048/0, 12-13=-483/718 |
| BOT CHORD | 2-22=-943/910, 21-22=0/1629, 20-21=0/1643, 18-20=0/856, 17-18=0/856, 15-17=-504/504, 13-15=-504/500 |
| WEBS | 4-20=-1072/189, 12-17=-63/1483, 12-15=-1962/409, 6-20=-599/357, 4-21=0/722, 10-17=-648/250, 6-24=-311/684, 24-26=-311/730, 25-26=-311/730, 10-25=-322/645, 7-24=-69/515, 9-25=-2/466 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) -0-6-3 to 4-10-10, Interior(1) 4-10-10 to 23-5-1, Exterior(2) 23-5-1 to 28-8-8, Interior(1) 28-8-8 to 36-6-15, Exterior(2) 36-6-15 to 41-11-12, Interior(1) 41-11-12 to 54-8-8 zone; cantilever left and right exposed ;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Ceiling dead load (10.0 psf) on member(s). 6-24, 24-26, 25-26, 10-25; Wall dead load (5.0psf) on member(s).6-20, 10-17
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 18-20, 17-18
8) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 76 lb uplift at joint 22.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
10) Attic room checked for L/360 deflection.


February 7,2022



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A5 | ROOF TRUSS | 1 | 1 | I50106920 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:10 2022 Page 1
ID:mHVPtvPrlWfejLZnULY80IyxYfS-N5eZAnsnONU0HkMmKb1g3NXwP2WehXHsvei0UVznXPV

| 8-1-12 | 13-0-8 | 15-0-12 | 17-5-1 | 22-5-12 | 24-0-0 | 30-6-15 | 32-4-4 | 35-2-9 | 39-10-4 | 48-0-0 | 48-10-8 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 8-1-12 | 4-10-12 | 2-0-4 | 2-4-5 | 5-0-11 | 1-6-4 | 6-6-15 | 1-9-5 | 2-10-5 | 4-7-11 | 8-1-12 | 0-10-8 |

Scale = 1:84.8




| 8-1-12 | 13-0-8 | 15-0-12 | 22-4-0 | 32-4-4 | 39-10-4 | 48-0-0 |
|---|---|---|---|---|---|---|
| 8-1-12 | 4-10-12 | 2-0-4 | 7-3-4 | 10-0-4 | 7-6-0 | 8-1-12 |

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.45 | Vert(LL) | -0.06 | 15-16 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.55 | Vert(CT) | -0.09 | 15-16 | >999 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.79 | Horz(CT) | 0.02 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.02 | 1-20 | >999 | 240 | Weight: 421 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x6 SP No.1 |
| BOT CHORD | 2x8 SP No.1 *Except* 14-17,17-20: 2x10 SP No.1 |
| WEBS | 2x4 SP No.2 *Except* 8-15,8-21,4-18,6-24,4-21: 2x6 SP No.1 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 5-9-9 oc purlins, except 2-0-0 oc purlins (5-6-15 max.): 5-7. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing, Except: 6-0-0 oc bracing: 13-15,11-13. |
| WEBS | 1 Row at midpt 2-18, 8-15, 4-18 |
| JOINTS | 1 Brace at Jt(s): 22, 24 |

**REACTIONS.** All bearings 0-3-8 except (jt=length) 1=Mechanical, 19=0-4-15.
(lb) - Max Horz 1=-253(LC 10)
Max Uplift All uplift 100 lb or less at joint(s) except 19=-104(LC 9)
Max Grav All reactions 250 lb or less at joint(s) except 1=916(LC 21), 13=2194(LC 27), 19=1137(LC 20), 16=1344(LC 18)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

| | |
|---|---|
| TOP CHORD | 1-2=-1396/0, 2-4=-1115/40, 4-5=-1661/339, 5-6=-1420/296, 6-7=-1420/296, 7-8=-1570/321, 8-10=-1078/0, 10-11=-472/683 |
| BOT CHORD | 1-20=0/1064, 19-20=0/1063, 18-19=0/1061, 16-18=0/857, 15-16=0/857, 13-15=-473/492, 11-13=-473/488 |
| WEBS | 2-18=-461/199, 10-13=-2003/405, 8-15=-583/242, 10-15=-50/1464, 4-22=-322/734, 22-24=-322/785, 23-24=-322/785, 8-23=-336/717, 5-22=-90/576, 7-23=-3/369, 4-18=-629/356 |

**NOTES-**

1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-1-4 to 4-10-14, Interior(1) 4-10-14 to 17-5-1, Exterior(2) 17-5-1 to 24-2-8, Interior(1) 24-2-8 to 30-6-15, Exterior(2) 30-6-15 to 37-4-6, Interior(1) 37-4-6 to 48-8-8 zone; cantilever right exposed ;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Ceiling dead load (10.0 psf) on member(s). 4-22, 22-24, 23-24, 8-23; Wall dead load (5.0psf) on member(s).8-15, 4-18
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 16-18, 15-16
8) Refer to girder(s) for truss to truss connections.
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 104 lb uplift at joint 19.
10) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
11) Attic room checked for L/360 deflection.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A6 | ROOF TRUSS | 1 | 1 | I50106921 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:12 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-JUmKbTt1w_kkX1W8R0389odGsr6q9UC9NyB7YOznXPT




Plate Offsets (X,Y)-- [15:0-5-0,0-7-8]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.46 | Vert(LL) | -0.40 | 15-17 | >736 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.95 | Vert(CT) | -0.61 | 15-17 | >484 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.63 | Horz(CT) | 0.02 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.02 | 15-17 | >999 | 240 | Weight: 421 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x8 SP No.1 *Except*
14-16: 2x10 SP No.1, 16-18: 2x10 SP 2400F 2.0E
WEBS 2x4 SP No.2 *Except*
8-15,8-19,4-17,6-22,4-19: 2x6 SP No.1

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 5-8-12 oc purlins, except
2-0-0 oc purlins (5-6-4 max.): 5-7.
BOT CHORD Rigid ceiling directly applied or 2-2-0 oc bracing.
WEBS 1 Row at midpt 2-17, 10-13, 8-15, 8-22, 4-17
JOINTS 1 Brace at Jt(s): 20, 22

**REACTIONS.** (size) 1=Mechanical, 17=0-4-15, 13=0-3-8
Max Horz 1=-253(LC 10)
Max Grav 1=1099(LC 21), 17=1740(LC 20), 13=2590(LC 27)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-1685/0, 2-4=-1639/0, 4-5=-1685/325, 5-6=-1450/280, 6-7=-1450/280, 7-8=-1602/303, 8-10=-1602/0, 10-11=-459/708
BOT CHORD 1-18=0/1385, 17-18=0/1380, 15-17=0/1305, 13-15=-492/483, 11-13=-492/477
WEBS 2-18=-357/174, 2-17=-496/336, 10-13=-2637/273, 8-15=-456/297, 10-15=0/2060, 4-20=-416/572, 20-22=-408/624, 21-22=-408/624, 8-21=-447/556, 5-20=-90/589, 7-21=0/400, 4-17=-532/411

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-1-4 to 4-10-14, Interior(1) 4-10-14 to 17-5-1, Exterior(2) 17-5-1 to 24-2-8, Interior(1) 24-2-8 to 30-6-15, Exterior(2) 30-6-15 to 37-4-6, Interior(1) 37-4-6 to 48-8-8 zone; cantilever right exposed ;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Ceiling dead load (10.0 psf) on member(s). 4-20, 20-22, 21-22, 8-21; Wall dead load (5.0psf) on member(s).8-15, 4-17
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 15-17
8) Refer to girder(s) for truss to truss connections.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
10) Attic room checked for L/360 deflection.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A7 | ROOF TRUSS | 1 | 1 | I50106922 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:13 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-ngKiopufhIsb8B5L?jbNh?9RbFS3uxSIbcwh5qznXPS

| 8-1-12 | 13-0-8 | 15-0-12 | 17-5-1 | 22-5-12 | 24-0-0 | 30-6-15 | 32-4-4 | 35-2-9 | 39-10-4 | 48-0-0 | 48-10-8 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 8-1-12 | 4-10-12 | 2-0-4 | 2-4-5 | 5-0-11 | 1-6-4 | 6-6-15 | 1-9-5 | 2-10-5 | 4-7-11 | 8-1-12 | 0-10-8 |

Scale = 1:84.8




| 8-1-12 | 13-0-8 | 15-0-12 | 15-1-12 | 32-4-4 | 39-10-4 | 48-0-0 |
|---|---|---|---|---|---|---|
| 8-1-12 | 4-10-12 | 2-0-4 | 0-1-0 | 17-2-8 | 7-6-0 | 8-1-12 |

Plate Offsets (X,Y)-- [15:0-5-0,0-7-8]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.46 | Vert(LL) | -0.40 | 15-17 | >736 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.95 | Vert(CT) | -0.61 | 15-17 | >484 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.63 | Horz(CT) | 0.02 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.02 | 15-17 | >999 | 240 | Weight: 421 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x8 SP No.1 *Except*
14-16: 2x10 SP No.1, 16-18: 2x10 SP 2400F 2.0E
WEBS 2x4 SP No.2 *Except*
8-15,8-19,4-17,6-22,4-19: 2x6 SP No.1

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 5-8-12 oc purlins, except
2-0-0 oc purlins (5-6-4 max.): 5-7.
BOT CHORD Rigid ceiling directly applied or 2-2-0 oc bracing.
WEBS 1 Row at midpt 2-17, 10-13, 8-15, 8-22, 4-17
JOINTS 1 Brace at Jt(s): 20, 22

**REACTIONS.** (size) 1=Mechanical, 17=0-3-8, 13=0-3-8
Max Horz 1=-253(LC 10)
Max Grav 1=1099(LC 21), 17=1740(LC 20), 13=2590(LC 27)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-1685/0, 2-4=-1639/0, 4-5=-1685/325, 5-6=-1450/280, 6-7=-1450/280, 7-8=-1602/303, 8-10=-1602/0, 10-11=-459/708
BOT CHORD 1-18=0/1385, 17-18=0/1380, 15-17=0/1305, 13-15=-492/483, 11-13=-492/477
WEBS 2-18=-357/174, 2-17=-496/336, 10-13=-2637/273, 8-15=-456/297, 10-15=0/2060, 4-20=-416/572, 20-22=-408/624, 21-22=-408/624, 8-21=-447/556, 5-20=-90/589, 7-21=0/400, 4-17=-532/411

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-1-4 to 4-10-14, Interior(1) 4-10-14 to 17-5-1, Exterior(2) 17-5-1 to 24-2-8, Interior(1) 24-2-8 to 30-6-15, Exterior(2) 30-6-15 to 37-4-6, Interior(1) 37-4-6 to 48-8-8 zone; cantilever right exposed ;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Ceiling dead load (10.0 psf) on member(s). 4-20, 20-22, 21-22, 8-21; Wall dead load (5.0psf) on member(s).8-15, 4-17
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 15-17
8) Refer to girder(s) for truss to truss connections.
9) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
10) Attic room checked for L/360 deflection.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A8 | ROOF TRUSS | 4 | 1 | I50106923 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:14 2022 Page 1
ID:mHVPtvPrlWfejLZnULY80lyxYfS-Fsu408vHSb_SmLgXZR6cEDic6fo6dLnSqGgEdGznXPR




Plate Offsets (X,Y)-- [15:0-8-8,0-2-4], [17:0-4-0,0-5-12]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.47 | Vert(LL) | -0.31 | 15-17 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.83 | Vert(CT) | -0.55 | 15-17 | >714 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.82 | Horz(CT) | 0.09 | 11 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.10 | 15 | >999 | 240 | Weight: 442 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x8 SP No.1 *Except*
14-16: 2x12 SP No.1, 16-18: 2x12 SP 2400F 2.0E
WEBS 2x4 SP No.2 *Except*
8-15,8-19,4-17,6-22,4-19: 2x6 SP No.1

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 3-8-0 oc purlins, except 2-0-0 oc purlins (5-1-4 max.): 5-7.
BOT CHORD Rigid ceiling directly applied or 9-6-0 oc bracing.
WEBS 1 Row at midpt 10-15, 8-22
JOINTS 1 Brace at Jt(s): 20, 22

**REACTIONS.** (size) 1=Mechanical, 17=0-3-8, 11=0-3-8
Max Horz 1=-253(LC 10)
Max Uplift 17=-145(LC 9)
Max Grav 1=2123(LC 21), 17=977(LC 26), 11=2512(LC 21)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-3664/207, 2-4=-3801/124, 4-5=-1898/356, 5-6=-1681/314, 6-7=-1680/314, 7-8=-1875/344, 8-10=-3757/110, 10-11=-4167/181
BOT CHORD 1-18=-42/2962, 17-18=-41/2956, 15-17=0/3121, 13-15=-40/3425, 11-13=-40/3422
WEBS 2-18=-486/63, 2-17=-261/475, 10-13=-59/304, 8-15=0/1121, 10-15=-626/293, 4-20=-1863/0, 20-22=-1818/0, 21-22=-1818/0, 8-21=-1923/0, 5-20=-96/640, 7-21=-21/584, 4-17=0/1091

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-1-4 to 4-10-14, Interior(1) 4-10-14 to 17-5-1, Exterior(2) 17-5-1 to 24-2-8, Interior(1) 24-2-8 to 30-6-15, Exterior(2) 30-6-15 to 37-4-6, Interior(1) 37-4-6 to 48-8-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Ceiling dead load (10.0 psf) on member(s). 4-20, 20-22, 21-22, 8-21; Wall dead load (5.0psf) on member(s).8-15, 4-17
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 15-17
8) Refer to girder(s) for truss to truss connections.
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 145 lb uplift at joint 17.
10) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
11) Attic room checked for L/360 deflection.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A9 | ROOF TRUSS | 3 | 1 | I50106924 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:15 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-k2SSDUwwDv6JOVEj78drmQFnq39qMprb3wPn9jznXPQ

| 8-1-12 | 13-0-8 | 15-0-12 | 17-5-1 | 22-5-12 | 24-0-0 | 30-6-15 | 32-4-4 | 35-2-9 | 39-10-4 | 48-0-0 | 48-10-8 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 8-1-12 | 4-10-12 | 2-0-4 | 2-4-5 | 5-0-11 | 1-6-4 | 6-6-15 | 1-9-5 | 2-10-5 | 4-7-11 | 8-1-12 | 0-10-8 |

Scale = 1:84.3




| 8-1-12 | 13-0-8 | 15-0-12 | 19-0-0 | 30-6-15 | 32-4-4 | 39-10-4 | 48-0-0 |
|---|---|---|---|---|---|---|---|
| 8-1-12 | 4-10-12 | 2-0-4 | 3-11-4 | 11-6-15 | 1-9-5 | 7-6-0 | 8-1-12 |

Plate Offsets (X,Y)-- [18:0-4-0,0-5-12]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.47 | Vert(LL) | -0.30 | 15-17 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.80 | Vert(CT) | -0.54 | 15-17 | >642 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.76 | Horz(CT) | 0.08 | 11 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.13 | 15 | >999 | 240 | Weight: 442 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x8 SP No.1 *Except*
14-16,16-19: 2x12 SP No.1
WEBS 2x4 SP No.2 *Except*
8-15,8-20,4-18,6-23,4-20: 2x6 SP No.1

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 3-10-5 oc purlins, except
2-0-0 oc purlins (5-1-12 max.): 5-7.
BOT CHORD Rigid ceiling directly applied or 9-2-13 oc bracing.
WEBS 1 Row at midpt 10-15, 8-23
JOINTS 1 Brace at Jt(s): 21, 23

**REACTIONS.** (size) 1=Mechanical, 17=0-3-8, 11=0-3-8
Max Horz 1=-253(LC 8)
Max Uplift 17=-29(LC 9)
Max Grav 1=1956(LC 2), 17=1300(LC 20), 11=2314(LC 21)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-3329/277, 2-4=-3273/211, 4-5=-1867/363, 5-6=-1647/325, 6-7=-1647/325, 7-8=-1825/360, 8-10=-3252/193, 10-11=-3853/231
BOT CHORD 1-19=-101/2739, 18-19=-99/2739, 17-18=0/2685, 15-17=0/2685, 13-15=-82/3157, 11-13=-82/3157
WEBS 2-19=-259/231, 2-18=-559/343, 10-13=0/382, 8-15=0/862, 10-15=-719/256, 4-21=-1490/14, 21-23=-1444/20, 22-23=-1444/20, 8-22=-1531/12, 5-21=-88/654, 7-22=-37/520, 4-18=-40/812

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-1-4 to 4-10-14, Interior(1) 4-10-14 to 17-5-1, Exterior(2) 17-5-1 to 24-2-8, Interior(1) 24-2-8 to 30-6-15, Exterior(2) 30-6-15 to 37-4-6, Interior(1) 37-4-6 to 48-8-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Ceiling dead load (10.0 psf) on member(s). 4-21, 21-23, 22-23, 8-22; Wall dead load (5.0psf) on member(s).8-15, 4-18
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 17-18, 15-17
8) Refer to girder(s) for truss to truss connections.
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 29 lb uplift at joint 17.
10) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
11) Attic room checked for L/360 deflection.


February 7,2022



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | A9GE | ROOF TRUSS | 1 | 1 | I50106925 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:16 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-CF0rRqwY_DEA0fpvgs84JenyYTaO5EYIla9Lh9znXPP

| 8-1-12 | 13-0-8 | 15-0-12 | 17-5-1 | 22-5-12 | 24-0-0 | 30-6-15 | 32-4-4 | 35-2-9 | 39-10-4 | 48-0-0 | 48-10-8 |
|---|---|---|---|---|---|---|---|---|---|---|---|
| 8-1-12 | 4-10-12 | 2-0-4 | 2-4-5 | 5-0-11 | 1-6-4 | 6-6-15 | 1-9-5 | 2-10-5 | 4-7-11 | 8-1-12 | 0-10-8 |

Scale = 1:84.3




| 8-1-12 | 13-0-8 | 15-0-12 | 19-0-0 | 32-4-4 | 39-10-4 | 48-0-0 |
|---|---|---|---|---|---|---|
| 8-1-12 | 4-10-12 | 2-0-4 | 3-11-4 | 13-4-4 | 7-6-0 | 8-1-12 |

Plate Offsets (X,Y)-- [5:0-4-4,0-3-4], [15:0-5-0,0-6-12], [18:0-4-0,0-4-12]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.47 | Vert(LL) | -0.37 | 15-17 | >926 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.46 | Vert(CT) | -0.63 | 15-17 | >545 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.80 | Horz(CT) | 0.08 | 11 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.18 | 15 | >999 | 240 | Weight: 421 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x8 SP No.1 *Except*
14-16,16-19: 2x10 SP 2400F 2.0E
WEBS 2x4 SP No.2 *Except*
8-15,8-20,4-18,6-23,4-20: 2x6 SP No.1

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 3-9-5 oc purlins, except 2-0-0 oc purlins (5-1-8 max.): 5-7.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.
WEBS 1 Row at midpt 2-18, 10-15, 8-23
JOINTS 1 Brace at Jt(s): 21, 23

**REACTIONS.** (size) 1=Mechanical, 17=0-3-8, 11=0-3-8
Max Horz 1=-316(LC 10)
Max Uplift 1=-55(LC 13), 17=-140(LC 9), 11=-190(LC 13)
Max Grav 1=2034(LC 2), 17=1210(LC 20), 11=2332(LC 21)


**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-3439/405, 2-4=-3317/300, 4-5=-1881/435, 5-6=-1659/395, 6-7=-1658/395, 7-8=-1833/441, 8-10=-3340/310, 10-11=-3867/380
BOT CHORD 1-19=-215/2831, 18-19=-214/2829, 17-18=0/2781, 15-17=0/2781, 13-15=-189/3179, 11-13=-189/3179
WEBS 2-19=-263/240, 2-18=-563/548, 10-13=0/370, 8-15=0/955, 10-15=-699/372, 4-21=-1688/212, 21-23=-1645/214, 22-23=-1645/214, 8-22=-1724/214, 5-21=-109/666, 7-22=-49/525, 4-18=-96/905

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) gable end zone and C-C Corner(3) 0-1-4 to 4-10-14, Exterior(2) 4-10-14 to 17-5-1, Corner(3) 17-5-1 to 22-2-11, Exterior(2) 22-2-11 to 30-6-15, Corner(3) 30-6-15 to 35-4-9, Exterior(2) 35-4-9 to 48-8-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Provide adequate drainage to prevent water ponding.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Ceiling dead load (10.0 psf) on member(s). 4-21, 21-23, 22-23, 8-22; Wall dead load (5.0psf) on member(s).8-15, 4-18
7) Bottom chord live load (40.0 psf) and additional bottom chord dead load (10.0 psf) applied only to room. 17-18, 15-17
8) Refer to girder(s) for truss to truss connections.
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 55 lb uplift at joint 1, 140 lb uplift at joint 17 and 190 lb uplift at joint 11.
10) Graphical purlin representation does not depict the size or the orientation of the purlin along the top and/or bottom chord.
11) Attic room checked for L/360 deflection.

February 7,2022




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | B1 | QUEENPOST | 2 | 1 | I50106926 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:16 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-CF0rRqwY_DEA0fpvgs84Jen2FTc75MZIIa9Lh9znXPP




Plate Offsets (X,Y)-- [7:0-5-14,Edge]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.11 | Vert(LL) | -0.06 | 1-10 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.35 | Vert(CT) | -0.12 | 1-10 | >999 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.29 | Horz(CT) | 0.01 | 7 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | Wind(LL) | 0.01 | 10 | >999 | 240 | Weight: 160 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x6 SP No.1
WEBS 2x4 SP No.2
SLIDER Left 2x4 SP No.2 3-4-3, Right 2x4 SP No.2 3-4-3

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (size) 7=0-3-8, 1=0-3-8
Max Horz 1=-224(LC 8)
Max Uplift 7=-44(LC 13), 1=-34(LC 12)
Max Grav 7=885(LC 1), 1=839(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-3=-983/269, 3-4=-796/274, 4-5=-796/270, 5-7=-983/263
BOT CHORD 1-10=-85/738, 7-10=-79/669
WEBS 3-10=-329/237, 4-10=-169/676, 5-10=-331/235

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-0-0 to 4-4-13, Interior(1) 4-4-13 to 10-6-0, Exterior(2) 10-6-0 to 14-10-13, Interior(1) 14-10-13 to 21-8-14 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
5) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 44 lb uplift at joint 7 and 34 lb uplift at joint 1.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | B1GE | GABLE | 1 | 1 | I50106927 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:17 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-gRZDeAxAlWM1doO6EZfJsrKExs1Dqr7uWEuuEbznXPO




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.05 | Vert(LL) | 0.00 | 13 | n/r | 120 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.04 | Vert(CT) | 0.00 | 13 | n/r | 120 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.14 | Horz(CT) | 0.00 | 13 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 191 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x6 SP No.1
OTHERS 2x4 SP No.2
SLIDER Left 2x4 SP No.2 1-6-10, Right 2x4 SP No.2 1-6-10

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.
WEBS 1 Row at midpt 7-20

**REACTIONS.** All bearings 21-0-0.
(lb) - Max Horz 1=-280(LC 8)
Max Uplift All uplift 100 lb or less at joint(s) 13, 1, 21, 23, 18, 16 except 22=-127(LC 12), 24=-227(LC 12), 17=-129(LC 13), 15=-211(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 13, 1, 20, 21, 22, 23, 18, 17, 16, 15 except 24=269(LC 19)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-3=-304/215, 11-13=-250/141

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) gable end zone and C-C Corner(3) 0-0-0 to 4-6-0, Exterior(2) 4-6-0 to 10-6-0, Corner(3) 10-6-0 to 14-10-13, Exterior(2) 14-10-13 to 21-8-14 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Truss designed for wind loads in the plane of the truss only. For studs exposed to wind (normal to the face), see Standard Industry Gable End Details as applicable, or consult qualified building designer as per ANSI/TPI 1.
4) All plates are 2x4 MT20 unless otherwise indicated.
5) Gable requires continuous bottom chord bearing.
6) Gable studs spaced at 2-0-0 oc.
7) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
8) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 13, 1, 21, 23, 18, 16 except (jt=lb) 22=127, 24=227, 17=129, 15=211.


February 7,2022



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | B1GR | FINK | 1 | 3 | I50106928 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:19 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-cqhz3szQG7dkt6YUM_hnxGPS3gfKIjoB_YN?IUznXPM




Plate Offsets (X,Y)-- [6:0-8-0,0-1-12], [8:0-8-0,0-1-12]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.52 | Vert(LL) | -0.06 | 6-8 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.32 | Vert(CT) | -0.13 | 6-8 | >999 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | NO | WB | 0.32 | Horz(CT) | 0.02 | 5 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | -0.00 | 8 | >999 | 240 | Weight: 614 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x6 SP No.1
BOT CHORD 2x10 SP 2400F 2.0E
WEBS 2x6 SP No.1 *Except*
2-8,4-6: 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (size) 1=0-3-8, 5=0-3-8
Max Horz 1=219(LC 26)
Max Grav 1=8759(LC 2), 5=9981(LC 2)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-10659/0, 2-3=-10317/0, 3-4=-11062/0, 4-5=-11410/0
BOT CHORD 1-8=0/7737, 6-8=0/5721, 5-6=0/8301
WEBS 2-8=-58/590, 3-8=0/6275, 3-6=0/7920, 4-6=-51/610

**NOTES-**
1) 3-ply truss to be connected together with 10d (0.131"x3") nails as follows:
Top chords connected as follows: 2x6 - 2 rows staggered at 0-9-0 oc.
Bottom chords connected as follows: 2x10 - 3 rows staggered at 0-5-0 oc.
Webs connected as follows: 2x4 - 1 row at 0-9-0 oc, 2x6 - 2 rows staggered at 0-9-0 oc.
2) All loads are considered equally applied to all plies, except if noted as front (F) or back (B) face in the LOAD CASE(S) section. Ply to ply connections have been provided to distribute only loads noted as (F) or (B), unless otherwise indicated.
3) Unbalanced roof live loads have been considered for this design.
4) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope); Lumber DOL=1.60 plate grip DOL=1.60
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
7) Use USP JUS26 (With 4-10d nails into Girder & 4-10d nails into Truss) or equivalent at 1-0-12 from the left end to connect truss(es) to front face of bottom chord, skewed 0.0 deg.to the right, sloping 0.0 deg. down.
8) Use USP JUS210 (With 8-10d nails into Girder & 4-10d nails into Truss) or equivalent spaced at 2-0-0 oc max. starting at 3-0-12 from the left end to 5-0-12 to connect truss(es) to front face of bottom chord.
9) Use USP MSH29 (With 18-10d nails into Girder & 4-10d nails into Truss) or equivalent spaced at 2-0-0 oc max. starting at 7-0-12 from the left end to 19-0-12 to connect truss(es) to front face of bottom chord.
10) Fill all nail holes where hanger is in contact with lumber.

**LOAD CASE(S)** Standard
1) Dead + Roof Live (balanced): Lumber Increase=1.15, Plate Increase=1.15
Uniform Loads (plf)
Vert: 1-5=-20, 1-3=-60, 3-5=-60


February 7,2022

Continued on page 2



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

**LOAD CASE(S)** Standard

Concentrated Loads (lb)

Vert: 8=-1938(F) 9=-832(F) 10=-979(F) 11=-979(F) 13=-1938(F) 14=-1938(F) 15=-1938(F) 16=-1887(F) 17=-1887(F) 18=-1887(F)

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | G1 | QUEENPOST | 5 | 1 | I50106929 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:19 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-cqhz3szQG7dkt6YUM_hnxGPVrgecII3B_YN?IUznXPM

-0-10-8 0-10-8 | 5-1-8 5-1-8 | 10-0-0 4-10-8 | 14-10-8 4-10-8 | 20-0-0 5-1-8 | 20-10-8 0-10-8

Scale = 1:34.9




10-0-0 10-0-0 | 20-0-0 10-0-0

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.34 | Vert(LL) | -0.06 | 6-9 | >999 | 360 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.36 | Vert(CT) | -0.13 | 6-9 | >999 | 240 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.17 | Horz(CT) | 0.02 | 6 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | Wind(LL) | 0.03 | 9 | >999 | 240 | Weight: 104 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x6 SP No.1
WEBS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 5-1-11 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (size) 2=0-3-8, 6=0-3-8
Max Horz 2=-54(LC 17)
Max Uplift 2=-64(LC 12), 6=-64(LC 13)
Max Grav 2=850(LC 1), 6=850(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 2-3=-1395/383, 3-4=-1069/271, 4-5=-1069/271, 5-6=-1395/383
BOT CHORD 2-9=-290/1205, 6-9=-291/1205
WEBS 3-9=-334/229, 4-9=-44/541, 5-9=-334/229

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) -0-10-8 to 3-6-5, Interior(1) 3-6-5 to 10-0-0, Exterior(2) 10-0-0 to 14-4-13, Interior(1) 14-4-13 to 20-10-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
5) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 2, 6.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | G1GE | GABLE | 1 | 1 | I50106930 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:20 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-40FLGC_21RlbUG7hvhD0TUylA42M1EVKCC7YqwznXPL




Plate Offsets (X,Y)-- [17:0-4-0,0-4-8]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.05 | Vert(LL) | -0.00 | 12 | n/r | 120 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.01 | Vert(CT) | -0.00 | 12 | n/r | 120 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.03 | Horz(CT) | 0.00 | 12 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 112 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x6 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** All bearings 20-0-0.
(lb) - Max Horz 2=-92(LC 13)
Max Uplift All uplift 100 lb or less at joint(s) 2, 12, 19, 20, 21, 22, 17, 16, 15, 14
Max Grav All reactions 250 lb or less at joint(s) 2, 12, 18, 19, 20, 21, 22, 17, 16, 15, 14

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) gable end zone and C-C Corner(3) -0-10-8 to 3-6-5, Exterior(2) 3-6-5 to 10-0-0, Corner(3) 10-0-0 to 14-4-13, Exterior(2) 14-4-13 to 20-10-8 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Truss designed for wind loads in the plane of the truss only. For studs exposed to wind (normal to the face), see Standard Industry Gable End Details as applicable, or consult qualified building designer as per ANSI/TPI 1.
4) All plates are 2x4 MT20 unless otherwise indicated.
5) Gable requires continuous bottom chord bearing.
6) Gable studs spaced at 2-0-0 oc.
7) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
8) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 2, 12, 19, 20, 21, 22, 17, 16, 15, 14.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | PB | PIGGYBACK | 22 | 1 | I50106931 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:21 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-YCpkUY_goltS6QitTPkF0hVrUUL3mgFURss6NMznXPK

6-6-15 / 6-6-15 — 13-1-14 / 6-6-15

Scale = 1:24.9




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.33 | Vert(LL) | 0.02 | 5 | n/r | 120 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.24 | Vert(CT) | 0.03 | 5 | n/r | 120 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.07 | Horz(CT) | 0.00 | 4 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 44 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (size) 2=11-5-9, 4=11-5-9, 6=11-5-9
Max Horz 2=-88(LC 10)
Max Uplift 2=-36(LC 12), 4=-45(LC 13)
Max Grav 2=253(LC 1), 4=253(LC 1), 6=478(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
WEBS 3-6=-303/127

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-3-8 to 4-8-4, Interior(1) 4-8-4 to 6-6-15, Exterior(2) 6-6-15 to 10-11-12, Interior(1) 10-11-12 to 12-10-6 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 2, 4.
7) See Standard Industry Piggyback Truss Connection Detail for Connection to base truss as applicable, or consult qualified building designer.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | PBGE | GABLE | 2 | 1 | I50106932 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:22 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-0PN6ht?JZ2?JkaH316FUZv14vtkhV8DdgWcfvpznXPJ

6-6-15 | 13-1-14
6-6-15 | 6-6-15

Scale: 1/2"=1'




13-1-14
13-1-14

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.03 | Vert(LL) | 0.00 | 8 | n/r | 120 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.02 | Vert(CT) | 0.00 | 8 | n/r | 120 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.02 | Horz(CT) | 0.00 | 8 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 53 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** All bearings 11-5-9.
(lb) - Max Horz 2=-110(LC 10)
Max Uplift All uplift 100 lb or less at joint(s) 2, 8, 13, 14, 11, 10
Max Grav All reactions 250 lb or less at joint(s) 2, 8, 12, 13, 14, 11, 10

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-3-8 to 4-6-15, Interior(1) 4-6-15 to 6-6-15, Exterior(2) 6-6-15 to 10-11-12, Interior(1) 10-11-12 to 12-10-6 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Truss designed for wind loads in the plane of the truss only. For studs exposed to wind (normal to the face), see Standard Industry Gable End Details as applicable, or consult qualified building designer as per ANSI/TPI 1.
4) All plates are 2x4 MT20 unless otherwise indicated.
5) Gable requires continuous bottom chord bearing.
6) Gable studs spaced at 2-0-0 oc.
7) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
8) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
9) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 2, 8, 13, 14, 11, 10.
10) See Standard Industry Piggyback Truss Connection Detail for Connection to base truss as applicable, or consult qualified building designer.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | V1 | GABLE | 1 | 1 | I50106933 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:23 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-VbxUvD0xKM7ALjsGbqmj56aDiH2YEYMnvALCRFznXPI




Scale = 1:77.8

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.16 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.17 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.22 | Horz(CT) | 0.01 | 10 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 160 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.
WEBS 1 Row at midpt 7-14, 6-15, 5-17, 8-13, 9-12

**REACTIONS.** All bearings 20-3-0.
(lb) - Max Horz 1=499(LC 12)
Max Uplift All uplift 100 lb or less at joint(s) 14, 15, 11, 12 except 1=-133(LC 10), 17=-182(LC 12), 18=-229(LC 12), 19=-224(LC 12), 13=-111(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 10, 14, 15, 13, 12 except 1=345(LC 12), 17=405(LC 19), 18=569(LC 19), 19=405(LC 19)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-590/403, 2-3=-395/274
WEBS 5-17=-271/221, 3-18=-341/280, 2-19=-325/264

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-4-13 to 4-9-10, Interior(1) 4-9-10 to 15-9-0, Exterior(2) 15-9-0 to 20-3-0 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) All plates are 2x4 MT20 unless otherwise indicated.
4) Gable requires continuous bottom chord bearing.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 14, 15, 11, 12 except (jt=lb) 1=133, 17=182, 18=229, 19=224, 13=111.


February 7,2022




ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | V2 | VALLEY | 1 | 1 | I50106934 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:24 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-znUs6Z1Z5gF1ztRS8XHyeK7ObhOqz0jw7q5mzhznXPH




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.15 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.17 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.15 | Horz(CT) | 0.01 | 8 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 114 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.
WEBS 1 Row at midpt 6-11, 5-13, 7-10

**REACTIONS.** All bearings 18-10-3.
(lb) - Max Horz 1=302(LC 12)
Max Uplift All uplift 100 lb or less at joint(s) except 8=-142(LC 20), 1=-142(LC 10), 13=-136(LC 12), 14=-126(LC 12), 15=-107(LC 12), 10=-143(LC 13), 9=-184(LC 18)
Max Grav All reactions 250 lb or less at joint(s) 8, 1 except 11=502(LC 19), 13=563(LC 19), 14=451(LC 19), 15=288(LC 19), 10=608(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-379/378, 2-3=-271/249
WEBS 5-13=-343/242, 3-14=-335/215, 2-15=-281/213, 7-10=-369/282

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-4-13 to 4-9-10, Interior(1) 4-9-10 to 14-4-3, Exterior(2) 14-4-3 to 18-10-3 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) All plates are 2x4 MT20 unless otherwise indicated.
4) Gable requires continuous bottom chord bearing.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 142 lb uplift at joint 8, 142 lb uplift at joint 1, 136 lb uplift at joint 13, 126 lb uplift at joint 14, 107 lb uplift at joint 15, 143 lb uplift at joint 10 and 184 lb uplift at joint 9.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VB1 | VALLEY | 1 | 1 | I50106935 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:25 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-R_2EKv1BszNub1?eiFoBAXfYf5k3iRn3MUqJW8znXPG




Plate Offsets (X,Y)-- [6:0-0-0,0-0-0], [7:0-0-0,0-0-0], [8:0-0-0,0-0-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.19 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.17 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.29 | Horz(CT) | 0.01 | 9 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 133 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.
WEBS 1 Row at midpt 5-13

**REACTIONS.** All bearings 25-10-13.
(lb) - Max Horz 1=-251(LC 8)
Max Uplift All uplift 100 lb or less at joint(s) 1 except 14=-128(LC 12), 15=-152(LC 12), 11=-127(LC 13), 10=-152(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 1, 9 except 13=440(LC 22), 14=544(LC 19), 15=518(LC 19), 11=544(LC 20), 10=518(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 4-5=-256/236, 5-6=-256/236
WEBS 4-14=-327/235, 2-15=-389/270, 6-11=-327/235, 8-10=-389/270

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-4-13 to 4-11-6, Interior(1) 4-11-6 to 12-11-6, Exterior(2) 12-11-6 to 17-4-3, Interior(1) 17-4-3 to 25-6-0 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) All plates are 2x4 MT20 unless otherwise indicated.
4) Gable requires continuous bottom chord bearing.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1 except (jt=lb) 14=128, 15=152, 11=127, 10=152.


February 7,2022



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VB2 | VALLEY | 1 | 1 | I50106936 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:25 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-R_2EKv1BszNub1?eiFoBAXfZM5kFiSy3MUqJW8znXPG




Plate Offsets (X,Y)-- [5:0-0-0,0-0-0], [6:0-0-0,0-0-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.15 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.16 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.21 | Horz(CT) | 0.00 | 7 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 115 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.
WEBS 1 Row at midpt 4-11

**REACTIONS.** All bearings 23-1-3.
(lb) - Max Horz 1=-223(LC 8)
Max Uplift All uplift 100 lb or less at joint(s) 1 except 12=-137(LC 12), 13=-121(LC 12), 9=-137(LC 13), 8=-121(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 1, 7 except 11=430(LC 22), 12=556(LC 19), 13=376(LC 19), 9=555(LC 20), 8=377(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
WEBS 3-12=-350/249, 2-13=-315/229, 5-9=-350/249, 6-8=-315/229

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-4-13 to 4-9-10, Interior(1) 4-9-10 to 11-6-9, Exterior(2) 11-6-9 to 15-11-6, Interior(1) 15-11-6 to 22-8-6 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) All plates are 2x4 MT20 unless otherwise indicated.
4) Gable requires continuous bottom chord bearing.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1 except (jt=lb) 12=137, 13=121, 9=137, 8=121.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VB3 | VALLEY | 1 | 1 | I50106937 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:26 2022 Page 1
ID:mHVPtvPrlWfejLZnULY80lyxYfS-vAcdXF2pdHVlCBaqGyJQjlCk_V41RwhDb8at2aznXPF




Plate Offsets (X,Y)-- [5:0-0-0,0-0-0], [6:0-0-0,0-0-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.16 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.19 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.18 | Horz(CT) | 0.00 | 7 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 97 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** All bearings 20-3-9.
(lb) - Max Horz 1=-195(LC 8)
Max Uplift All uplift 100 lb or less at joint(s) 1, 7 except 12=-141(LC 12), 13=-101(LC 12), 9=-141(LC 13), 8=-101(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 1, 7 except 11=440(LC 22), 12=475(LC 19), 13=275(LC 19), 9=474(LC 20), 8=275(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
WEBS 3-12=-358/254, 2-13=-271/210, 5-9=-358/254, 6-8=-271/210

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-4-13 to 4-9-10, Interior(1) 4-9-10 to 10-1-13, Exterior(2) 10-1-13 to 14-6-9, Interior(1) 14-6-9 to 19-10-12 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) All plates are 2x4 MT20 unless otherwise indicated.
4) Gable requires continuous bottom chord bearing.
5) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
6) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1, 7 except (jt=lb) 12=141, 13=101, 9=141, 8=101.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VB4 | VALLEY | 1 | 1 | I50106938 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:27 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-NMA?kb3RObdcqL91qgrfGykvBuPLAOvMpoJQa0znXPE




Plate Offsets (X,Y)-- [4:0-0-0,0-0-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.19 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.18 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.12 | Horz(CT) | 0.00 | 5 | n/a | n/a | | |
| BCDL | 10.0 | Code IRC2015/TPI2014 | | Matrix-S | | | | | | | Weight: 78 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** All bearings 17-6-0.
(lb) - Max Horz 1=-167(LC 8)
Max Uplift All uplift 100 lb or less at joint(s) 1 except 9=-160(LC 12), 6=-160(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 1, 5 except 8=417(LC 22), 9=527(LC 19), 6=527(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
WEBS 2-9=-399/275, 4-6=-399/275

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-4-13 to 4-9-0, Interior(1) 4-9-0 to 8-9-0, Exterior(2) 8-9-0 to 13-1-13, Interior(1) 13-1-13 to 17-1-3 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1 except (jt=lb) 9=160, 6=160.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VB5 | VALLEY | 1 | 1 | I50106939 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:28 2022 Page 1
ID:mHVPtvPrlWfejLZnULY80IyxYfS-rZkNyx439ulTSVkDNNMuoAH4nIl4urcW2R3z6SznXPD




Plate Offsets (X,Y)-- [4:0-0-0,0-0-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.14 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.15 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.09 | Horz(CT) | 0.00 | 5 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 64 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** All bearings 14-8-6.
(lb) - Max Horz 1=-139(LC 8)
Max Uplift All uplift 100 lb or less at joint(s) 1 except 8=-134(LC 12), 6=-134(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 1, 5 except 7=398(LC 19), 8=388(LC 19), 6=388(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
WEBS 2-8=-336/245, 4-6=-336/245

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-4-13 to 4-9-10, Interior(1) 4-9-10 to 7-4-3, Exterior(2) 7-4-3 to 11-9-0, Interior(1) 11-9-0 to 14-3-9 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1 except (jt=lb) 8=134, 6=134.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VB6 | VALLEY | 1 | 1 | I50106940 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:29 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-JlIl9H4iwCtK3eJPx4t7LNqFfi6EdJLfH5oXfvznXPC




Plate Offsets (X,Y)-- [4:0-0-0,0-0-0]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.13 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.09 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.06 | Horz(CT) | 0.00 | 5 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 49 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** All bearings 11-10-13.
(lb) - Max Horz 1=-111(LC 8)
Max Uplift All uplift 100 lb or less at joint(s) 1, 5 except 8=-124(LC 12), 6=-123(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 1, 5, 7 except 8=325(LC 19), 6=325(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
WEBS 2-8=-315/247, 4-6=-315/247

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-4-13 to 4-9-10, Interior(1) 4-9-10 to 5-11-6, Exterior(2) 5-11-6 to 10-4-3, Interior(1) 10-4-3 to 11-6-0 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1, 5 except (jt=lb) 8=124, 6=123.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VB7 | VALLEY | 1 | 1 | I50106941 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:29 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80lyxYfS-JIll9H4iwCtK3eJPx4t7LNqFwi6fdJdfH5oXfvznXPC




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.18 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.13 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.04 | Horz(CT) | 0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 34 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (size) 1=9-1-3, 3=9-1-3, 4=9-1-3
Max Horz 1=-83(LC 8)
Max Uplift 1=-19(LC 13), 3=-27(LC 13)
Max Grav 1=177(LC 1), 3=177(LC 1), 4=309(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1, 3.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VB8 | VALLEY | 1 | 1 | I50106942 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:30 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-nxs7Nd5KhW?BhoucVoOMtbMRm6T?MmFoWlY4BLznXPB




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.11 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.06 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.02 | Horz(CT) | 0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-P | | | | | | | Weight: 23 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (size) 1=6-3-9, 3=6-3-9, 4=6-3-9
Max Horz 1=55(LC 9)
Max Uplift 1=-19(LC 13), 3=-24(LC 13)
Max Grav 1=127(LC 1), 3=127(LC 1), 4=185(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1, 3.


February 7,2022



ENGINEERING BY
TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VB9 | VALLEY | 1 | 1 | I50106943 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:30 2022 Page 1
ID:mHVPtvPrlWfejLZnULY80IyxYfS-nxs7Nd5KhW?BhoucVoOMtbMS26TvMmVoWlY4BLznXPB




Plate Offsets (X,Y)-- [2:0-2-0,Edge]

| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.02 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.06 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.00 | Horz(CT) | 0.00 | 3 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-P | | | | | | | Weight: 10 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 3-6-0 oc purlins.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** (size) 1=3-6-0, 3=3-6-0
Max Horz 1=-27(LC 8)
Max Uplift 1=-5(LC 12), 3=-5(LC 13)
Max Grav 1=108(LC 1), 3=108(LC 1)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.

**NOTES-**
1) Unbalanced roof live loads have been considered for this design.
2) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 1, 3.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VMB1 | GABLE | 1 | 1 | I50106944 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:31 2022 Page 1
ID:mHVPtvPrIWfejLZnULY80IyxYfS-G7QWay6ySp72JyTo3VvbQovc3Wpo5C?ykPHdjnznXPA




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.07 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.02 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.11 | Horz(CT) | 0.01 | 12 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 63 lb | FT = 20% |

**LUMBER-**

| | |
|---|---|
| TOP CHORD | 2x4 SP No.1 |
| BOT CHORD | 2x4 SP No.1 |
| WEBS | 2x4 SP No.2 |
| OTHERS | 2x4 SP No.2 |

**BRACING-**

| | |
|---|---|
| TOP CHORD | Structural wood sheathing directly applied or 6-0-0 oc purlins, except end verticals. |
| BOT CHORD | Rigid ceiling directly applied or 10-0-0 oc bracing. |
| WEBS | 1 Row at midpt 2-12 |

**REACTIONS.** All bearings 9-10-4.
(lb) - Max Horz 1=-369(LC 13)
Max Uplift All uplift 100 lb or less at joint(s) 12, 7, 13, 8 except 1=-107(LC 11), 11=-121(LC 13), 10=-108(LC 13), 9=-114(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 12, 7, 11, 10, 9, 8 except 1=303(LC 13)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-396/477, 2-3=-363/427, 3-4=-270/320

**NOTES-**
1) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) gable end zone and C-C Exterior(2) 0-0-0 to 6-3-8, Interior(1) 6-3-8 to 9-5-7 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) All plates are 2x4 MT20 unless otherwise indicated.
3) Gable requires continuous bottom chord bearing.
4) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
5) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members.
6) Bearing at joint(s) 1 considers parallel to grain value using ANSI/TPI 1 angle to grain formula. Building designer should verify capacity of bearing surface.
7) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 12, 7, 13, 8 except (jt=lb) 1=107, 11=121, 10=108, 9=114.




February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

| Job | Truss | Truss Type | Qty | Ply | Regency Homes/4 Avery Farm/Harnett |
|---|---|---|---|---|---|
| J0222-0517 | VMB2 | VALLEY | 1 | 1 | I50106945 |
| | | | | | Job Reference (optional) |

Comtech, Inc, Fayetteville, NC - 28314, 8.430 s Aug 16 2021 MiTek Industries, Inc. Mon Feb 7 12:19:32 2022 Page 1
ID:mHVPtvPrlWfejLZnULY80lyxYfS-kKzuoI7aC7Fuw62_cDQqz0SlNv7Cqf55z31BGEznXP9




| LOADING (psf) | | SPACING- | 2-0-0 | CSI. | | DEFL. | in | (loc) | l/defl | L/d | PLATES | GRIP |
|---|---|---|---|---|---|---|---|---|---|---|---|---|
| TCLL | 20.0 | Plate Grip DOL | 1.15 | TC | 0.23 | Vert(LL) | n/a | - | n/a | 999 | MT20 | 244/190 |
| TCDL | 10.0 | Lumber DOL | 1.15 | BC | 0.14 | Vert(CT) | n/a | - | n/a | 999 | | |
| BCLL | 0.0 * | Rep Stress Incr | YES | WB | 0.12 | Horz(CT) | 0.00 | 6 | n/a | n/a | | |
| BCDL | 10.0 | Code | IRC2015/TPI2014 | Matrix-S | | | | | | | Weight: 47 lb | FT = 20% |

**LUMBER-**
TOP CHORD 2x4 SP No.1
BOT CHORD 2x4 SP No.1
WEBS 2x4 SP No.2
OTHERS 2x4 SP No.2

**BRACING-**
TOP CHORD Structural wood sheathing directly applied or 6-0-0 oc purlins, except end verticals.
BOT CHORD Rigid ceiling directly applied or 10-0-0 oc bracing.

**REACTIONS.** All bearings 9-3-1.
(lb) - Max Horz 1=-240(LC 13)
Max Uplift All uplift 100 lb or less at joint(s) 6, 4 except 1=-115(LC 11), 7=-280(LC 18), 5=-167(LC 13)
Max Grav All reactions 250 lb or less at joint(s) 1, 4 except 6=481(LC 18), 5=544(LC 20)

**FORCES.** (lb) - Max. Comp./Max. Ten. - All forces 250 (lb) or less except when shown.
TOP CHORD 1-2=-409/476, 2-3=-334/369
WEBS 3-5=-437/338

**NOTES-**
1) Wind: ASCE 7-10; Vult=130mph Vasd=103mph; TCDL=6.0psf; BCDL=6.0psf; h=15ft; Cat. II; Exp C; Enclosed; MWFRS (envelope) and C-C Exterior(2) 0-0-0 to 6-2-11, Interior(1) 6-2-11 to 8-10-4 zone;C-C for members and forces & MWFRS for reactions shown; Lumber DOL=1.60 plate grip DOL=1.60
2) Gable requires continuous bottom chord bearing.
3) This truss has been designed for a 10.0 psf bottom chord live load nonconcurrent with any other live loads.
4) * This truss has been designed for a live load of 30.0psf on the bottom chord in all areas where a rectangle 3-6-0 tall by 2-0-0 wide will fit between the bottom chord and any other members, with BCDL = 10.0psf.
5) Bearing at joint(s) 1 considers parallel to grain value using ANSI/TPI 1 angle to grain formula. Building designer should verify capacity of bearing surface.
6) Provide mechanical connection (by others) of truss to bearing plate capable of withstanding 100 lb uplift at joint(s) 6, 4 except (jt=lb) 1=115, 7=280, 5=167.


February 7,2022



ENGINEERING BY TRENCO
A MiTek Affiliate
818 Soundside Road
Edenton, NC 27932

# Symbols

## PLATE LOCATION AND ORIENTATION




Center plate on joint unless x, y offsets are indicated. Dimensions are in ft-in-sixteenths. Apply plates to both sides of truss and fully embed teeth.




For 4 x 2 orientation, locate plates 0- 1/16" from outside edge of truss.

This symbol indicates the required direction of slots in connector plates.

*** Plate location details available in MiTek 20/20 software or upon request.**

## PLATE SIZE

4 x 4

The first dimension is the plate width measured perpendicular to slots. Second dimension is the length parallel to slots.

## LATERAL BRACING LOCATION



Indicated by symbol shown and/or by text in the bracing section of the output. Use T or I bracing if indicated.

## BEARING



Indicates location where bearings (supports) occur. Icons vary but reaction section indicates joint number where bearings occur. Min size shown is for crushing only.

**Industry Standards:**

ANSI/TPI1: National Design Specification for Metal Plate Connected Wood Truss Construction.
DSB-89: Design Standard for Bracing.
BCSI: Building Component Safety Information, Guide to Good Practice for Handling, Installing & Bracing of Metal Plate Connected Wood Trusses.

# Numbering System




**JOINTS ARE GENERALLY NUMBERED/LETTERED CLOCKWISE AROUND THE TRUSS STARTING AT THE JOINT FARTHEST TO THE LEFT.**

**CHORDS AND WEBS ARE IDENTIFIED BY END JOINT NUMBERS/LETTERS.**

## PRODUCT CODE APPROVALS

ICC-ES Reports:

ESR-1311, ESR-1352, ESR1988
ER-3907, ESR-2362, ESR-1397, ESR-3282

Trusses are designed for wind loads in the plane of the truss unless otherwise shown.

Lumber design values are in accordance with ANSI/TPI 1 section 6.3 These truss designs rely on lumber values established by others.



MiTek Engineering Reference Sheet: MII-7473 rev. 5/19/2020

# General Safety Notes

Failure to Follow Could Cause Property Damage or Personal Injury

1. Additional stability bracing for truss system, e.g. diagonal or X-bracing, is always required. See BCSI.
2. Truss bracing must be designed by an engineer. For wide truss spacing, individual lateral braces themselves may require bracing, or alternative Tor I bracing should be considered.
3. Never exceed the design loading shown and never stack materials on inadequately braced trusses.
4. Provide copies of this truss design to the building designer, erection supervisor, property owner and all other interested parties.
5. Cut members to bear tightly against each other.
6. Place plates on each face of truss at each joint and embed fully. Knots and wane at joint locations are regulated by ANSI/TPI 1.
7. Design assumes trusses will be suitably protected from the environment in accord with ANSI/TPI 1.
8. Unless otherwise noted, moisture content of lumber shall not exceed 19% at time of fabrication.
9. Unless expressly noted, this design is not applicable for use with fire retardant, preservative treated, or green lumber.
10. Camber is a non-structural consideration and is the responsibility of truss fabricator. General practice is to camber for dead load deflection.
11. Plate type, size, orientation and location dimensions indicated are minimum plating requirements.
12. Lumber used shall be of the species and size, and in all respects, equal to or better than that specified.
13. Top chords must be sheathed or purlins provided at spacing indicated on design.
14. Bottom chords require lateral bracing at 10 ft. spacing, or less, if no ceiling is installed, unless otherwise noted.
15. Connections not shown are the responsibility of others.
16. Do not cut or alter truss member or plate without prior approval of an engineer.
17. Install and load vertically unless indicated otherwise.
18. Use of green or treated lumber may pose unacceptable environmental, health or performance risks. Consult with project engineer before use.
19. Review all portions of this design (front, back, words and pictures) before use. Reviewing pictures alone is not sufficient.
20. Design assumes manufacture in accordance with ANSI/TPI 1 Quality Criteria.
21. The design does not take into account any dynamic or other loads other than those expressly stated.