



Fire Marshal Division

October 1, 2018

**Re: Central Harnett Hospital
215 Brightwater Drive
Lillington, NC 27546**

Application Number BCOM1809-0003

To Whom It May Concern,

Thank you for submitting the plans for the Central Harnett Hospital renovations. The plans have been carefully reviewed by a qualified code enforcement official to examine for compliance with the North Carolina Fire Prevention Code and all other fire protection regulatory documents. There are some items that were found during the plan review process that need to be addressed before a final inspection of the new facility can be given. These items are outlined and described below.

- **906.1 Fire Extinguishers**
 - Minimum of (1) 2A:10BC fire extinguisher shall be installed not to exceed 75' distance of travel.
 - All Fire extinguishers shall be properly mounted and tagged by a fire extinguisher company.

- **1006.1 Means of Egress Illumination**
 - The means of egress, including the exit discharge, shall be illuminated at all time the building space is served by the means of egress is occupied.
 - Means of egress consist of three separate and distinct parts: the exit access, the exit and the exit discharge.
 - The means of egress illumination shall not be less than 1 foot-candle at the walking surface.

- **1008.1.4.4 Access-controlled egress doors.**
 - The entrance doors in a *means of egress* in buildings with an occupancy in Group A, B, E, I-2, M, R-1 or R-2 and entrance doors to tenant spaces in occupancies in Groups A, B, E, I-2, M, R-1 and R-2 are permitted to be equipped with an *approved* entrance and egress access control system which shall be installed in accordance with all of the following criteria:



1. A sensor shall be provided on the egress side arranged to detect an occupant approaching the doors. The doors shall be arranged to unlock by a signal from or loss of power to the sensor.
2. Loss of power to that part of the access control system which locks the doors shall automatically unlock the doors.
3. The doors shall be arranged to unlock from a manual unlocking device located 40 inches to 48 inches (1016mm to 1219 mm) vertically above the floor and within 5 feet (1524 mm) of the secured doors. Ready access shall be provided to the manual unlocking device and the device shall be clearly identified by a sign that reads "PUSH TO EXIT." When operated, the manual unlocking device shall result in direct interruption of power to the lock— independent of the access control system electronics—and the doors shall remain unlocked for a minimum of 30 seconds.
4. Activation of the building fire alarm system, if provided, shall automatically unlock the doors, and the doors shall remain unlocked until the fire alarm system has been reset.
5. Activation of the building automatic sprinkler or fire detection system, if provided, shall automatically unlock the doors. The doors shall remain unlocked until the fire alarm system has been reset.

- **907.1.2 Fire Alarm System Shop Drawings**
 - Shop drawings from the licensed installing contractor shall be submitted prior to work beginning.
 - A rough in inspection is required.
 - A final acceptance test is required. (100%)
- **901.6.1 Sprinkler System Shop Drawings**
 - Sprinkler system shop drawings shall be submitted by the installing contractor prior to work beginning.
 - A rough in inspection is required.
 - A final acceptance test is required.
- **703.5 Identification**
 - Walls and partitions required to have protected openings shall be permanently identified with signs or stencils. (Example "2- hour Fire Barrier Protect All Openings")
- **Notes**
 - A final fire inspection is required.
 - Schedule all fire inspections through the Fire Marshal's Office. (910) 984-4003

1941

The first part of the report deals with the general situation in the country. It is noted that the economy is in a state of depression, and that the government is unable to meet its obligations. The report also mentions the fact that the population is suffering from a lack of food and clothing, and that the government is unable to provide for their needs.

The second part of the report deals with the financial situation. It is noted that the government has a large deficit, and that it is unable to pay its debts. The report also mentions the fact that the government is unable to raise revenue, and that it is forced to print money, which leads to inflation.

The third part of the report deals with the political situation. It is noted that the government is weak and corrupt, and that it is unable to carry out its duties. The report also mentions the fact that there is a lack of unity among the different groups in the country, and that this makes it difficult to carry out any reforms.

The fourth part of the report deals with the social situation. It is noted that the population is suffering from a lack of education and health care, and that the government is unable to provide for their needs. The report also mentions the fact that there is a high level of unemployment, and that this leads to poverty and social unrest.

The fifth part of the report deals with the international situation. It is noted that the country is isolated, and that it is unable to trade with other countries. The report also mentions the fact that the country is being threatened by foreign powers, and that it is unable to defend itself.

The report concludes that the country is in a state of crisis, and that it needs to take immediate action to reform itself. It is suggested that the government should be replaced by a more responsible and efficient one, and that there should be a focus on economic and social reforms.

The report also mentions that the country needs to improve its relations with other countries, and that it should seek to join the League of Nations. It is suggested that the country should take steps to improve its economy, and that it should focus on providing for the needs of its population.

The report ends with a call for action, and a hope that the country will be able to overcome its difficulties and build a better future for itself.

Prepared by the Committee on the State of the Country
 1941



Harnett
COUNTY
NORTH CAROLINA



Emergency Services Department

www.harnett.org

Thank you again for submitting the plans for the hospital renovations. Please review the plans and adhere to any notes and alterations that were made in addition to the original drawings. These remarks are for the plans that were submitted and its original intent. These remarks do not apply if the original intent changes or what was submitted on the above date changes. If you have any questions, please do not hesitate to call this office.

Sincerely,

D. Banks Wallace
Chief Deputy Fire Marshal