

**Date:** 01/23/2023

**To:** **Jazell Hudson**  
D Clugston Inc  
2506 Reliance Ave  
Apex, NC 27539  
jazell@dclugston.com  
267-455-3309

**Re:** **Truss Repair Verification**  
Location: 32 Retreat Dr. (Fuquay-Varina, NC)  
JDS Project No.: RDU2300477  
Date of Inspection: 01/20/2023

A representative of JDS Consulting arrived on site to observe the issues reported to us by the client, which are presented, along with our recommendations, in this report.

#### Observations


Verification of repairs to trusses CT1, CT1 G, CT2S and CT2S G at the attic access in the fitness room and the women's bathroom. The repairs have been made in general accordance with the recommendations with the exception of 7/16" OSB was used in lieu of 3/4" OSB.

#### Recommendations

Based on our onsite observations and review, the repairs with the 7/16" OSB are adequate. No further repairs are required.

If you have any questions or if I can be of further assistance to you on this project, please contact me at 984-297-5949.

Respectfully Submitted,  
John Lowrance



Reviewing Engineer: Uchenna Onwuemene, PE

