

7 919 773-1200 * F 919 773-9658 250 Shipwash Drive, Suite 104 * Garner * North Carolina * 27529 www.tyndallengineering.com

February 19, 2025

Larry Barefoot 2763 Johnston County Road Angier, NC 27501

Email: larrybarefoot1951@gmail.com

OS/07/2025

OS/07/2025

OS/07/2025

Reference:

Engineering Services

29 E Main Street Coats, NC 27521

TE&D Project No.: 2501-020115

To Whom It May Concern:

As requested, a representative of Tyndall Engineering & Design, PA (TE&D) was on-site to observe the following item(s):

1) Proposed opening of the party wall dividing the left and right sections of the library.

The following conclusions and recommendations were noted:

- 1) We understand the new opening is to be approximately 6'-6" wide in the CMU wall dividing the buildings. The right-side of the wall is an 8" CMU wall. The left side of the wall is a 4" CMU wall. Based on our observations and analysis, the new opening is to be framed as follows:
 - a. For the 8" CMU wall, install a minimum (4) 2 x 12 beam. The header is to be supported with (3) 2 x 8 jack studs and (1) 2 x 8 pressure-treated king stud at each end. A new 2 x 8 pressure-treated top plate is to be installed tightly between the new header and the existing 8" CMU wall.
 - b. For the 4" CMU wall, install a minimum (2) 1-3/4 x 7-1/4 LVL beam. The new header is to be supported with (3) 2 x 4 jack studs and (1) 2 x 8 pressure treated king stud. A new 2 x 4 pressure-treated top plate is to be installed tightly between the new header and the existing 4" CMU wall.

Stud columns are to be blocked solid to the foundation. See the attached Header Masonry Support on Page 3 of this report for clarification.

Upon completion of the above recommendations, the structure will provide the required support for the anticipated loading conditions. We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,

Tyndall Engineering & Design

Tripp Amos

RS | 2501-020115

Prentice Tyndall Jr., P.E.



7 919 773-1200 * F 919 773-9658 250 Shipwash Drive, Suite 104 * Garner * North Carolina * 27529 www.tyndallengineering.com




Front of Building



Wall to be Removed



7 919 773 1200 ■ £ 919 773 9658 250 Shipwash Drive, Suite 104 ■ Garner ■ North Carolina ■ 27529 www.tyndallengineering.com



Page 3 of 3

29 East Main St. Coats, N.C, 27521

Coats

MAGENTA = EXISTING/REMAIN Add (1) 50 x 68 Double Door Unit y TOWN HALL COMPUTER CIRCULATION DESK OVERFLOW MAIN LIBRARY Double Door RELOCATE DIRECTOR OFFICE EMP PATRON BATH DIRECTOR BATH BREAK ROOM/STORAGE STORAGE STORAGE STORAGE MECH BATH BATH LARRY BAREFOOT-General Contractor

2763 Johnston Co. Rd. Angier, N.C. 27501 Cell: 919-795-6511

to scale