



February 19, 2026

Mike Rimbey
Ph: (919) 901-2284, (919) 821-1300
3709 Auburn Church Rd,
Garner, NC 27529
Email: mike.rimbey@inlandconstructionco.com

Reference: Engineering Services
Project No.: 2401-010249_H

As requested by the client, a representative of Tyndall Engineering & Design, PA (TE&D) has reviewed the following item(s):

- 1) Contractor requested a review of the as-built condition of the bolt edge distance of the installed moment frames.

Based on our review and worst-case analyses, TE&D recommends the following:

- 1) Install a 12" wide by 4" thick pedestal adjacent to existing column base plate per drawing on page 2 of this report.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,
Tyndall Engineering & Design

Bob Ahimbisibwe, PE
BEA/2401-010249_H

Prentice A. Tyndall Jr., P.E



