



# Permit Reviews

## Harnett County

**Permit Number: BCOM2506-0003**

Description: **Word and Glory Church in existing building**

Applied: **6/10/2025**

Approved:

Site Address: **109 E B ST**

Issued:

Finalized:

City, State Zip Code: **ERWIN, NC 28339**

Status: **RECEIVED**

Applicant: **Brafford Kevin**

Parent Permit:

Owner: **DEOLIVEIRA MANOEL L**

Parent Project:

Contractor: **<NONE>**

Details:

### LIST OF REVIEWS

SENT DATE	RETURNED DATE	DUE DATE	TYPE	CONTACT	STATUS	REMARKS
Review Group: ALL						
7/23/2025	7/31/2025	8/6/2025	FIRE MARSHAL	Roger Sullivan	DISAPPROVED	see notes
Notes: See building inspector notes, same comments.						
10/23/2025	10/28/2025	11/6/2025	FIRE MARSHAL	Roger Sullivan	DISAPPROVED	in attachments
Notes: Same comments as the building inspector. There are three units and three addresses at this location. How are the side exits directly to the outside? Is this upfit taking the whole building? Are the walls being removed from the other tenant spaces to make one building/address?						
Review Group: AUTO						
6/10/2025	6/10/2025		COMMERCIAL INTAKE	CP Bucket	APPROVED	
Notes:						
6/10/2025	6/11/2025	6/24/2025	COMMERCIAL BUILDING REVIEW	Brad Sutton	DISAPPROVED	
Notes: 1. If drawn to scale, please provide the scale. 2. Need to know where doors either side of seating area lead to. 3. Provide all door hardware types (lever, knob, push bar etc)						
6/10/2025	6/13/2025	6/25/2025	FIRE MARSHAL	Leslie Jackson	DISAPPROVED	See Notes
Notes: - Need to submit a life safety plan. - Same comments as building.						





# Permit Reviews Harnett County

7/23/2025	7/29/2025	8/6/2025	COMMERCIAL BUILDING REVIEW	Brad Sutton	DISAPPROVED	
<p>Notes:</p> <p>All exits shown shall be directly to the exterior of the building.          All exits doors shall swing in direction of egress          Panic hardware required for calculated occupant load.</p>						
10/23/2025	10/24/2025	11/6/2025	COMMERCIAL BUILDING REVIEW	Brad Sutton	DISAPPROVED	in attachments
<p>Notes:</p> <p>There are three units and three addresses at this location. How are the side exits directly to the outside? Is this upfit taking the whole building? Are the walls being removed from the other tenant spaces to make one building/address?</p>						
10/24/2025			COMMERCIAL BUILDING REVIEW	Building Bucket		
<p>Notes:</p>						

