

Main Office: 5001 Weston Parkway Suite 100 Cary, NC 27513 919.465.3801 Charlotte Office: 10400 Mallard Creek Road Suite 320 Charlotte, NC 28262 704.810.1808

NC Lic. No.: C-2871

September 10, 2025

58 Foundations Attn: Matt Morgan

Re: Inspection of Structural Repairs

Olivia Evangelical Presbyterian Church 3363 Olivia Road

Sanford, NC

Dear Mr. Morgan:

Giles Flythe Engineers previously performed a Limited Structural Inspection for the above-noted property, and issued a report with repair specifications dated February 14, 2025. A re-inspection of repairs was performed on August 18, 2025. The purpose of the inspection was to determine if the floor framing repairs were performed in accordance with the report recommendations, and to evaluate the alternative construction installations for conformance with the intent of the original repair design.

The following itemizes our review of the repairs:

- 1) Widespread floor framing repairs were observed throughout the building. This included full replacement of floor joists, replacement of perimeter bands, replacement of girder sections, installation of new CMU piers on concrete footings, installation of supplemental steel post-and-beam shoring systems, and widespread replacement of subflooring throughout the repair areas. The supplement steel post-and-beam shoring systems were observed to provide full contact to the above floor framing, and the steel jack posts were installed onto new concrete footings. The steel jack post leveling plates were fitted with set screws / locknuts to permanently hold the support brackets in place.
- 2) We identified limited areas which required additional attention, including additional fasteners into ledger strips, new shimming at girder bearing points, and additional support needed below a girder intersection. We provided design guidance and consultation during construction of these additional repairs, and reviewed contractor-provided documentation of the completed work.

The floor framing repairs, including the alternative construction installations, were observed to meet or exceed the intent of the original repair recommendations outlined in our February 14, 2025 report.

No further structural repairs or modifications are required.

CONCLUSION

We trust that this letter provides the information you require. Please contact us at 919-465-3801 if you have any questions. Thank you for the opportunity to be of assistance to you.

Sincerely,

Andrew D. Crook, PE Project Manager Giles Flythe Engineers Inc. NC Lic. No. C-2871

