

**ROBERT J. BRACKEN, P.E.**

PLEASE NOTE   
ADDRESS CHANGE

3768 CARBONTON RD.  
SANFORD, N.C. 27330  
TELEPHONE (919) 774-6074  
BJBRACKEN@WINDSTREAM.NET

CHOO CHOO HOMES  
5657 BEAG BLVD  
FRYETTEVILLE, NC  
28303

SERVICES RENDERED THRU \_\_\_\_\_

PROJECT NO. 11519

INVOICE DATE 3-15-19

ALL ACCOUNTS DUE IN 30 DAYS.

PLEASE DETACH AND MAIL TOP PORTION WITH YOUR REMITTANCE.

CURTAIN WALL INSPECTION

*Thank*

Ref: 3878 Hwy 27 W  
Wilmington

AMOUNT DUE

\$350<sup>00</sup>

ROBERT J. BRACKEN, P.E., SANFORD, NORTH CAROLINA 27330

An 18% annual service charge will be added to all accounts not paid within 30 days of invoice date

# RJB, P.E., P.A.

C-0269

ROBERT J. BRACKEN  
ENGINEER + SURVEYOR

3768 Carbonton Road • Sanford, North Carolina 27330  
(919) 774-6074 • bjbracken@windstream.net

March 14, 2019

Harnett County Building Inspections  
P.O. Box 65  
Lillington, NC 27546

REF: Curtain wall inspection  
3878 NC Hwy 27W  
Lillington, NC 27546  
Choo Choo Homes, Cont.,

Dear Sir/Madam,

I made an onsite visit to the above referenced Mobile Home building site on March 13, 2019. The purpose of the visit was to examine the curtain wall. Approximately 10 feet at the left front and approximately 10 feet on the left wall was over 40 inches high. The contractor completely removed the 20 feet of wall and placed a new 12" wide x 8" deep concrete footing. He then built an 8" block curtain wall with lateral support piers 6 foot on center. The piers were attached to the walls with ladder wire. With the placement of the new the footings and piers the wall will resist the lateral loads according to the requirements of the NC State Building Code, 2018,ed.

If you have any questions please feel free to call me at 774-6074.

Sincerely,



Robert J. Bracken, PE

