Initial Application Date: 4/18/19 Application # BRES 904-6040
Country OF HARNETT DEMOLITION APPLICATION Central Permitting 108 E. Front Street, Lillington, NC 27546 Phone: (910) 893-7525 Fax: (910) 893-2793 www.hamett.org/permits
LANDOWNERGITD-Woodgrove, LLC Mailing Address: 1330 Sunly Or. Ste. 105
city: Baleigh state: NC zipol7607 contact # 919-422-5741 Email: juhite agreen hawlecorp. ca
APPLICANT Cecil Holcomb Denne liting Tric Mailing Address: 8315 La Matis se Nd.
City: 1(a) e's - State WC ZID TV15 Contact & Cecil Holcomb Email: Chdemo lition & act. con Please fill out applicant information if different than landowner
CONTACT NAME APPLYING IN OFFICE:Phone #
PROPERTY LOCATION: Subdivision: 166 167 Stewart LW. FV Lot #:Lot Size:
State Road # State Road Name: Map Book&Page: /
Parcel:
Zoning: Flood Zone: Watershed: Deed Book&Page: /
SPECIFIC DIRECTIONS TO THE PROPERTY FROM LILLINGTON: US 401
North gapprox metaly 10 miles and take right on
ICT Stewart Live and you are at your
destination
Structure(s) to be demolished & removed: Single family dwelling Manufactured Home Other (specify)
Structures (existing and/or proposed): Single family dwellings Manufactured Homes Other (specify)
Water Supply: (_) County (_) Existing Well
Sewage Supply: Existing Septic Tank () County Sewer
* If a new structure is to be replaced on this lot, please ensure that existing septic system is not damaged.
* If an existing well is on site and is to be discontinued, please contact Hamett County Environmental Health for assistance.
*Upon the issuance of the Certificate of Compliance, the Harnett County Tax Department shall be notified of the removal to
ensure proper listing.
*The demolition contractor is responsible for submitting verification of proper disposal prior to the Final inspection.
PLEASE NOTEFailure to completely demolish, remove, and clear the premises will result in the withholding of the Certificate
of Compliance. Thus, future permits for the property will be denied, and fines may be imposed for failure to complete demolition/
removal.
If permits are greated in acceptance to address to all auditors and in a file of the control of
If permits are granted I agree to conform to all ordinances and laws of the State of North Carolina regulating such work and the specifications of plans submitted. I hereby state that foregoing statements are accurate and correct to the best of my knowledge. Permit subject to revocation if false information is provided.
Slooming of Owners of Owne

This application expires 6 months from the initial date if no permits have been issued

Asbestos requirements are applicable if the occupancy use is or changes to Commercial (not residential), or if multiple structures are being demolished & removed at one time.

An Asbestos Inspection Report prepared by an N.C. Accredited Asbestos Inspector must be provided with application to demolish any building including residences demolished for commercial or industrial expansion or structures. It is the contractor's responsibility to properly notify the Department of Health and Human Services Division of Public Health – Health Hazards Control Unit at least ten (10) working days before the demolition is to begin whether or not the building is known to contain asbestos.

I hereby certify that the information on this application is correct and that all work in connection with the above referenced job will be performed under my supervision and that such work complies with the requirements of the NC State Building Codes and applicable Harnett County Ordinances. Call for inspection at proper stage of work.

CONTRACTOR / APPLICANT

4-17-19

DATE

LICENSE NO. (If applicable)

Please contact the Department of Health and Human Services for their requirements and permit information. http://www.epi.state.nc.us/epi/asbestos/ahmp.html

Innes Environmental Associates, LLC

Doug Guild, President, Senior Environmental Scientist
536 BOWDEN ROAD, CHAPEL HILL, NC 27516-5505
TEL 919-280-6185 cell

April 10, 2019

Cecil Holcombe CH Demolition 8315 La Matisse Road Raleigh, North Carolina 27615

> JOB: 2 Single Family Homes, Remains of commercial building, 166 and 168 Kit Stewart Lane, Fuquay-Varina, NC

RE: Asbestos Inspection Services

Dear Mr. Holcombe:

We are pleased to provide you with this report detailing our asbestos inspection services completed on 4/8/19. We completed a review of the two subject homes and the remains of a commercial building for a determination of suspect building materials that may contain asbestos. Representative samples were collected and these were taken under proper Chain-Of-Custody procedures to an independent, licensed, and fully accredited laboratory for analysis. There were thirty-three (33) samples collected. In summary, none of the samples that were submitted for analysis were reported as positive for asbestos by laboratory analysis. The laboratory report is attached.

INNES ENVIRONMENTAL ASSOCIATES, LLC

Page 2 Holcombe April 10, 2019

Please let me know if you have any questions on this report or on the project in general. Thank you for the opportunity to complete this work for you.

Sincerely yours,

INNES ENVIRONMENTAL ASSOCIATES, LLC

Douglas Guild, President/CEO NC Asbestos Inspector #10673

Attachment

TABLE 1

Bulk Asbestos Samples - Single Family Home

166 and 168 Kit Stewart Lane, Fuquay-Varina, NC

A-1	Drywaii Composite - walls	Throughout	Not Detected	Good	UNK
A-2	Drywall Composite - walls	Throughout	Not Detected	Good	UNK
A-3	Linoleum	Front Bedroom Bath	Not Detected	Fair	50 SF
A-4	Linoleum	Front Bedroom Bath	Not Detected	Fair	50 SF
A-5	12" X 12" Ceiling Tile	Throughout	Not Detected	Good	1500 SF
A-6	12" X 12" Ceiling Tile	Throughout	Not Detected	Good	1500 SF
A-7	Linoleum	Kitchen, back rooms	Not Detected	Fair	800 SF
A-8	Linoleum	Kitchen, back rooms	Not Detected	Fair	800 SF
A-9	Drywall Composite - cellings	Throughout	Not Detected	Fair	275 SF
A-10	Drywail Composite - ceilings	Throughout	Not Detected	Fair	275 SF
A-1 1	Attic Insulation	Attic	Not Detected	Good	1500 SF
A-12	Attic insulation	Attic	Not Detected	Good	1500 SF
A-13	Roof	Roof	Not Detected	Good	2000 SF
A-14	Roof	Roof	Not Detected	Good	2000 SF
A-15	Linoleum	Central Bath	Not Detected	Fair	25 SF

			Carrier and an			
A-16	Linoleum	Central Bath	Not Detected	Fair	25 SF	
A-17	Linoleum	Side Bath	Not Detected	Fair	25 SF	
A-18	Linoleum	Side Bath	Not Detected	Fair	25 SF	
A-19	Roof	Roof	Not Detected	Good	2000 SF	
2H - A-1	Drywall Composite - walls	2nd House walls	Not Detected	Good	UNK	
2H - A-2	Drywall Composite - walls	2nd House walls	Not Detected	Good	UNK	
2H - A-3	Drywall Composite - ceilings	2nd House ceilings	Not Detected	Good	1500 SF	
2H - A-4	Drywall Composite - ceilings	2nd House cailings	Not Detected	Good	1500 SF	
2H - A-5	Linoleum	Kitchen, Laundry, Dining	Not Detected	Good	450 SF	
2H - A-6	Linaleum	Kitchen, Laundry, Dining	Not Detected	Good	450 SF	
H - A-7	Linoleum	Central and Master Baths	Not Detected	Good	75 SF	
8-A - H	Lino le um	Central and Master Baths	Not Detected	Good	75 SF	
H - A-9	Roof	Roof	Not Detected	Good	1500 SF	
H - 1-10	Roof	Roof	Not Detected	Good	1500 SF	
BB A-1	Plaster	Inside exterior brick	Not Detected	Poor	500 SF	
8 A-2	Plaster	Inside exterior brick	Not Detected	Poor	500 SF	
B A-3	Roofing	Roofing lying on ground	Not Detected	Poor	UNK	
B A-4	Roofing	Roofing lying on ground	Not Detected	Poor	UNK	