

4/18/19

Initial Application Date: _____

Application # RES 1904-0011

COUNTY OF HARNETT DEMOLITION APPLICATION

Central Permitting 108 E. Front Street, Lillington, NC 27546 Phone: (910) 893-7525 Fax: (910) 893-2793 www.harnett.org/permits

LANDOWNER: GHD-Woodgrove, LLC Mailing Address: 1330 Sunday Dr. Ste. 105

City: Raleigh State: NC Zip: 27607 Contact # 919-422-5741 Email: jwhite@greenhawkcorp.com

APPLICANT: Cecil Holcomb Demolition Inc Mailing Address: 8315 La Matisse Rd.

City: Raleigh State: NC Zip: 27615 Contact # 919-876-4060 Email: chdemolition@wcl.com

*Please fill out applicant information if different than landowner

CONTACT NAME APPLYING IN OFFICE: _____ Phone # _____

PROPERTY LOCATION: Subdivision: 168 Kit Stewart Ln. FV Lot #: _____ Lot Size: _____

State Road # _____ State Road Name: _____ Map Book & Page: 1

Parcel: _____ PIN: 0653-77-4878.000

Zoning: _____ Flood Zone: _____ Watershed: _____ Deed Book & Page: 1

SPECIFIC DIRECTIONS TO THE PROPERTY FROM LILLINGTON: US 401 North go
approximately 10 miles and take right on
Kit Stewart Ln. and you are at your
destination.

Structure(s) to be demolished & removed: Single family dwelling Manufactured Home _____ Other (specify) remains of Comm. bldg.

Structures (existing and/or proposed): Single family dwellings _____ Manufactured Homes _____ Other (specify) _____

Water Supply: County Existing Well

Sewage Supply: Existing Septic Tank County Sewer

- * If a new structure is to be replaced on this lot, please ensure that existing septic system is not damaged.
- * If an existing well is on site and is to be discontinued, please contact Harnett County Environmental Health for assistance.
- *Upon the issuance of the Certificate of Compliance, the Harnett County Tax Department shall be notified of the removal to ensure proper listing.
- *The demolition contractor is responsible for submitting verification of proper disposal prior to the Final inspection.

PLEASE NOTE Failure to completely demolish, remove, and clear the premises will result in the withholding of the Certificate of Compliance. Thus, future permits for the property will be denied, and fines may be imposed for failure to complete demolition/ removal.

If permits are granted I agree to conform to all ordinances and laws of the State of North Carolina regulating such work and the specifications of plans submitted. I hereby state that foregoing statements are accurate and correct to the best of my knowledge. Permit subject to revocation if false information is provided.

Cecil Holcomb
Signature of Owner or Owner's Agent

4-17-19
Date

This application expires 6 months from the initial date if no permits have been issued

Asbestos requirements are applicable if the occupancy use is or changes to Commercial (not residential), or if multiple structures are being demolished & removed at one time.

An Asbestos Inspection Report prepared by an N.C. Accredited Asbestos Inspector must be provided with application to demolish any building including residences demolished for commercial or industrial expansion or structures. It is the contractor's responsibility to properly notify the Department of Health and Human Services Division of Public Health – Health Hazards Control Unit at least ten (10) working days before the demolition is to begin whether or not the building is known to contain asbestos.

I hereby certify that the information on this application is correct and that all work in connection with the above referenced job will be performed under my supervision and that such work complies with the requirements of the NC State Building Codes and applicable Harnett County Ordinances. Call for inspection at proper stage of work.

Cecil Holcomb

CONTRACTOR / APPLICANT

4-17-19

DATE

23312

LICENSE NO. (If applicable)

Please contact the Department of Health and Human Services for their requirements and permit information.
<http://www.epi.state.nc.us/epi/asbestos/ahmp.html>

Asbestos requirements are applicable if the occupancy use is or changes to Commercial (not residential), or if multiple structures are being demolished & removed at one time.

An Asbestos Inspection Report prepared by an N.C. Accredited Asbestos Inspector must be provided with application to demolish any building including residences demolished for commercial or industrial expansion or structures. It is the contractor's responsibility to properly notify the Department of Health and Human Services Division of Public Health – Health Hazards Control Unit at least ten (10) working days before the demolition is to begin whether or not the building is known to contain asbestos.

I hereby certify that the information on this application is correct and that all work in connection with the above referenced job will be performed under my supervision and that such work complies with the requirements of the NC State Building Codes and applicable Harnett County Ordinances. Call for inspection at proper stage of work.

Cecil Holcomb
CONTRACTOR / APPLICANT

4-17-19
DATE

23312
LICENSE NO. (if applicable)

**Please contact the Department of Health and Human Services for their requirements and permit information.
<http://www.epi.state.nc.us/epi/asbestos/ahmp.html>**

Innes Environmental Associates, LLC

Doug Guild, President, Senior Environmental Scientist

536 BOWDEN ROAD, CHAPEL HILL, NC 27516-5505

doug@innesenvironmental.com

TEL 919-260-6185 cell

April 10, 2019

Cecil Holcombe
CH Demolition
8315 La Matisse Road
Raleigh, North Carolina 27615

JOB: 2 Single Family Homes, Remains of commercial building, 166 and 168
Kit Stewart Lane, Fuquay-Varina, NC

RE: Asbestos Inspection Services

Dear Mr. Holcombe:

We are pleased to provide you with this report detailing our asbestos inspection services completed on 4/8/19. We completed a review of the two subject homes and the remains of a commercial building for a determination of suspect building materials that may contain asbestos. Representative samples were collected and these were taken under proper Chain-Of-Custody procedures to an independent, licensed, and fully accredited laboratory for analysis. There were thirty-three (33) samples collected. In summary, none of the samples that were submitted for analysis were reported as positive for asbestos by laboratory analysis. The laboratory report is attached.

INNES ENVIRONMENTAL ASSOCIATES, LLC

Page 2
Holcombe
April 10, 2019

Please let me know if you have any questions on this report or on the project in general. Thank you for the opportunity to complete this work for you.

Sincerely yours,

INNES ENVIRONMENTAL ASSOCIATES, LLC

Douglas Guild, President/CEO
NC Asbestos Inspector #10673

Attachment

TABLE 1

Bulk Asbestos Samples - Single Family Home
 166 and 168 Kit Stewart Lane, Fuquay-Varina, NC

A-1	Drywall Composite - walls	Throughout	Not Detected	Good	UNK
A-2	Drywall Composite - walls	Throughout	Not Detected	Good	UNK
A-3	Linoleum	Front Bedroom Bath	Not Detected	Fair	50 SF
A-4	Linoleum	Front Bedroom Bath	Not Detected	Fair	50 SF
A-5	12" X 12" Ceiling Tile	Throughout	Not Detected	Good	1500 SF
A-6	12" X 12" Ceiling Tile	Throughout	Not Detected	Good	1500 SF
A-7	Linoleum	Kitchen, back rooms	Not Detected	Fair	800 SF
A-8	Linoleum	Kitchen, back rooms	Not Detected	Fair	800 SF
A-9	Drywall Composite - ceilings	Throughout	Not Detected	Fair	275 SF
A-10	Drywall Composite - ceilings	Throughout	Not Detected	Fair	275 SF
A-11	Attic Insulation	Attic	Not Detected	Good	1500 SF
A-12	Attic Insulation	Attic	Not Detected	Good	1500 SF
A-13	Roof	Roof	Not Detected	Good	2000 SF
A-14	Roof	Roof	Not Detected	Good	2000 SF
A-15	Linoleum	Central Bath	Not Detected	Fair	25 SF

A-16	Linoleum	Central Bath	Not Detected	Fair	25 SF
A-17	Linoleum	Side Bath	Not Detected	Fair	25 SF
A-18	Linoleum	Side Bath	Not Detected	Fair	25 SF
A-19	Roof	Roof	Not Detected	Good	2000 SF
2H - A-1	Drywall Composite - walls	2nd House walls	Not Detected	Good	UNK
2H - A-2	Drywall Composite - walls	2nd House walls	Not Detected	Good	UNK
2H - A-3	Drywall Composite - ceilings	2nd House ceilings	Not Detected	Good	1500 SF
2H - A-4	Drywall Composite - ceilings	2nd House ceilings	Not Detected	Good	1500 SF
2H - A-5	Linoleum	Kitchen, Laundry, Dining	Not Detected	Good	450 SF
2H - A-6	Linoleum	Kitchen, Laundry, Dining	Not Detected	Good	450 SF
2H - A-7	Linoleum	Central and Master Baths	Not Detected	Good	75 SF
2H - A-8	Linoleum	Central and Master Baths	Not Detected	Good	75 SF
2H - A-9	Roof	Roof	Not Detected	Good	1500 SF
2H - A-10	Roof	Roof	Not Detected	Good	1500 SF
BB A-1	Plaster	Inside exterior brick	Not Detected	Poor	500 SF
BB A-2	Plaster	Inside exterior brick	Not Detected	Poor	500 SF
BB A-3	Roofing	Roofing lying on ground	Not Detected	Poor	UNK
BB A-4	Roofing	Roofing lying on ground	Not Detected	Poor	UNK