Builder John Wisson RON HISE 910-984-5089 134 Widgen Way Thomas MANOR Concrete Pation
Existang 4" Cut out slab for posts to sit on new footings. 6

ROW HISE Bullder John Wilson 134 WIOSON WAY 910-989-5088 Thomas MANOR Collar ties every third VINH Slding 2x6 ceiling joists 16"oc per code Yxy Post Brackets BEAM 2×10 50/10 to AHACL post to Beam Yxyx8 4'oc Sleeved Post villa Post footings to be 18x18x8 under roof support beams. Cut YMY post Bracket out existing slab at post and dig footing AHACKED to concrete below existing slab. Post must sit on new 2xy treatd footing.

PlATES