



October 10, 2019

Howard Babbitt  
56 East Williams Street  
Angier, NC 27501  
Email: Hbabbitt@ncparkrentals.com

Reference: Engineering Services  
26 Sunrise Lane  
Angier, NC 27501  
Project No.: 1901-020577

As requested by the client, a representative of Tyndall Engineering & Design, PA (TE&D) was on-site on to observe the following:

- 1) Damage to the existing roof structure and the rear right walls of the dwelling due to a previous fire.

The following conclusions and recommendations were noted:


- 1) Based on our observations and analysis, TE&D recommends modifying the existing damaged roof in general accordance with the plans attached on pages 3 and 4 of this report.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,  
Tyndall Engineering & Design


Jasmine Paddock  
JMP/ 1901-020577

Prentice Tyndall Jr., P.E.









**OPTION 1 ROOF PLAN**

Engineers and does not include construction plans, methods, techniques, equipment, procedures or safety precautions. Any modification or change in scope of work shall be subject to the written approval of Tyndall Engineering & Design, P.A. Plans to be used only for Tyndall Engineering & Design, P.A. facility. Plans reflect those documents available. Tyndall Engineering & Design, P.A. will not be held liable for any errors, omissions, or delays provided to these documents were based on acceptable source information.

**TYNDALL**  
ENGINEERING & DESIGN, P.A.



1 919 773-1000 • 1 919 773-9688  
340 Shipwash Drive • Garner • North Carolina • 27829  
www.tyndallengineering.com

**CLIENT:**  
HOWARD RABBITT  
86 E. WILLIAMS STREET  
ANGIER, NC 27801

**TYPE:**  
ROOF REPAIRS  
28 SUNRISE LANE  
ANGIER, NC 27801



Project: 1901-020377  
Date: 10/04/2019  
Drawing Title: IMP  
Client: Howard R. Rabitt  
Rev: 001  
Sheet Title: ROOF PLAN

REVISIONS	
NO.	REMARKS