



**TYNDALL**  
ENGINEERING & DESIGN, P.A.

1 919 773-1200 • F 919 773-9658  
250 Shipwash Drive Suite 104 • Garner • North Carolina • 27529  
www.tyndallengineering.com

October 10, 2019

Howard Babbitt  
56 East Williams Street  
Angier, NC 27501  
Email: Hbabbitt@ncparkrentals.com

Reference: Engineering Services  
26 Sunrise Lane  
Angier, NC 27501  
Project No.: 1901-020577

As requested by the client, a representative of Tyndall Engineering & Design, PA (TE&D) was on-site on to observe the following:

- 1) Damage to the existing roof structure and the rear right walls of the dwelling due to a previous fire.

The following conclusions and recommendations were noted:

- 1) Based on our observations and analysis, TE&D recommends modifying the existing damaged roof in general accordance with the plans attached on pages 3 and 4 of this report.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,  
Tyndall Engineering & Design

Jasmine Paddock  
JMP/ 1901-020577

Prentice Tyndall Jr., P.E.







