CERTIFICATE OF COMPLETION / OPERATIONAL PERMIT

Name: (owner) LARRY Allen	New Installation	Sentic Tenk
Property Location: SR# 141 Micro Tower Subdivision High land H.115	☐ Repairs	Nitrification Line
Subdivision Highland Hills	Lot# 136	× Trumication Line
TAX ID#	Ouadrant #	
Contractor: WAYNE 5 harpe	Registration #	
Basement with Plumbing: Garage: G		
Water Supply: Well Public Community		
Distance From Well: ft.		
Following are the specifications for the sewage disposal	l system on above co	entioned
		aptioned property.
Type of system: Conventional Other		-
Size of tank: Septic Tank: 1000 gallons Pump T	ank: gallons	3
Subsurface No. of exact length of each ditch 100 ft	width of	depth of
French Drain: Linear feet	. ditches ft.	ditches <u> </u>
Deta	3-28-95	
	ected by:: Dr Un	ARI
Ilispe		
	Environmental H	lealth Specialist
		1
2.21.95 103-1000 Com-1000		
103- 103		
comiss		
11000		
	\ \	
3Be		
SDE		
,\		10
	4	
	7 7	
	100 10	2

IMPROVEMENT PERMIT

Be it ordained by the Harnett County Board of Health as follows: Section III, Item B. "No person shall begin construction of any building at which a septic tank system is to be used for disposal of sewage without first obtaining a written permit from the Harnett County Health Department".

Name: (owner) Larry Allen New Installation Septic Tank		
Property Location: SR#		
Subdivision High I and Hills Lot # 136		
Tax ID# Quadrant #		
Number of Bedrooms Proposed: 3 Lot Size: 1.0AC		
Basement with Plumbing: Garage:		
Water Supply: Well Public Community		
Distance From Well: NA ft.		
Following is the minimum specifications for sewage disposal system on above captioned property. Subject to final approval.		
Type of system: Other		
Size of tank: Septic Tank: gallons Pump Tank: gallons		
Subsurface No. of exact length width of depth of ditches of each ditch ft. ditches ft. ditches in.		
French Drain required: Linear feet		
This permit is subject to revocation if site plans or intended use change. Date: 5 - 3 8 - 9 4 Signed: Mere Butter R		
VOID AFTER 5 YEARS Permit Conding F Deninsiel Environmental Health Specialist Contour is Problem in rear, ESTABLISH deninsield to Front.		