

Seacoast Engineering, P.C.

Geotechnical & Structural Engineering

5111 Everette Court Wilmington, NC 28412 Phone: (910) 622-4001 NC License No. C-2917

December 15, 2020

Clayton Homes, Inc. 2001 W. Cumberland Drive Dunn, North Carolina 28334

Reference: Soil Evaluation

11 Wood Valley Drive Erwin, North Carolina

Dear Sirs,

Seacoast Engineering P.C. recently provided a soil evaluation within the residential manufactured home being set at 11 Wood Valley Drive located in Erwin, North Carolina. This letter is the report of our findings and evaluations.

The manufactured home is to be set at 11 Wood Valley Drive. There is standing water in the bottom of some of the footings.

Based on the results of our evaluation, we recommend pumping out the water and remove any soft soils then replace it with a no. 57 stone. The footings than can be filled with conctete.

All organic matter, such as tree stumps and root systems, should be removed from all structural areas, such as subgrades for foundations and ground-supported slabs. All disturbed zones left from stump and/or root system removal within structural areas should be properly backfilled and compacted.

If you have any questions after reviewing this, letter, please do not hesitate to contact us at your convenience.

Respectfully,

Michael A. Copeland, P.E.