

OPERATIONS PERMIT

Name: (owner) Custom Contracting New Installation Septic Tank
Property Location: SR# 1201 Repairs Nitrification Line
Subdivision Carolina Season Lot # V-11
TAX ID# _____ Quadrant # _____
Contractor: W. Spivey Registration # _____


Basement with Plumbing: Garage:
Water Supply: Well Public Community
Distance From Well: 50 min ft.

Following are the specifications for the sewage disposal system on above captioned property.

Type of system: Conventional Other _____
Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons
Subsurface No. of exact length width of depth of
Drainage Field ditches 3 of each ditch 70 ft. ditches 3 ft. ditches 1824 in.
French Drain: _____ Linear feet

Date: 11-8-96
Inspected by: [Signature]
Environmental Health Specialist

PERMIT NO. 10447



IMPROVEMENT PERMIT

Be it ordained by the Harnett County Board of Health as follows: Section III, Item B. "No person shall begin construction of any building at which a septic tank system is to be used for disposal of sewage without first obtaining a written permit from the Harnett County Health Department".

Name: (owner) Custom Contracting Corp New Installation Septic Tank
Property Location: SR# 1201 Ponderosa Rd Repairs Nitrification Line
Hunters Ridge

Subdivision Carolina Seasons Ph IV Lot # V-11

Tax ID# _____ Quadrant # _____

Number of Bedrooms Proposed: 3 Lot Size: 0.66 AC

Basement with Plumbing: Garage:

Water Supply: Well Public Community

Distance From Well: 50m ft.

Following is the minimum specifications for sewage disposal system on above captioned property. Subject to final approval.

Type of system: Conventional Other _____

Size of tank: Septic Tank: 1000 gallons Pump Tank: _____ gallons

Subsurface No. of 3 exact length 70 width of 3 depth of 18-24 in.
Drainage Field ditches of each ditch ft. ditches ft. ditches in.

French Drain required: _____ Linear feet

This permit is subject to revocation if site plans or intended use change.

Date: 7-27-96

Signed: [Signature]

Environmental Health Specialist

VOID AFTER 5 YEARS

