

т 919 773-1200 = г 919 773-9658

250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com

September 2, 2021 Revised September 22, 2021

Jason Buie Buie Construction P.O. Box 612

Buies Creek, NC 27506 Email: <u>buiebuilt@gmail.com</u>

Reference: Engineering Services

188 Saddle Lane Lillington, NC 27546

Project No.: DRB2001-0046A-R

As requested by the client, Tyndall Engineering & Design (TE&D) is providing analysis for the following items:

1) Analysis of (3) 2 x 10 beam supporting vaulted ceiling for attic renovation.

The following conclusions and recommendations were noted:

1) Based on our observations and analysis, the existing (3) 2 x 10 beam is suitable to support the anticipated loading conditions. No structural modifications are required.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,

Tyndall Engineering & Design

Tripp Amos

PT III | DRB2001-0046A-R

Triggs Amos

Revised 9/22/21

Prentice Tyndall Jr., P.E.



τ 919 773-1200 = ε 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com



