

## Permit Inspections Harnett County

Permit Number: BRES2203-0057 Description: 13.8 x 21.2 bedroom addition

Applied: 3/24/2022 Approved: 11/14/2022 Site Address: 1861 US 401 S

Issued: 1/4/2023 Finaled: City, State Zip Code: LILLINGTON, NC 27546

Status: ISSUED Applicant: CRUZ GABRIEL CABRERA
Parent Permit: Owner: CRUZ GABRIEL CABRERA

Parent Project: Contractor: CRUZ GABRIEL CABRERA

Details:

LIST OF INSPECTIONS									
SEQ ID	SCHEDULED DATE	COMPLETED DATE	ТҮРЕ	INSPECTOR	RESULT	REMARKS			
			MONO SLAB	Steven Gazlay					
Notes:	Notes:								
			SLAB	Steven Gazlay					
Notes:									
			UNDER SLAB TRADES	Steven Gazlay					
Notes:									
	9/29/2023	9/29/2023	FOOTING	John B Kokoszka	DISAPPROVED				
	Notes: Inspector JTH changed the inspection assignment from JTH to JBK No plans on site								
	10/4/2023	10/4/2023	FOOTING	James T Hall	DISAPPROVED				
Notes:  1. Footing needs to be under existing footing on each corner of house 1' for continuous footing2. Need to support Reid bar 3" from bottom of footing and extend Reid bar under each corner of house									
	10/10/2023	10/10/2023	FOOTING	James T Hall	APPROVED				
Notes:									
Inspecto	or SPG changed the inspe	ction assignment from SP	G to JTH						
	10/26/2023	10/26/2023	FOUNDATION	John B Kokoszka	APPROVED				
Notes: Inspector JTH changed the inspection assignment from JTH to JBK									
	11/2/2023	11/2/2023	OPEN FLOOR	John B Kokoszka	DISAPPROVED				
Notes:  Need to have 18" from the bottom of joist to dirt. Or needs to be treated wood									
	11/6/2023	11/6/2023	OPEN FLOOR	Daniel L Floyd	APPROVED				
Notes:									



## Permit Inspections Harnett County

	3/1/2024	3/1/2024	ROUGH IN	James T Hall	FAIL W/ PENALTY				
Notes:  Missing 2-2x10 header over door at laundry roomMissing nails in hurricane strap over back doorMissing hurricane strap and nails in hurricane straps on back wall in bedroomInsulation bafflesFire caulk refrigerant lines on end wall in bedroomMissing air barrier on wall over old roof up to top plate, behind									
tub and in chase at end of tubMissing nailer to nail tub surroundFire caulk all holes and wires through top and bottom platesNeed to seal around tub drainNeed 3' head of water on drain line testNeed 100 psi on water line test had 77 psiNeed 2' walkway to AHU in atticRafter can not be wider than ridge beamHeal of rafter needs to bare solid on 2x on roof in atticPlumbing vent in attic needs to go 6" above ew roofRed light and receptacle at AHU in atticNeed smoke detector inside front bedroom and combo smoke and carbon outside bedroom and they need to all be interconnectedCrawl space access needs to be 18" x24" per code									
access i	3/5/2024	3/5/2024	ROUGH IN REINSPECT	James T Hall	FAIL W/ PENALTY				
Notes:  Insulation bafflesFire caulk refrigerant lines on end wall in bedroomMissing air barrier on wall over old roof up to top plate, behind tub and in chase at end of tubNeed 100 psi on water line test had 44 psiRafter can not be wider than ridge beamHeal of rafter needs to bare solid on 2x on roof in atticPlumbing vent in attic needs to go 6" above ew roofNeed light and receptacle at AHU in atticNeed smoke detector inside front bedroom and combo smoke and carbon outside bedroom and they need to all be interconnectedCrawl space access needs to be 18" x24" per code									
Silloke (	3/11/2024	3/11/2024	ROUGH IN REINSPECT	John B Kokoszka	DISAPPROVED	- per code			
Notes: Floor Jo									
	3/14/2024	3/14/2024	ROUGH IN REINSPECT	Daniel L Floyd	APPROVED				
Notes: Items fr	Notes:  Items from the previous inspection were completed								
	3/18/2024	3/18/2024	INSULATION	John B Kokoszka	APPROVED				
Notes:									
	7/31/2024	7/31/2024	UNDER SLAB TRADES	James T Hall	DISAPPROVED				
Notes:  No under slab plumbing here									
	8/2/2024	8/2/2024	SEWER CONNECTION	John B Kokoszka	DISAPPROVED				
Notes: The slop	pe of the sewer needs to	drain the tank. The slope	is drain back to the	house within the f	re 5 ft				
	8/14/2024	8/14/2024	SEWER CONNECTION	James T Hall	DISAPPROVED				
Notes:  Need sweep fitting at cleanout not T fittingBed pipe per codeNeed correct pipe 1 section of pipe has no label on it									
	10/1/2024	10/1/2024	SEWER CONNECTION	James T Hall	DISAPPROVED				
Notes:  Bed pipe per code ditch full of water Missing cleanouts per code									
	10/9/2024	10/9/2024	SEWER CONNECTION	James T Hall	APPROVED				
Notes:									



## Permit Inspections Harnett County

0	9/12/2023	9/12/2023	ENVIR OPERATIONS PERMIT	Oliver Tolksdorf	APPROVED			
Notes:								
50			FINAL**	Steven Gazlay				
Notes:								
50	7/17/2024	7/17/2024	FINAL**	John B Kokoszka	CANCELLED			
Notes:								
Inspecto	Inspector SPG changed the inspection assignment from SPG to JBK							
not ready 1. Need ladder for attic access2. Missing expansion tank on hot water heater3. Need to seal around toilet4. Need to seal around sink drain in bathroom5. Missing rear steps6. Need to sell sleeve at sewer line7. Need to get the sewer line inspected before finals8. Crawlspace access 18 x 249. Sewer line needs to be in beddeddidn't look in crawlspace because it's full of dirt. Need to call in sewer lines inspection before final. Need to do complete final inspection on the addition. just noticed a couple of things								
50	10/11/2024	10/18/2024	FINAL**	Deen Taylor	DISAPPROVED			
Notes:								
Unable to locate expansion tank								
50	10/29/2024	10/29/2024	FINAL**	James T Hall	DISAPPROVED			
Notes:	Notes:							
Inspector JBK changed the inspection assignment from JBK to JTH								
House locked								
50	10/31/2024	10/31/2024	FINAL**	Ricardo D Honrada	DISAPPROVED			
Notes:								
Custom	Customer said the house is not occupied & the back door will be unlocked.							

Need to pass the failed inspection mechanical, electrical and plumbing.