

т 919 773-1200 = F 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com

July 8, 2022

Josh Harlow Harlow Construction, LLC 199 Chase Street Cameron, NC 28326

Email: joshaharlow@gmail.com

Reference: Engineering Services

55 Wessex Court Cameron, NC 28326

TE&D Project No.: 2201-020599

To Whom It May Concern;

As requested, a representative of Tyndall Engineering & Design, PA (TE&D) was on-site to observe the following item(s):

1) Observation of notched rafters at roof overhang for rear screened-in porch.

The following conclusions and recommendations were noted:

1) We observed the 2 x 6 at 16" o.c. rafters as having been notched up to 2-1/2" where the rafters bear at the left and right exterior walls. Based on our observations and analysis, the notched rafters are adequate to support the anticipated loading conditions. No action needed.

We appreciate being able to assist you during this phase of the project. If you need further assistance or require additional information, please do not hesitate to contact us.

Sincerely,

Tyndall Engineering & Design

riggs Amos

Tripp Amos

PT III | 2201-020599

Prentice Tyndall Jr., P.E.



τ 919 773-1200 = ε 919 773-9658 250 Shipwash Drive, Suite 104 = Garner = North Carolina = 27529 www.tyndallengineering.com





Example of notched rafters