

Permit Inspections Harnett County

Permit Number: BRES2207-0018 Description: 24 x 24 attached garage

Applied: 7/8/2022 Approved: 7/22/2022 Site Address: 155 BLUE PINE DR

Issued: **7/22/2022** Finaled: **10/18/2023** City, State Zip Code: **SPRING LAKE, NC 28390**

Status: FINALED Applicant: Autry Danny
Parent Permit: Owner: FERGUSON ROSE

Parent Project: Contractor: FERGUSON ROSE

Details:

	LIST OF INSPECTIONS							
	SEQ ID	SCHEDULED DATE	COMPLETED DATE	ТҮРЕ	INSPECTOR	RESULT	REMARKS	
		8/1/2022	8/1/2022	FOOTING	John B Kokoszka	DISAPPROVED		
N	Notes:							
s	Scheduled by Jeff Autry							

Footing had water in it. The bottom of the footing need to be at frost level 12' below gradePipe sleeve need to be 2 sizes bigger and Annular space need to be filled. Cannot use corrugated pipe

8/4/2022	8/4/2022	FOOTING	Steven Gazlav	DISAPPROVED	eTRAKiT Inspection Request
0,7,2022	0/ -/ 2022	10011110	Jickell Gazlay	DISKITIKOVED	c in this inspection request

Notes:

8/2/2022 10:39 AM Danny Autry Sr

Contact Name: Danny Autry Sr Site Address: 155 BLUE PINE DR

Phone: 9192621867

e-Mail: danny.autry@yahoo.com

Inspector JTH changed the inspection assignment from JTH to SPG

Footing must be continuous across garage door opening. Dowel into existing footing.

Tooting	outing must be continuous across garage door opening. Dower into existing rooting.							
	8/5/2022	8/5/2022	FOOTING	James T Hall	APPROVED	eTRAKiT Inspection Request		
Notes:								
	9/7/2022	9/7/2022	FOUNDATION	James T Hall	APPROVED			
Notes:								
Please call Rose Ferguson (owner) before going out at (910)578-3688.								
	9/25/2023	9/25/2023	FINAL**	Steven Gazlay	DISAPPROVED			
Notes:								
Missing section of railing by roof.								
	10/18/2023	10/18/2023	FINAL**	Daniel L Floyd	APPROVED			
Notes:								



Permit Inspections Harnett County

20	10/6/2022	10/6/2022	FOUNDATION SURVEY	Donna Johnson	APPROVED				
Notes:									
30	11/14/2022	11/14/2022	ROUGH IN	James T Hall	DISAPPROVED				
plate joi 24"6.Mi old wire with and	Notes: 1.No truss docs on site for inspection2. Nail garage door header every 12" per docs3. Fire caulk all wires at top plate per code4. Missing stud under top plate joint to left and 2 places to right of window5. Need to strap top plate joint to left of window over window and to right of window joint less than 24"6. Missing 2 king studs each side of window in garage7. Missing stud under top plate joint on back wall8. Need to install junction box with access on old wires for garage lights on right side of garage9. Fire block crack at top plate where wall joins house 10. Need to anchor load bearing wall against house with anchor bolts per code11. Stud under top plate joint over man door12. Need to flash roof where it joins house and need access to see roof13. Need engineer letter for design of roof /floor								
30	12/7/2022	12/7/2022	ROUGH IN REINSPECT	James T Hall	FAIL W/ PENALTY				
Notes: Items #1, 4, 5, 7, 8, 11, 12 & 13 were not corrected									
30	4/20/2023	4/20/2023	ROUGH IN REINSPECT	James T Hall	DISAPPROVED				
Notes:									
Waiting on engineer third party letter or the picture of the 2x4 vertical in floor trusses per engineers repair letter									
30	4/21/2023	4/21/2023	ROUGH IN REINSPECT	James T Hall	APPROVED	per eng letter			
Notes:	Notes:								