



Permit Inspections Harnett County

Permit Number: BRES2211-0028

Description: **16x36 Workshop/garage**

Applied: **11/9/2022**

Approved: **12/14/2022**

Site Address: **3905 MCLEAN CHAPEL CHURCH RD**

Issued: **12/14/2022**

Finalized:

City, State Zip Code: **BUNNLEVEL, NC 28323**

Status: **ISSUED**

Applicant: **Amy Mian Lin**

Parent Permit:

Owner: **MOOS FARAM LLC**

Parent Project:

Contractor: **<NONE>**

Details:

LIST OF INSPECTIONS

SEQ ID	SCHEDULED DATE	COMPLETED DATE	TYPE	INSPECTOR	RESULT	REMARKS
			FOUNDATION	Steven Gazlay		
Notes:						
			MONO SLAB	Steven Gazlay		
Notes:						
			SLAB	Steven Gazlay		
Notes:						
			FINAL**	Steven Gazlay		eTRAKIT Inspection Request
Notes:						
	1/4/2023	1/4/2023	FOOTING	John B Kokoszka	DISAPPROVED	eTRAKIT Inspection Request
Notes: 12/29/2022 10:39 PM Li Lin Contact Name: Li Lin Site Address: 3905 MCLEAN CHAPEL CHURCH RD Phone: 6267575472 e-Mail: oztaxx@gmail.com Footing was already poured						
	1/26/2023	1/26/2023	FOOTING	James T Hall	DISAPPROVED	eTRAKIT Inspection Request
Notes: 1/24/2023 2:03 PM Li Lin Please let me know what time you will be there cause I live about an hour away from jobsite. Contact Name: Li Lin Site Address: 3905 MCLEAN CHAPEL CHURCH RD Phone: 6267575472 e-Mail: oztaxx@gmail.com Gate locked need third party letter for footing inspection						





Permit Inspections

Harnett County

	1/27/2023	1/27/2023	FOOTING	John B Kokoszka	DISAPPROVED	eTRAKiT Inspection Request
Notes: Multiple Locations have existing footing. Part of the piers and footings are in the middle of the leach field Vegetation needs to be removed Per plans footings need to be continuous. Need to clean out footings.						
	2/3/2023	2/3/2023	FOOTING	James T Hall	APPROVED	eTRAKiT Inspection Request
Notes: Passed By JK						
	2/3/2023	2/3/2023	OPEN FLOOR	James T Hall	APPROVED	
Notes:						
	3/2/2023	3/2/2023	ROUGH IN	James T Hall	DISAPPROVED	eTRAKiT Inspection Request
Notes: 2/28/2023 7:16 PM Li Lin Contact Name: Li Lin Site Address: 3905 MCLEAN CHAPEL CHURCH RD Phone: 6267575472 e-Mail: oztaxx@gmail.com 1. Need studs under all top plate breaks. 2. Nail girder beam on porch per code. 3. Missing king studs each sides of door & windows per code. 4. Strap all top plate joints That are 24" and less apart. 5. Make up all ground wires in boxes. 6. Fire caulk all holes through top plates per code.						
	3/6/2023	3/6/2023	ROUGH IN REINSPECT	James T Hall	APPROVED	eTRAKiT Inspection Request
Notes:						
	3/15/2023	3/15/2023	FINAL**	James T Hall	CANCELLED	eTRAKiT Inspection Request
Notes: 3/13/2023 6:40 PM Li Lin Contact Name: Li Lin Site Address: 3905 MCLEAN CHAPEL CHURCH RD Phone: 6267575472 e-Mail: oztaxx@gmail.com						
	3/20/2023	3/20/2023	FINAL**	John B Kokoszka	DISAPPROVED	eTRAKiT Inspection Request
Notes: 3/17/2023 1:47 PM Li Lin Contact Name: Li Lin Site Address: 3905 MCLEAN CHAPEL CHURCH RD Phone: 6267575472 e-Mail: oztaxx@gmail.com All upside receptacle need to be GFCI Front step landing needs to be to codeMissing hand rails if more than 30" away at 3 ft from edge						





Permit Inspections Harnett County

	7/14/2025	7/14/2025	FINAL**	James T Hall	DISAPPROVED	eTRAKIT Inspection Request
--	-----------	-----------	---------	--------------	-------------	----------------------------

Notes:
 7/11/2025 9:56 AM Li Lin

Contact Name: Amy Lin
 Site Address: 3905 MCLEAN CHAPEL CHURCH RD
 Phone: 9199031702
 e-Mail: wawamay@gmail.com

Need 3'x3' flat area at bottom of stairs short concrete is a trip hazardNeed to call electrical inspection in at the same time as final

	3/12/2026	3/12/2026	FINAL**	James T Hall	DISAPPROVED	eTRAKIT Inspection Request
--	-----------	-----------	---------	--------------	-------------	----------------------------

Notes:
 3/11/2026 2:16 PM Li Lin

Contact Name: AmyLin
 Site Address: 3905 MCLEAN CHAPEL CHURCH RD
 Phone: 9199031702
 e-Mail: wawamay@gmail.com

Need electrical final scheduled at same time as final building

