

Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

6/9/2023

SUBJECT: BRES2212-0037

BUILDING RESIDENTIAL

To: STAVRINOS PHILIP

Here are the results of all Inspections located at 198 FLETCHER TUTOR RD:

Inspection Type: FOOTING

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: FOUNDATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: INSULATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: MONO SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:



Harnett County

420 Mckinney Pkwy

LILLINGTON,NC 27546

Phone: Fax:

Inspection Type: OPEN FLOOR

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:

Inspection Type: ENVIR OPERATIONS PERMIT

Scheduled Date/Time: Completed Date/Time:

Inspector: EH Bucket

Result: Remarks: Notes:

Inspection Type: FINAL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result: Remarks: Notes:



Harnett County

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: Completed Date/Time:

Inspector: Justin Ryan McLeod

Result:

Remarks: eTRAKiT Inspection Request

Notes:

Inspection Type: ROUGH IN Scheduled Date/Time: 6/7/2023 Completed Date/Time: 6/7/2023

Inspector: Justin Ryan McLeod Result: DISAPPROVED

Remarks: eTRAKiT Inspection Request

Notes: 6/5/2023 1:00 PM Nathan Benson

MECHANICAL

Contact Name: Nathan Benson

Site Address: 198 FLETCHER TUTOR RD

Phone: 9196248943

e-Mail: nate.benson123@gmail.com

1. Fur down rafters or add ceiling joists for r38 insulation. 2. Studs over bored on exterior wall for plumbing by sink

for plumbing by sink.

