



**Harnett County**  
420 McKinney Pkwy  
LILLINGTON, NC 27546  
Phone:  
Fax:

4/6/2023

**SUBJECT: BRES2301-0066**  
**BUILDING RESIDENTIAL**

To: Tommy Core's Residential Construction LLC

Here are the results of all Inspections located at **255 STONEY CREEK DR:**

Inspection Type: FINAL\*\*  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: James T Hall  
Result:  
Remarks:  
Notes:

Inspection Type: ROUGH IN REINSPECT  
Scheduled Date/Time:  
Completed Date/Time:  
Inspector: James T Hall  
Result:  
Remarks:  
Notes:

Inspection Type: FOOTING  
Scheduled Date/Time: 2/22/2023  
Completed Date/Time: 2/22/2023  
Inspector: Steven Gazlay  
Result: DISAPPROVED  
Remarks:  
Notes: Dowel to existing other. 2 pieces number 4 bar each side.

Inspection Type: FOOTING  
Scheduled Date/Time: 2/27/2023  
Completed Date/Time: 2/27/2023  
Inspector: James T Hall  
Result: APPROVED  
Remarks:  
Notes: cus advised Steven said ok for pics



**Harnett County**  
420 McKinney Pkwy

LILLINGTON, NC 27546  
Phone:  
Fax:

Inspection Type: FOUNDATION  
Scheduled Date/Time: 3/8/2023  
Completed Date/Time: 3/8/2023  
Inspector: James T Hall  
Result: DISAPPROVED  
Remarks:  
Notes: Uncover footings for foundation inspection

Inspection Type: FOUNDATION  
Scheduled Date/Time: 3/13/2023  
Completed Date/Time: 3/13/2023  
Inspector: Steven Gazlay  
Result: APPROVED  
Remarks:  
Notes:

Inspection Type: INSULATION  
Scheduled Date/Time: 4/5/2023  
Completed Date/Time: 4/5/2023  
Inspector: Steven Gazlay  
Result: CANCELLED  
Remarks:  
Notes:

Inspection Type: ROUGH IN  
Scheduled Date/Time: 4/5/2023  
Completed Date/Time: 4/5/2023  
Inspector: Steven Gazlay  
Result: DISAPPROVED  
Remarks:  
Notes: Remove insulation to allow for visual inspection, Missing insulation baffles Ridge beam must be longer than cut face of rafter. need collar ties. Seal plumbing penetration to floor. Add cripple studs adjacent doorway. Need tempered window at bathtub. Need correct number of kings and jack studs on opening. Nail ceiling joist to rafters. Block frame fly rafters . Flash penetration for bath fan. Cannot tape over bottom of window flange.

