

DAVID MILLER, PE  
6300 Creedmoor Rd, STE 170#363  
Raleigh, NC 27612  
(919) 422-8932 (Office); [DAVE@DMA-PA.COM](mailto:DAVE@DMA-PA.COM)

August 6, 2018

Ruben Mejia Lira  
E mailed to: [marcoscanales98@gmail.com](mailto:marcoscanales98@gmail.com)  
Ruben Mejia (919)551-1966

RE: Engineering  
75 Currin Drive, Spring Lake, NC  
Project No.: 18DDM-0806E

To Whom It May Concern/Inspections Dept.:

The undersigned arrived on-site on 8-6-18 to to observe the following for the above referenced site. Based on the observations the manufactured home to be remediated was adequate to support the loading conditions for the remedial repairs. Areas of the sheetrock to be removed for the undersigned's observation was outlined in the field. Once these areas are opened the undersigned should observe the conditions and provide recommendations for remedial repairs if needed. The rear deck and roof cover are being analyzed for remedial repairs as well.

Sincerely,

David Miller, PE

DEM18DDM 0806E

