

Joe E Godwin Sr., P.E., P.L.S.

Jason E Godwin, P.L.S.

**ENOCH  
ENGINEERS, P.A.**1403 NC Highway 50 South  
Benson, North Carolina 27504  
919.894.7765Email: [general@enochengineers.com](mailto:general@enochengineers.com)[www.enochengineers.com](http://www.enochengineers.com)**MATERIALS & TEST DIVISION****FIELD REPORT****PROJECT**

CLIENT: GAMMON CONST

DATE: 3.12.25

PROJECT: RESI FOOTINGS

CONTRACTOR: D. GAMMON

ADDRESS: 211 ROLLING ACRES LN

TECHNICIAN: BLH

LOT #: COATS NC

**TEST SUMMARY**

PERFORMED SOIL BEARING CAPACITY EVALUATION OF SITE NOTED ABOVE.  
RECOMMEND 8" UNDERCUT, ADD 8" OF WASHED #57 STONE THROUGHOUT  
MARKED UNDERCUT AREAS AT REAR FOOTING.  
SOILS CONFIRMED A MINIMUM 2000PSF ONCE STONE IS PLACED.

**TESTING RESULTS**


SERVICE PERFORMED	TEST NO.	COMP %	WD PCF	DD PCF	MOISTURE %

**RETURN VISIT REQUIRED**

YES

☐

NO

☒**TECHNICIAN:**Disclaimer:

Soils & Material Inspections, testing results and on-site determinations contained in this report become void after 30 days of non-use of this report and/or following any inclement weather which causes structural soil or material deterioration. Additional testing will be required following a voided report determined by a North Carolina Building Code enforcement official or Enoch Engineers P.A. The client/contractor is responsible for notifying Enoch Engineers P.A. of any soil & material condition changes which could void this report.

3/12/2025, 8:54 AM