

- DETACH AND RESET FRONT DOOR
 - REPLACE VINYL WINDOW
 - REPLACE BURNT FRAMING & INSULATION & DRYWALL
 - REPLACE 2 CONDENSATION UNIT & LINE SETS
 - REPAIR TO WIRING AS NEEDED.
POSSIBLE REPLACE PANEL.
-

PROJECT INVOLVES REPAIRS FOR FIRE DAMAGE.
FIRE WAS AT 2 CONDENSATION UNITS ON SIDE
OF GARAGE. FIRE CAUSED DAMAGE TO SIDING, FRAMING,
INSULATION, DRYWALL, ELECTRICAL & HVAC.
NO DAMAGE TO ROOF OR FOUNDATION.
DAMAGE IS ABOUT A 10' X 10' WALL SECTION.