

Howerton Services, PLLC
License # P-1716
3513 Cathedral Bell Road
Raleigh, NC 27614
(919) 270-3460

August 5, 2024

Subject: 100 Mystic Lane
Lillington, NC 27546
Framing Inspection Letter
Harnett County Permit #: BRES2406-0022

Based on the request of the Contractor, I inspected 1 item in the Screened Porch from the framing inspection notice for code compliance. My assessment and recommendations are as follows:

- Item 1: The Contractor has a triple stud column under the double 11 7/8 LVL ridge beam at the connection to the existing home. The triple stud column is bearing on a double 2x10 header in the inset wall above the window. The LVL ridge beam is properly supported at the existing home.

The 1 item noted above meets all the requirements of the 2018 North Carolina Building Code for Residences.



08 05 2024 EDT