

Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

6/18/2025

SUBJECT: BRES2407-0034

BUILDING RESIDENTIAL

To: Rescue Construction Solution

Here are the results of all Inspections located at 121 STEWART FARM LN:

Inspection Type: ADDRESS

Scheduled Date/Time: Completed Date/Time:

Inspector: GIS Bucket

Result: Remarks: Notes:

Inspection Type: MARRIAGE WALL

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: ROUGH IN

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: SEWER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:





Harnett County

420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone: Fax:

Inspection Type: T-POLE

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: TEMP POWER CERTIFICATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: WATER CONNECTION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: MODULAR FINAL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: ZONING

Scheduled Date/Time: Completed Date/Time:

Inspector: Planning Bucket

Result:

Remarks: Flood final Cert inspection

Notes:



Harnett County

420 Mckinney Pkwy

LILLINGTON,NC 27546

Phone: Fax:

Inspection Type: FOUNDATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: FOOTING
Scheduled Date/Time: 5/21/2025
Completed Date/Time: 5/21/2025
Inspector: James T Hall
Result: APPROVED

Remarks: Notes:

Inspection Type: FOUNDATION Scheduled Date/Time: 6/17/2025 Completed Date/Time: 6/17/2025 Inspector: Deen Taylor Result: DISAPPROVED

Remarks:

Notes:

Top of footing must be exposed for foundation inspection to verify bed joint and projection.

Top of footing must be exposed for foundation inspection to verify bed joint and projection.