



Permit Inspections

Harnett County

Permit Number: **BRES2407-0034**

Description: **58.2x29.7 Off Frame**

Applied: **7/9/2024**

Approved: **9/16/2024**

Site Address: **121 STEWART FARM LN**

Issued: **9/19/2024**

Finalized:

City, State Zip Code: **SPRING LAKE, NC 28390**

Status: **ISSUED**

Applicant: **Rescue Construction Solution**

Parent Permit:

Owner: **DARRIGAN SHERRY STEWART**

Parent Project:

Contractor: **Rescue Construction Solution**

Details:

LIST OF INSPECTIONS

| SEQ ID | SCHEDULED DATE | COMPLETED DATE | TYPE | INSPECTOR | RESULT | REMARKS |
|--|----------------|----------------|--------------------------|-------------------|-------------|---------|
| | | | SEWER CONNECTION | Steven Gazlay | | |
| Notes: | | | | | | |
| | | | T-POLE | Steven Gazlay | | |
| Notes: | | | | | | |
| | | | TEMP POWER CERTIFICATION | Steven Gazlay | | |
| Notes: | | | | | | |
| | | | WATER CONNECTION | Steven Gazlay | | |
| Notes: | | | | | | |
| | 5/21/2025 | 5/21/2025 | FOOTING | James T Hall | APPROVED | |
| Notes: | | | | | | |
| | 6/17/2025 | 6/17/2025 | FOUNDATION | Deen Taylor | DISAPPROVED | |
| Notes: | | | | | | |
| Top of footing must be exposed for foundation inspection to verify bed joint and projection. | | | | | | |
| Top of footing must be exposed for foundation inspection to verify bed joint and projection. | | | | | | |
| | 6/24/2025 | 6/24/2025 | FOUNDATION | James T Hall | DISAPPROVED | |
| Notes: | | | | | | |
| Uncover footings on foundation walls and piers inside and out for inspection | | | | | | |
| | 6/26/2025 | 6/26/2025 | FOUNDATION | Ricardo D Honrada | APPROVED | |
| Notes: | | | | | | |



Permit Inspections

Harnett County

| | | | | | | |
|--|-----------|-----------|--------------------|-----------------|-------------|-----------------------------|
| | 7/11/2025 | 7/11/2025 | MARRIAGE WALL | James T Hall | APPROVED | |
| Notes: | | | | | | |
| | 7/29/2025 | 7/29/2025 | ROUGH IN | James T Hall | DISAPPROVED | |
| Notes: LOCK BOX 4760 Missing nails in collar ties plans call for 14- 16 D nails, in each end of collar ties to connect collar tie to raftersThree nails each bay at TrussesNo vent pipes in the attic through the roofMissing light and receptacle in atticFix hole around drain line and sleeve at foundation wallAll footings for porches and decks need to be inspected | | | | | | |
| | 8/8/2025 | 8/8/2025 | ADDRESS | GIS Bucket | APPROVED | |
| Notes: 121 STEWRT FARM LN SPRING LAKE 28390. | | | | | | |
| | 8/8/2025 | 8/8/2025 | ROUGH IN | Deen Taylor | APPROVED | |
| Notes: | | | | | | |
| | 8/8/2025 | 8/8/2025 | FOUNDATION | Deen Taylor | APPROVED | |
| Notes: Please check blocking for ramp on side/front per inspector. Porch/ramp footings approved | | | | | | |
| 20 | | | ZONING | Planning Bucket | | Flood final Cert inspection |
| Notes: | | | | | | |
| 40 | | | MODULAR FINAL** | Steven Gazlay | | |
| Notes: | | | | | | |