

Peak Truss Builders, LLC

PO Box 340, New Hill, NC 27562

Comments and Clarifications

Job #:	Description:	Notes:
Q-2401843	Cotton	Roof Trusses This quote is based off of information
Customer:	Contact:	received on 7/30/24.
PHC Restoration		
Address:	Site Address:	
1601 E McNeill St Lillington NC 27546	300 Grameta Ln Lillington NC	
O: (910) 814.2502 Jeremy (910) 890.4039		
Truss Design Date:		
Installation Package. However, "syste 3. Overhang horizontal truss dimen 4. All perimeter dimensions on layout sheathing is beyond. 5. This quote is based off of information 6. Peak Truss has attempted to help of	equire proper bracing and blocking. Some ematic" or "whole house" bracing is the resision is 12". Sub-fascia and fascia are be reflect outside to outside of the stud. Wall on received on 7/30/24.	eyond. I studs are to line up with edge of slab, and elop a new truss design for this project. This
have Reviewed and Approved abo	ve Clarifications:	
Signed:	D	Oate: