

Harnett County 420 Mckinney Pkwy

LILLINGTON, NC 27546

Phone:

Fax:

11/21/2024

SUBJECT: **BRES2410-0059**

BUILDING RESIDENTIAL

To: Kevin A. Borge, T/A

Here are the results of all Inspections located at 11134 US 421 N:

Inspection Type: FINAL**

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: FOOTING

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: FOUNDATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: INSULATION

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:





Harnett County

420 Mckinney Pkwy

LILLINGTON,NC 27546

Phone: Fax:

Inspection Type: MONO SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: OPEN FLOOR

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: SLAB

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: UNDER SLAB TRADES

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:

Inspection Type: ROUGH IN REINSPECT

Scheduled Date/Time: Completed Date/Time:

Inspector: Steven Gazlay

Result: Remarks: Notes:



Harnett County

420 Mckinney Pkwy

LILLINGTON,NC 27546

Phone: Fax:

Inspection Type: T-POLE
Scheduled Date/Time: 11/8/2024
Completed Date/Time: 11/8/2024
Inspector: John B Kokoszka

Result: APPROVED

Remarks: Notes:

Inspection Type: ROUGH IN
Scheduled Date/Time: 11/20/2024
Completed Date/Time: 11/20/2024
Inspector: John B Kokoszka
Result: DISAPPROVED

Remarks:

Notes:

1. Throughout the house where the splice is from the new to the old or less than 24 inches

apart at the top plate, needs a 24 inch strap. All the nails filled.2. Did a cripple stud under splice at kitchen, small doorway right the back door3. Fire stop hole, bottom plate right of panel box at outlets4. Missing baffles and air barrier upstairs5. Need a fire start electrical line at stairs

outlet