
- *House footprint to be field staked by surveyor and system verified prior to any construction
- **Septic area must not be altered by construction activities.
- ***No cuts of 2' or greater within within 15' of septic area
- **** Recommend protective barrier around septic field during construction.


pump tank will be required to septic field

Duncan Creeks Lot 32 3 Bedroom Harnett County

N/F JOHNNY LYNWOOD HOLLAND D.B. 2433, PG. 915 PLAT CABINET F SLIDE 586-A



Adams Soil Consulting 919-414-6761 BEACON HILL ROAD 50' PUBLIC R/W




INITIAL: Lines 1-3 (300') Accepted Status Gravity Serial REPAIR: Lines 4-5 (225") PPBPS Pressure Manifold

- *House footprint to be field staked by surveyor and system verified prior to any construction
- **Septic area must not be altered by construction activities.
- ***No cuts of 2' or greater within within 15' of septic area
- **** Recommend protective barrier around septic field during construction.
 - *If plumbing is not sufficient a pump tank will be required to septic field

Duncan Creeks Lot 32 3 Bedroom Harnett County

N/F JOHNNY LYNWOOD HOLLAND D.B. 2433, PG. 915 PLAT CABINET F SLIDE 586-A



Adams Soil Consulting 919-414-6761





INITIAL: Lines 1-3 (300') Accepted Status Gravity Serial REPAIR: Lines 4-5 (225") PPBPS Pressure Manifold