

November 183<sup>th</sup>, 2025

Maria Escobar  
198 Sebastian Lane  
Cameron, NC 28326

Harnett County Government Complex  
307 W. Cornelius Harnett Boulevard  
Lillington, NC 27546

ph: 910-893-7550  
fax: 910-893-9429

**Re: Status of Permit Application-BRES2509-0073**

**To whom it may concern,**

An attempt was made to evaluate your property for issuing an Improvement Permit. The evaluation could not be completed for one or more of the following reasons.

- 1. Survey Corner Irons need to be uncovered and clearly demonstrated. Have surveyor flag/mark every 50' between property survey corner irons. (25.00 Fee Incurred)
- 2. House Box needs to be marked/demonstrated clearly. (25.00 Fee Incurred)
- 3. Directions not clear to property (*\$25.00 fee incurred*)
- 4. Needs more clearing. Do not disturb the soil. Need access points to do evaluations.
- 5. Driveway not shown on site plan
- 6. Backhoe Pits Required

**X 7. Other- Need existing septic tank and drain lines located.**

Your application will be put on hold until the selected items above have been addressed.  
**Please call 910-893-7525 to schedule** your property for evaluation.

Sincerely,



Mark Osborne, REHS  
Environmental Health Specialist  
MO/kh  
Copy: Central Permitting