TREFFRED 10/10/10; 14:03:33 THREECTION TICKET DATE 10/19/10 INSPECTOR: IVR Harnett County ADDRESS . : 8521 CHRISTIAN LIGHT RD SUBDIV: CONTRACTOR : PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE : PARCEL . .: 05-0645- - -0022- -05-APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL DIRECTIONS: T/S: 09/22/2010 08:33 AM VBROWN ----8521 CHRISTIAN LIGHT RD. 401N, LEFT ON CHRISTIAN LIGHT RD, GO 8MI YELLOW HOUSE IS ON THE LEFT. ______ STRUCTURE: 000 000 35X42 ADDIT ADD 1BDR TOTAL BDR 4 FLOOD ZONE . . . : FLOOD ZONE X SEPTIC - EXISTING? . . . : EXISTING # BEDROOMS : 1.00 WATER SUPPLY : COUNTY ______ PERMIT: CPBP 00 CP BUILDING PERMIT REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS ______

ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001994102

----- COMMENTS AND NOTES -----

H824 01 10/13/10 JM

PAGE 23 Harnett County INSPECTOR: IVR DATE 10/28/10 ______ ADDRESS . : 8521 CHRISTIAN LIGHT RD SUBDIV: CONTRACTOR: PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE : PARCEL . .: 05-0645- - -0022- -05-APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL DIRECTIONS : T/S: 09/22/2010 08:33 AM VBROWN ----8521 CHRISTIAN LIGHT RD. 401N, LEFT ON CHRISTIAN LIGHT RD, GO 8MI YELLOW HOUSE IS ON THE LEFT. STRUCTURE: 000 000 35X42 ADDIT ADD 1BDR TOTAL BDR 4 FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS : 1.00 SEPTIC - EXISTING? . . . : EXISTING WATER SUPPLY : COUNTY PERMIT: CPBP 00 CP BUILDING PERMIT REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS

TYP/SO H824 01 10/13/10 ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001994102 JM 10/13/10 AP T/S: 10/13/2010 10:34 AM SSTEWART -----T/S: 10/13/2010 10:34 AM SSTEWART -----10/19/10 BS R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001995711 10/19/10 AP T/S: 10/18/2010 10:29 AM VBROWN ------B101 01 T/S: October 19, 2010 08:38 AM BSUTTON -----B103 01 10/28/10 TI R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001999408 10:28-10 AEBS T/S: 10/27/2010 01:13 PM DJOHNSON -----CUSTOMER CALLED IN FOR AN OPEN FLOOR INSPECTION. SHE HAS NOT HAD A FOUNDATION INSPECTION. I TALKED TO BRAD AND HE SAID THEY WILL HAVE TO HAVE ALL PIERS AND INSIDE AND OUTSIDE WALL OPEN TO THE FOOTING FOR HIM TO SEE. THE CUSTOMER HAS NOT BACKFILLED ANYTHING YET. IF OPEN FLOOR IS DONE AT SAME TIME PLEASE HAVE A TECH SCHEDULE FOR YOU, BECAUSE I CANNOT SCHEDULE AN OPEN FLOOR UNTIL FOUNDATION APPROVED. THANKS

COMMENTS AND NOTES

PREPARED 10/29/10, 14:04:14 INSPECTION TICKET PAGE 18

Harnett County DATE 11/01/10 INSPECTOR: IVR

ADDRESS . : 8521 CHRISTIAN LIGHT RD SUBDIV: CONTRACTOR : PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE :

PARCEL . .: 05-0645- - -0022- -05-

APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL DIRECTIONS: T/S: 09/22/2010 08:33 AM VBROWN ----8521 CHRISTIAN LIGHT RD. 401N, LEFT ON CHRISTIAN LIGHT RD, GO 8MI YELLOW HOUSE

IS ON THE LEFT.

STRUCTURE: 000 000 35X42 ADDIT ADD 1BDR TOTAL BDR 4

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 1.00 SEPTIC - EXISTING? . . . : EXISTING

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT			
TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	10/13/10 10/13/10	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001994102 T/S: 10/13/2010 10:34 AM SSTEWART
B101 01	10/19/10 10/19/10	BS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001995711 T/S: 10/18/2010 10:29 AM VBROWN
B103 01	10/28/10 10/28/10	BS AE	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001999408 T/S: 10/27/2010 01:13 PM DJOHNSON
B105 02	10/28/10 10/28/10	BS DA	R*OPEN FLOOR TIME: 17:00 VRU #: 002000115 T/S: October 28, 2010 12:31 PM BSUTTON All joints in girders shall be supportted on a pier. You cannot splice girders midspan. Do not cover floor system. Correct and call for reinspection
B105 03	10/29/10 10/29/10	BS DP	R*OPEN FLOOR VRU #: 002000347 SPLICES FIXED All girders still have splice joints between piers. Splices are marked on side of girders (from access door) Do not cover \$50 reinspection fee
B105 01 B105 04	10/29/10 10/28/10 11/01/10	BS CA TI	R*OPEN FLOOR VRU #: 002000073 T/S: October 28, 2010 12:28 PM BSUTTON
PT02 04	#-1-10	4PB/	T/S: 10/29/2010 12:35 PM VBROWN

PERMIT: CPNP 00 CP MISC NOTIFICATION PERMIT

REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS TYP/SQ

----- CONTINUED ONTO NEXT PAGE ----------

PREPARED 10/29/10, 14:04:14 INSPECTION TICKET 19 PAGE Harnett County INSPECTOR: IVR DATE 11/01/10 ADDRESS . : 8521 CHRISTIAN LIGHT RD SUBDIV: CONTRACTOR: PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE : PARCEL . . : 05-0645- - -0022- -05-APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL INSP REQUESTED DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS ______ ENVIR. HLTH. CONFIRMATION VRU #: 001986435 H800 01 10/07/10 JM T/S: 10/04/2010 09:54 AM SZIMMER -----10/08/10 AP

T/S: 10/05/2010 10:51 AM SSTEWART -----T/S: 10/11/2010 08:36 AM SZIMMER -----

------ COMMENTS AND NOTES -----

 PREPARED 11/19/10, 13:59:39
 INSPECTION TICKET
 PAGE 27

 Harnett County
 INSPECTOR: IVR
 DATE 11/22/10

ADDRESS : 8521 CHRISTIAN LIGHT RD SUBDIV: CONTRACTOR : PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE :

PARCEL . . : 05-0645- - -0022- -05-

APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL DIRECTIONS: T/S: 09/22/2010 08:33 AM VBROWN ---- 8521 CHRISTIAN LIGHT RD. 401N, LEFT ON CHRISTIAN LIGHT RD, GO 8MI YELLOW HOUSE

IS ON THE LEFT.

STRUCTURE: 000 000 35X42 ADDIT ADD 1BDR TOTAL BDR 4

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 1.00 SEPTIC - EXISTING? : EXISTING

WATER SUPPLY : COUNTY

PERMIT. CRRD ON CR RITTLDING PERMIT

PERMIT: CPBP 00 CP BUILDING PERMIT				
TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS	
11F/5Q		RESULI	RESOLIS/ COMMENTS	
H824 01	10/13/10	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001994102	
	10/13/10	AP	T/S: 10/13/2010 10:34 AM SSTEWART	
			T/S: 10/13/2010 10:34 AM SSTEWART	
B101 01	10/19/10	BS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001995711	
	10/19/10	AP	T/S: 10/18/2010 10:29 AM VBROWN	
			T/S: October 19, 2010 08:38 AM BSUTTON	
B103 01	10/28/10	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001999408	
	10/28/10	AE	T/S: 10/27/2010 01:13 PM DJOHNSON	
			CUSTOMER CALLED IN FOR AN OPEN FLOOR INSPECTION. SHE HAS	
			NOT HAD A FOUNDATION INSPECTION. I TALKED TO BRAD AND HE	
			SAID THEY WILL HAVE TO HAVE ALL PIERS AND INSIDE AND	
			OUTSIDE WALL OPEN TO THE FOOTING FOR HIM TO SEE. THE CUSTOMER HAS NOT BACKFILLED ANYTHING YET. IF OPEN FLOOR IS	
			DONE AT SAME TIME PLEASE HAVE A TECH SCHEDULE FOR YOU,	
			BECAUSE I CANNOT SCHEDULE AN OPEN FLOOR UNTIL FOUNDATION	
			APPROVED. THANKS	
			Clean footing (exterior) and install damproofing from	
			footing up to final grade height. Will check at next	
			inspection (rough ins)	
B105 02	10/28/10	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002000115	
	10/28/10	DA	T/S: October 28, 2010 12:31 PM BSUTTON	
			All joints in girders shall be supportted on a pier. You	
			cannot splice girders midspan. Do not cover floor system.	
			Correct and call for reinspection	
B105 03	10/29/10	BS	R*OPEN FLOOR VRU #: 002000347	
	10/29/10	DP	SPLICES FIXED	
			All girders still have splice joints between piers. Splices	
			are marked on side of girders (from access door) Do not cover \$50 reinspection fee	
B105 01	10/29/10	BS	R*OPEN FLOOR VRU #: 002000073	
P102 01	10/28/10	CA	T/S: October 28, 2010 12:28 PM BSUTTON	
B105 04	11/01/10	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002000693	
2103 04	11/01/10	AP	T/S: 10/29/2010 12:35 PM VBROWN	
	,,		T/S: November 01, 2010 10:10 AM BSUTTON	
R425 01	11/22/10	TI -	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002008712	
	11.22-10	NAKS	T/S: 11/19/2010 07:56 AM NTART	

------ COMMENTS AND NOTES ------

PREPARED 11/23/10, 14:02:33 Harnett County

INSPECTION TICKET INSPECTOR: IVR

PAGE

DATE 11/24/10

ADDRESS . : 8521 CHRISTIAN LIGHT RD

SUBDIV: PHONE :

PHONE :

CONTRACTOR :

OWNER . . : PEARSON MICHAEL BRADLEY &

PARCEL . .: 05-0645- - -0022- -05-APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL

DIRECTIONS: T/S: 09/22/2010 08:33 AM VBROWN ----8521 CHRISTIAN LIGHT RD. 401N, LEFT ON

CHRISTIAN LIGHT RD, GO 8MI YELLOW HOUSE

IS ON THE LEFT.

STRUCTURE: 000 000 35X42 ADDIT ADD 1BDR TOTAL BDR 4

FLOOD ZONE . . . : FLOOD ZONE X

SEPTIC - EXISTING? . . . : EXISTING 1.00 # BEDROOMS :

WATER SUPPLY : COUNTY

TYP/SO	CPBP 00 CP BU REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
H824 01	10/13/10 10/13/10	JМ AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001994102 T/S: 10/13/2010 10:34 AM SSTEWART
B101 01	10/19/10 10/19/10	BS AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001995711 T/S: 10/18/2010 10:29 AM VBROWN T/S: October 19, 2010 08:38 AM BSUTTON R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001999408 T/S: 10/27 10 01:13 PM DJOHNSON CUSTOMER CELED IN FOR AN OPEN FLOOR INSPECTION. SHE HAS NOT HAD A FOUNDATION INSPECTION. I TALKED TO BRAD AND HE SAID THEY WILL HAVE TO HAVE ALL PIERS AND INSIDE AND OUTSIDE WALL OPEN TO THE FOOTING FOR HIM TO SEE. THE CUSTOMER HAS NOT BACKFILLED ANYTHING YET. IF OPEN FLOOR IS DONE AT SAME TIME PLEASE HAVE A TECH SCHEDULE FOR YOU, BECAUSE I CANNOT SCHEDULE AN OPEN FLOOR UNTIL FOUNDATION APPROVED. THANKS
B103 01	10/28/10 10/28/10	BS AE	
B105 02	10/28/10 10/28/10	BS DA	Clean footing (exterior) and install damproofing from footing up to final grade height. Will check at next inspection (rough ins) R*OPEN FLOOR TIME: 17:00 VRU #: 002000115 T/S: October 28, 2010 12:31 PM BSUTTON
B105 03	10/29/10 10/29/10	BS DP	Correct and call for reinspection R*OPEN FLOOR VRU #: 002000347 SPLICES FIXED All girders still have splice joints between piers. Splices are marked on side of girders (from access door) Do not cover \$50 reinspection fee
B105 01	10/29/10 10/28/10	BS CA	R*OPEN FLOOR VRU #: 002000073 T/S: October 28, 2010 12:28 PM BSUTTON
B105 04	11/01/10 11/01/10	BS AP	R*OPEN FLOOR TIME: 17:00 VRU #: 002000693 T/S: 10/29/2010 12:35 PM VBROWN T/S: November 01, 2010 10:10 AM BSUTTON
R425 01	11/22/10 11/22/10	DA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002008712 T/S: 11/19/2010 07:56 AM NTART 1. Support all joints in top plate with studs. 2. Shim jack

INSPECTION TICKET PAGE PREPARED 11/23/10, 14:02:33 DATE 11/24/10 INSPECTOR: IVR Harnett County ______ ADDRESS . : 8521 CHRISTIAN LIGHT RD SUBDIV: CONTRACTOR : PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE : PARCEL . .: 05-0645- - -0022- -05-APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL ______ INSP DESCRIPTION REQUESTED TYP/SQ COMPLETED RESULT RESULTS/COMMENTS _____ studs at headers where there are gaps. 3. Ceiling joists over closet must be full 2x6 (nominal). OK TO SIDE/INSULATE R425 02 11/24/10 TI FOUR TRADE ROUGH IN VRU #: 002011278 11-2410 AP-MR PERMIT: CPIR 00 CP INSULATION RESIDENTIAL REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

R*INSULATION INSPECTION VRU #: 002011252

------ COMMENTS AND NOTES ------

I129 01 11/24/10 TI

1124/10 DA-MR

HARNETT COUNTY

Building Inspections Dept. 108 E. Front St. Lillington, NC 27546 910-893-7525

DATE: 11-24-10

PERMIT # 10-50025249

ADDRESS: 8521 Christian light

CORRECTIONS NEEDED:

1. Install insulation per code.

2. R -30 is allowed when it extends un-compressed over the top plate. If this installation cuts off the required air space, then baffles will have to be added.

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

PREPARED 11/24/10, 14:28:22 INSPECTION TICKET PAGE 1 DATE 11/29/10 Harnett County INSPECTOR: IVR ADDRESS . : 8521 CHRISTIAN LIGHT RD SUBDIV. CONTRACTOR: PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE : PARCEL . .: 05-0645- - -0022- -05-APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL _______ DIRECTIONS: T/S: 09/22/2010 08:33 AM VBROWN ----8521 CHRISTIAN LIGHT RD. 401N, LEFT ON CHRISTIAN LIGHT RD, GO 8MI YELLOW HOUSE IS ON THE LEFT. STRUCTURE: 000 000 35X42 ADDIT ADD 1BDR TOTAL BDR 4 FLOOD ZONE . . . : FLOOD ZONE X # BEDROOMS : SEPTIC - EXISTING? . . . : EXISTING 1.00 WATER SUPPLY : COUNTY

------ COMMENTS AND NOTES -----

PAGE 29 INSPECTION TICKET PREPARED 12/21/10, 14:00:24 Harnett County DATE 12/22/10 INSPECTOR: IVR

ADDRESS . : 8521 CHRISTIAN LIGHT RD SUBDIV: CONTRACTOR : PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE :

PARCEL . .: 05-0645- - -0022- -05-

APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL DIRECTIONS: T/S: 09/22/2010 08:33 AM VBROWN ----8521 CHRISTIAN LIGHT RD. 401N, LEFT ON CHRISTIAN LIGHT RD, GO 8MI YELLOW HOUSE

IS ON THE LEFT.

STRUCTURE: 000 000 35X42 ADDIT ADD 1BDR TOTAL BDR 4

FLOOD ZONE . . . : FLOOD ZONE X

1.00 SEPTIC - EXISTING? . . . : EXISTING # BEDROOMS :

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT			
PERMIT:	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED		RESULTS/COMMENTS
H824 01	10/13/10	. ЈМ	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001994102
11024 01	10/13/10	AP	T/S: 10/13/2010 10:34 AM SSTEWART
	10/13/10	***	T/S: 10/13/2010 10:34 AM SSTEWART
B101 01	10/19/10	BS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001995711
	10/19/10	AP	T/S: 10/18/2010 10:29 AM VBROWN
	• •		T/S: October 19, 2010 08:38 AM BSUTTON
B103 01	10/28/10	BS	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 001999408
	10/28/10	AE	T/S: 10/27/2010 01:13 PM DJOHNSON
			CUSTOMER CALLED IN FOR AN OPEN FLOOR INSPECTION. SHE HAS
			NOT HAD A FOUNDATION INSPECTION. I TALKED TO BRAD AND HE
			SAID THEY WILL HAVE TO HAVE ALL PIERS AND INSIDE AND
			OUTSIDE WALL OPEN TO THE FOOTING FOR HIM TO SEE. THE
			CUSTOMER HAS NOT BACKFILLED ANYTHING YET. IF OPEN FLOOR IS
			DONE AT SAME TIME PLEASE HAVE A TECH SCHEDULE FOR YOU,
			BECAUSE I CANNOT SCHEDULE AN OPEN FLOOR UNTIL FOUNDATION
			APPROVED. THANKS
			Clean footing (exterior) and install damproofing from
			footing up to final grade height. Will check at next
	/ /	5.0	inspection (rough ins) R*OPEN FLOOR TIME: 17:00 VRU #: 002000115
B105 02	10/28/10	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002000115 T/S: October 28, 2010 12:31 PM BSUTTON
	10/28/10	DA	All joints in girders shall be supported on a pier. You
			cannot splice girders midspan. Do not cover floor system.
			Correct and call for reinspection
B105 03	10/29/10	BS	R*OPEN FLOOR VRU #: 002000347
B103 03	10/29/10	DP	SPLICES FIXED
	10/23/10	21	All girders still have splice joints between piers. Splices
			are marked on side of girders (from access door) Do not
			cover \$50 reinspection fee
B105 01	10/29/10	BS	R*OPEN FLOOR
	10/28/10	CA	T/S: October 28, 2010 12:28 PM BSUTTON
B105 04	11/01/10	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002000693
	11/01/10	AP	T/S: 10/29/2010 12:35 PM VBROWN
			T/S: November 01, 2010 10:10 AM BSUTTON
R425 01	11/22/10	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002008712
	11/22/10	DA	T/S: 11/19/2010 07:56 AM NTART
			1. Support all joints in top plate with studs. 2. Shim jack

------ CONTINUED ONTO NEXT PAGE ------

INSPECTION TICKET 30 PREPARED 12/21/10, 14:00:24 PAGE Harnett County DATE 12/22/10 INSPECTOR: IVR ADDRESS . : 8521 CHRISTIAN LIGHT RD SUBDIV: CONTRACTOR : PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE : PARCEL . .: 05-0645- - -0022- -05-APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL _______ REQUESTED INSP DESCRIPTION TYP/SQ COMPLETED RESULT RESULTS/COMMENTS studs at headers where there are gaps. 3. Ceiling joists over closet must be full 2x6 (nominal). OK TO SIDE/INSULATE R425 02 11/24/10 MR FOUR TRADE ROUGH IN VRU #: 002011278 11/24/10 AP / 7.2. 11/24/2010 02:18 PM MREARIC -THREE TRADE FINAL VRU #: 002022226 T/S: 11/24/2010 02:18 PM MREARIC -----TI/

------ COMMENTS AND NOTES -----

R329 01 12/22/10

11

PREPARED 1/04/11, 14:09:00 INSPECTION TICKET PAGE 20
Harnett County INSPECTOR: IVR DATE 1/05/11

Harnett County INSPECTOR: IVR DATE 1/05/11

ADDRESS .. : 8521 CHRISTIAN LIGHT RD SUBDIV: CONTRACTOR : PHONE : OWNER . . : PEARSON MICHAEL BRADLEY & PHONE :

PARCEL . .: 05-0645- - -0022- -05-

APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL DIRECTIONS: T/S: 09/22/2010 08:33 AM VBROWN ---- 8521 CHRISTIAN LIGHT RD. 401N, LEFT ON CHRISTIAN LIGHT RD, GO 8MI YELLOW HOUSE

IS ON THE LEFT.

STRUCTURE: 000 000 35X42 ADDIT ADD 1BDR TOTAL BDR 4

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : 1.00 SEPTIC - EXISTING? : EXISTING

WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT			
	REQUESTED	INSP	DESCRIPTION
TYP/SQ	COMPLETED		RESULTS/COMMENTS
H824 01	10/13/10	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001994102
	10/13/10	AP	T/S: 10/13/2010 10:34 AM SSTEWART
B101 01	10/19/10	BS	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 001995711
	10/19/10	AP	T/S: 10/18/2010 10:29 AM VBROWN
	/ /		T/S: October 19, 2010 08:38 AM BSUTTON
B103 01	10/28/10	BS	
	10/28/10	AE	T/S: 10/27/2010 01:13 PM DJOHNSON
B105 02	10/28/10	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002000115
	10/28/10	DA	T/S: October 28, 2010 12:31 PM BSUTTON
B105 03	10/29/10	BS	R*OPEN FLOOR VRU #: 002000347
	10/29/10	DP	SPLICES FIXED All girders still have splice joints between piers. Splices are marked on side of girders (from access door) Do not cover \$50 reinspection fee
B105 01	10/29/10	BS	R*OPEN FLOOR VRU #: 002000073
	10/28/10	CA	T/S: October 28, 2010 12:28 PM BSUTTON
B105 04	11/01/10	BS	R*OPEN FLOOR TIME: 17:00 VRU #: 002000693
	11/01/10	AP	T/S: 10/29/2010 12:35 PM VBROWNT/S: November 01, 2010 10:10 AM BSUTTON
D40E 01	11/20/10	DC	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002008712
R425 01	11/22/10 11/22/10	BS DA	T/S: 11/19/2010 07:56 AM NTART 1. Support all joints in top plate with studs. 2. Shim jack
i			

------ CONTINUED ONTO NEXT PAGE ------

PREPARED 1/04/11, 14:09:00 Harnett County

1/05/11

INSPECTION TICKET INSPECTOR: IVR

PAGE DATE

1/05/11

ADDRESS . : 8521 CHRISTIAN LIGHT RD

SUBDIV: PHONE :

CONTRACTOR :

PHONE :

R329 02

OWNER . . : PEARSON MICHAEL BRADLEY & PARCEL . .: 05-0645- - -0022- -05-

APPL NUMBER: 10-50025249 CP ADD & ALTER RESIDENTIAL

DESCRIPTION INSP REQUESTED RESULTS/COMMENTS TYP/SQ COMPLETED RESULT -----studs at headers where there are gaps. 3. Ceiling joists over closet must be full 2x6 (nominal). OK TO SIDE/INSULATE FOUR TRADE ROUGH IN VRU #: 002011278

T/S: 11/24/2010 02:18 PM MREARIC ----
THREE TRADE FINAL VRU #: 002022226

Rake crawlspace level, must have 6 mil plastic vapor barrier in crawl space. 100% cover, lap joints 12 inches R425 02 11/24/10 MR 11/24/10 AP BS R329 01 12/22/10 12/22/10 THREE TRADE FINAL VRU #: 002025112

------ COMMENTS AND NOTES ------

