Bui	COUNTY OF HA Iding Inspections Planning Serv	Department
Certificate of Cor Certificate issued pursuant to the requirer This certifies at the time of issuance, this North Carolina State Building Codes. For	npliance: nents of North Carolina General S structure was in compliance with	Occupancy: X tatute 153A-363 and Harnett County Zoning Ordinances the various ordinances of the County of Harnett and the
Use Classification: Finish farm o		Permit Numbers
Name: James P & Kelly Moore		Building: 16-50037872
Address: 461 Cedar Rock Trail		Electrical:
Fuquay Varina NC 27526		Mechanical
Date: 03/01/2017	Dellaine Official	Brad Sutton

PAGE DATE 3/01/17

OWNER . . : MOORE JAMES P & KELLY #9 PARCEL . . : 05-0633- - -0112--11-APPL NUMBER: 16-50037872 CP ADD & ALTER RESIDENTIAL

DIRECTIONS: T/S: 01/20/2016 12:29 PM DJOHNSON --

CEDAR ROCK TRAIL LOT 9

401 N ABOUT 3.6 MILES THEN LEFT ONTO CHRISTIAN LIGHT RD. GO 4.3 MILES AND THEN LEFT ONTO COKESBURY RD DRIVE 1/2 MILE AND TURN LEFT ONTO CEDAR ROCK TRL GRAVEL DRIVE AT THE END OF CUL DE SAC.

STRUCTURE: 000 000 TURN UPSTAIRS OF FARM BLDG OFFICE W/BATH

FLOOD ZONE . . . : FLOOD ZONE X

BEDROOMS : .00 SEPTIC - EXISTING? . . . : EXISTING

WATER SUPPLY : COUNTY

TYP/SQ	REQUESTED COMPLETED		DESCRIPTION RESULTS/COMMENTS
R425 01	3/08/16	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002785632
3/08/16 D	DA	T/S: 03/04/2016 04:41 PM DJOHNSON	
		T/S: March 08, 2016 09:45 AM BSUTTON	
		1. All kneewalls adjoining attic space must be covered with	
		an air barrier on the attic side, as well as behind the	
		shower. Insulation baffles must be installed in cathedral	
		portions of the ceiling as well. This must be in for the	
			rough in inspections. Reschedule four trade rough ins once
R425 02	3/11/16	BS	these items are completed. Call me with any questions.
R425 02	3/11/16	CA	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002787455
	3/11/10	CA	T/S: 03/10/2016 08:21 AM DJOHNSON
R425 03	3/21/16	KS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 002791143
	3/21/16	AP	T/S: 03/21/2016 11:09 AM KSLATTUM
R429 01	2/07/17	BS	FOUR TRADE FINAL TIME: 17:00 VRU #: 002929727
	2/07/17	DA	T/S: 02/06/2017 09:09 AM JBROCK
			T/S: February 07, 2017 10:04 AM BSUTTON
			Foam seal attic access door. 2. Need GFCI at laundry 3.
			Insulate water lines at water heater back to inside wall.
			4. Caulk toilet at floor.
R429 02	3/01/17	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 002938959
	3-177	4435	T/S: 02/27/2017 04:28 PM BPETRICH

----- COMMENTS AND NOTES -----

0110.028x-20110