

-----  
ADDRESS . . : 1941 OVERHILLS RD SUBDIV:  
CONTRACTOR : HART CONSTRUCTION/REMODELING PHONE : (919) 935-2603  
OWNER . . . : PRICE JAMES D & P PHONE : (910) 893-3058  
PARCEL . . . : 01-0525- - -0046- - -  
APPL NUMBER: 16-50040387 CP ADD & ALTER RESIDENTIAL  
DIRECTIONS : T/S: 12/15/2016 08:56 AM LBENNETT --  
TAKE 210 S TURN LEFT ONTO OVERHILLS RD  
- 1941 ON THE RIGHT  
-----

**STRUCTURE: 000 000 ROOF TO EXIST PORCH & 12X24 BACK DECK COV**

FLOOD ZONE . . . . : FLOOD ZONE X  
# BEDROOMS . . . . . : 3.00 SEPTIC - EXISTING? . . . . : EXIST  
WATER SUPPLY . . . . . : COUNTY  
-----

**PERMIT: CPBP 00 CP BUILDING PERMIT**

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	1/05/17 1/05/17	JH AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002916732 T/S: 01/04/2017 11:07 AM DJOHNSON ----- WOULD LIKE AN AM INSPECTION IF POSSIBLE
B101 02	1/18/17 1/18/17	MR AP	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002920627 T/S: 01/13/2017 04:08 PM JBROCK ----- footing on the front deck per customer, they said jimmy would know about this one T/S: 01/18/2017 03:12 PM MREARIC -----
R125 01	1/19/17 1/19/17	JH DA	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002921609 T/S: 01/18/2017 10:12 AM DJOHNSON ----- PLEASE MAKE SURE FOOTING PASSED BEFORE THIS ROUGH IN CAN BE DONE. 1)Replace short nails in hangers with correct size nails.2)Need stud under back side of ridge beam.
R125 02	1/20/17 1/20/17	JH AP	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002922706 T/S: 01/19/2017 02:10 PM DJOHNSON -----
R131 01	1/25/17 <i>1-25-17</i>	TI <i>APJV</i>	ONE TRADE FINAL TIME: 17:00 VRU #: 002923936 T/S: 01/24/2017 11:50 AM DJOHNSON -----

----- COMMENTS AND NOTES -----