

County of Harnett
Building Inspections Department
Planning Services

Certificate of Compliance: _____ Occupancy: ☒

Certificate issued pursuant to the requirements of North Carolina General Statute 153A-363 and Harnett County Zoning Ordinances. This certifies at the time of issuance, this structure was in compliance with the various ordinances of the County of Harnett and the North Carolina State Building Codes. For the following:

Use Classification: Utility

Permit Numbers

Name: Manuel S. 105

Building: 12-500 28494

Electrical: 12-500 28494

Address: 14199 AC 210 S

Insulation: _____

Plumbing: _____

Mechanical: _____

MFG Home: _____

Date: 5-24-12

Building Official: James J. Hall

PREPARED 5/23/12, 14:11:24
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 1
DATE 5/24/12

ADDRESS : 14199 NC 210 S
CONTRACTOR : HAYES INC
OWNER : ENOS MANUEL & NELLIE RUTH
PARCEL : 01-0513- - -0138- - -
APPL NUMBER: 12-50028494 CP GARAGE/CARPORT RESIDENTIAL DETACHED

SUBDIV: HARNETT LAKES
PHONE : (910) 323-9112
PHONE : (910) 497-2467

DIRECTIONS : T/S: 03/02/2012 02:13 PM JBROCK ----
STRAIGHT DOWN HWY 210 TOWARDS SPRING
LAKE AT COUNTY LINE FOR HARNETT AND
CUMBERLAND COUNTIES

STRUCTURE: 000 000 26X32 GARAGE

FLOOD ZONE : FLOOD ZONE X

PROPOSED USE : GARAGE

WATER SUPPLY : COUNTY

SEPTIC - EXISTING? : EXT

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/23/12	MR	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002206308
	3/23/12	AP	T/S: 03/21/2012 03:05 PM VBROWN ----- T/S: 03/23/2012 12:55 PM MREARIC -----
B103 01	3/28/12	DT	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002207959
	3/28/12	DA	ENG. REPAIR LETTER NEEDED
B103 02	4/05/12	JH	R*BLDG FOUND & TEMP SVC POLE TIME: 17:00 VRU #: 002212256
	4/05/12	AP	AM INSPECITON per eng letter
B111 01	4/09/12	JH	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002212710
	4/09/12	AP	
R225 01	4/23/12	JH	TWO TRADE ROUGH IN TIME: 17:00 VRU #: 002218220
	4/23/12	DA	1)Shingles need to be on @ roughin.2)Add stud under break in top plate on right side of garage.3)Missing nail guards on all plumbing @ top & bottom plates.4)Fire caulk 2" pipe @ top plate.5)Missing roof boots.6)Nail 2 ply lvls over garage doors every 12" per manufactures instructions.7)Need truss repair letter for cut gable truss @ windows.8)Post for porch need to be installed.
B101 02	4/26/12	JH	R*BLDG FOOTING / TEMP SVC POLE TIME: 17:00 VRU #: 002219434
	4/26/12	AP	FOOTING FOR PORCH
R325 01	5/04/12	JH	THREE TRADE ROUGH IN TIME: 17:00 VRU #: 002223386
	5/04/12	AP	
R329 01	5/24/12	TI	THREE TRADE FINAL TIME: 17:00 VRU #: 002231181

5-24-12 AP JV

COMMENTS AND NOTES