
 ADDRESS . : 1296 YOUNG RD SUBDIV: THE H P YOUNG LANDS
 CONTRACTOR : PHONE :
 OWNER . . : FRAME HARLEY G & RUTH J PHONE :
 PARCEL . . : 07-0692- - -0085- - -
 APPL NUMBER: 12-50029398 CP GARAGE/CARPORT RESIDENTIAL DETACHED
 DIRECTIONS : T/S: 07/17/2012 11:10 AM VBROWN ----
 1296 YOUNG RD ANGIER 27501.
 T/S: 08/17/2012 11:47 AM JBROCK ----
 REF #0850019942 - POOL
 POOL NEEDS TO BE CO'ED AT THE SAME TIME
 AS THE GARAGE

STRUCTURE: 000 000 28X54 DET GARAGE STORAGE

FLOOD ZONE : FLOOD ZONE X
 PROPOSED USE : DET GAR SEPTIC - EXISTING? : EXISTING
 WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B111 01	8/22/12 8/23/12	DT AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002268894 T/S: 08/21/2012 11:34 AM VBROWN ----- CUSTOMER REQUEST PM INSP INCASE OF RAIN HE CAN CLEAN IT OUT FOR YOU.
R125 01	9/11/12 9/11/12	BS AE	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002276905 SHEATHING INSPECTION - CUSTOEMR PAID T/S: 09/10/2012 01:07 PM JBROCK ----- T/S: September 11, 2012 11:50 AM BSUTTON ----- OSB must maintain 6 inches clearance to grade. At front apron, remove OSB, and replace with 1/2 inch treated plywood. We can verify this correction at rough ins. OK to install siding
H824 01	10/10/12 10/10/12	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002290203 T/S: 10/11/2012 10:52 AM SSTEWARD ----- T/S: 10/11/2012 10:53 AM SSTEWARD -----
R425 01	2/07/13 2/07/13	BS CA	FOUR TRADE ROUGH IN VRU #: 002336136 T/S: February 07, 2013 01:15 PM BSUTTON ----- per hoomeowner
R425 02	4/04/13 4/04/13	KS AP	FOUR TRADE ROUGH IN VRU #: 002360741 T/S: 04/04/2013 11:49 AM KSLATTUM -----
I129 01	4/18/13	TI	R*INSULATION INSPECTION VRU #: 002368690

4-18-13 APB

----- COMMENTS AND NOTES -----

ADDRESS : 1296 YOUNG RD SUBDIV: THE H P YOUNG LANDS
CONTRACTOR : PHONE :
OWNER : FRAME HARLEY G & RUTH J PHONE :
PARCEL : 07-0692- - -0085- - -
APPL NUMBER: 12-50029398 CP GARAGE/CARPORT RESIDENTIAL DETACHED
DIRECTIONS : T/S: 07/17/2012 11:10 AM VBROWN ----
1296 YOUNG RD ANGIER 27501.
T/S: 08/17/2012 11:47 AM JBROCK ----
REF #0850019942 - POOL
POOL NEEDS TO BE CO'ED AT THE SAME TIME
AS THE GARAGE

STRUCTURE: 000 000 28X54 DET GARAGE STORAGE

FLOOD ZONE : FLOOD ZONE X
PROPOSED USE : DET GAR SEPTIC - EXISTING? : EXISTING
WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B111 01	8/22/12 8/23/12	DT AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002268894 T/S: 08/21/2012 11:34 AM VBROWN ----- CUSTOMER REQUEST PM INSP INCASE OF RAIN HE CAN CLEAN IT OUT FOR YOU.
R125 01	9/11/12 9/11/12	BS AE	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002276905 SHEATHING INSPECTION - CUSTOEMR PAID T/S: 09/10/2012 01:07 PM JBROCK ----- T/S: September 11, 2012 11:50 AM BSUTTON ----- OSB must maintain 6 inches clearance to grade. At front apron, remove OSB, and replace with 1/2 inch treated plywood. We can verify this correction at rough ins. OK to install siding
H824 01	10/10/12 10/10/12	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002290203 T/S: 10/11/2012 10:52 AM SSTEWARD ----- T/S: 10/11/2012 10:53 AM SSTEWARD -----
R425 01	2/07/13 2/07/13	BS CA	FOUR TRADE ROUGH IN VRU #: 002336136 T/S: February 07, 2013 01:15 PM BSUTTON ----- per hoomeowner
R425 02	4/04/13 <u>4-4</u>	TI <u>AP</u>	FOUR TRADE ROUGH IN VRU #: 002360741

COMMENTS AND NOTES

Need Baffle

ADDRESS . . : 1296 YOUNG RD SUBDIV: THE H P YOUNG LANDS
 CONTRACTOR : PHONE :
 OWNER . . : FRAME HARLEY G & RUTH J PHONE :
 PARCEL . . : 07-0692- - -0085- - -
 APPL NUMBER: 12-50029398 CP GARAGE/CARPORT RESIDENTIAL DETACHED
 DIRECTIONS : T/S: 07/17/2012 11:10 AM VBROWN ----
 1296 YOUNG RD ANGIER 27501.
 T/S: 08/17/2012 11:47 AM JBROCK ----
 REF #0850019942 - POOL
 POOL NEEDS TO BE CO'ED AT THE SAME TIME
 AS THE GARAGE

STRUCTURE: 000 000 28X54 DET GARAGE STORAGE

FLOOD ZONE : FLOOD ZONE X
 PROPOSED USE : DET GAR SEPTIC - EXISTING? : EXISTING
 WATER SUPPLY : COUNTY

PERMIT: CPBP 00 CP BUILDING PERMIT

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B111 01	8/22/12 8/23/12	DT AP	R*BLDG SLAB INSP/TEMP SVC POLE TIME: 17:00 VRU #: 002268894 T/S: 08/21/2012 11:34 AM VBROWN ----- CUSTOMER REQUEST PM INSP INCASE OF RAIN HE CAN CLEAN IT OUT FOR YOU.
R125 01	9/11/12 9/11/12	BS AE	ONE TRADE ROUGH IN TIME: 17:00 VRU #: 002276905 SHEATHING INSPECTION - CUSTOEMR PAID T/S: 09/10/2012 01:07 PM JBROCK ----- T/S: September 11, 2012 11:50 AM BSUTTON ----- OSB must maintain 6 inches clearance to grade. At front apron, remove OSB, and replace with 1/2 inch treated plywood. We can verify this correction at rough ins. OK to install siding
H824 01	10/10/12 10/10/12	JM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002290203 T/S: 10/11/2012 10:52 AM SSTEWARD ----- T/S: 10/11/2012 10:53 AM SSTEWARD -----
R425 01	2/07/13	TI	FOUR TRADE ROUGH IN VRU #: 002336136

----- COMMENTS AND NOTES -----