


APPLICANT NAME _____

FACTORS		PROFILES								
		1	2	3	4	5	6	7	8	9
LANDSCAPE POSITION	.1940									
SLOPE (%)	.1940									
HORIZON 1 DEPTH		0-39	0-24	0-38	0-38	0-38	0-32	0-22		
Texture Group	.1941(A)(1)	cl/s	cl/s	cl/s	cl/s	cl/s	cl/s	cl/s	"	
Consistence	.1941								"	
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 2 DEPTH		24-42	24-36				32-36	22-36		
Texture Group	.1941(A)(1)	sl	sl				sl	sl		
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 3 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
HORIZON 4 DEPTH										
Texture Group	.1941(A)(1)									
Consistence	.1941									
Structure	.1941(A)(2)									
Mineralogy	.1941(A)(3)									
SOIL WETNESS	.1942	—	—	—	—	—	—	—	—	—
RESTRICTIVE HORIZON	.1944									
SAPROLITE	.1943/1956									
CLASSIFICATION	.1948	ps	ps	is	ps	s	ps			
LONG TERM										
ACCEPTANCE RATE	.1955	.4	.5	.8	.8	.8	.6	.6		



System laid out
3x100' lines
18'-24" (top 2 lines)
18" deep (bottom line)

Repair 50'
below initial
system below
next burm.

remove trees - no soil