SOIL EVALUATION REPORT

Date: 5/18/02

Developer: Mr. Larry K. Allen

Location: Murchisontown Rd. Harnett County Project: Major subdivision of the Morley Farm

SOIL EVALUATION

Developer Mr. Larry K. Allen proposes to subdivide a section of the Marley Farm into nine lots. Site evaluations were conducted on lot numbers 7,8,9,10,11,12,13,14,and 15 for the purpose of determining the soil suitability for subsurface sewage disposal. The proposed lots are located off Murchisontown Road and will be served by Harnett County Public Water.

An area of suitable to provisionally suitable soil was located on each lot that should support the installation and repair of a conventional to an "At-Grade" fill septic system for a three-bedroom home. Soil depths ranged from 24" to 36" of sandy loam to sandy clay loam. The LTAR should range between .5g/ft. to .7g/ft.

Soil profiles have been identified on site by pink and blue ribbons with soil depths recorded on them. The developer has been issued a plat indicating the general areas of potentially useable soil.

These determinations were made in accordance with 15A NCAC .1900 Laws and Rules for Sewage Treatment and Disposal. Due to variations in citing specific uses, and potential for changes in regulations or soil conditions, issuance of an Improvement Permit by the Harnett County Health Department is not guaranteed.

Report submitted by: ECS/Environmental Consulting Service

James Shackleton

Licensed Soil Scientist
Jerry Yarborough



Date: 12/03/02

Developer: Mr. Larry Allen

Project: Lot 16 Morley Farm Subdivision

Harnett County

Sewage disposal system design for a three- bedroom modular home.

A small area approximately 70' X 50' of provisionally suitable soil was located along the front of the lot adjacent to Ponderosa Rd. Soil depths ranged from 30" to 36" of sandy loam to sandy clay loam soil. This area should support the initial sewage disposal system for a three bed-room house. A shallow placed chamber tech graveless system with maximum trench depth of 18" is recommended for this site. With a flow rate of 360g/d and an LTAR of .5 g/ft? four lines of seven panels each should fit within this area. An interceptor drain may be needed on the up-slope side of the lot to control lateral water movement All ditches along the road and along the bottom side of lot should be cleaned out and properly maintained to control drainage conditions.


An area of provisionally suitable soil was located on the backside of the lot that should contain sufficient area for the installation and repair of a shallow placed conventional septic system for a three bedroom home. Soil depths ranged from 30" to 36" of sandy loam to sandy clay loam soil. A pump system would be needed to utilize this area at the present home location.

Report submitted by: Jame Shoulecton

James Shackleton

ECS/Environmental Consulting Services

SCALE 1" = 100'



SITE PLAN FOR:
LOT 16, MORLEY FARM SUBDIVISION
JOHNSONVILLE TWP. - HARNETT CO. - N.C.

MAP PREPARED BY: LARRY K. ALLEN, P.L.S. 2454 4469 PONDEROSA ROAD SANFORD, N.C. 27332 (919)721-0312

OCTOBER 29TH, 2002



HOMES Dr VANDERBUILT 3300 Jefferson Davis Highway Sanford, NC 27330 (919) 774-6319

FAX COVER SHEET

DATE: 4/21/03	<u>sia si</u> kir	TIME:	
TO: JOE WE	557	FAX NO:	893 - 9371
COMPANY: HAI	ENETT CO.		
FROM: LARRY	ALLEN		
	'4-6319 OR 800-537-2448		
FAX NO.: SALES OFF	, v	612	
	ATION OFFICE: 919-775-34	· · · ·	
NUMBER OF PAGES SENT (Inc	cluding Cover Sheet):	3	
DESCRIPTION:	E: OLIVIA L	OT	
	S THE LAYOU		
	ME IN DEC		
,	ID WE COUL		
	WINDER PAN		The second secon
/	NITH 4 -		
		,	ASSISTANCE
	F YOU NEED		REALLY NEE
	EED WITH T		
· ·			PATIENCE S'
AS5157	ANCE ON	THIS PROV	ECT.
	LARRY ALLE	٠	