

COMMENTS:

2/15/2011

BM Spoke with Beth Hing about app. 11-5-26036. Explained to her that we could not pass the existing system due to the pool & concret being on top of the drainfield. Suggested that they hire a private soils consultant to look at a possible repair.

BM 2/22/2011 Spoke with Neil Floyd, Soil Scientist, he will forward me info & report to Enr. HIK when finished.

BM 3/3/2011 Spoke with Ivey Johnson about removing the pool, concret pad, plumbing coming out of building, & the barrel in the ground.