

5/10/05

- OT OBSERVED MOORES STORAGE BUILDING ARRIVE WITH AN OUTBUILDING TO BE PLACED ON LOT. INFORMED HOME OWNER AND DELIVERY PERSON THAT PULLING STORAGE BUILDING TO DESIRED LOCATION WOULD INVOLVE CROSSING DRAIN LINES AND POTENTIALLY DAMAGING SYSTEM. STORAGE BUILDING WAS SET UP WITH NO REGARD FOR DRAINFIELD.

