PREPARED 4/15/09, 14:00:57 Harnett County

INSPECTION TICKET

INSPECTOR: IVR 

\_\_\_\_\_\_

PAGE

DATE 4/16/09

ż

ADDRESS . : 359 COLONIAL HILLS DR

SUBDIV: COLONIAL HILLS PH 2

CONTRACTOR : R & R ENTERPRISES OF FAY., LLC

PHONE: (910) 977-2562

OWNER . . : ADK PROPERTIES #22

PHONE :

PARCEL . .: 03-0507- - -0226- -36-

APPL NUMBER: 06-50015938 CP NEW RESIDENTIAL (SFD) DIRECTIONS : COLONIAL HILLS LOT 22. 210 RIGHT ON

RAY RD RIGHT ON NURSERY RD LEFT ON DOCS

RD ONE MILE ON LEFT. -A.DRIGGERS

LAND NOTES: LXMN 7/02/04 COLONIAL HILLS PH 2 LOT#22

SPLIT FROM THE MAIN PARCEL

STRUCTURE: 000 000 40X65 3BR SFD

FLOOD ZONE . . . : FLOOD ZONE X

PROPOSED USE . . . . . . : SFD


SEPTIC - EXISTING? . . . : NEW WATER SUPPLY . . . . . : UNKNOWN

PERMIT: CPSF 00 CP \* SFD

REQUESTED INSP DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

B101 01 4/16/09 R\*BLDG FOOTING / TEMP SVC POLE VRU #: 001756154



## ECS Carolinas, LLP

726 Ramsey Street Suite 3 Fayetteville, NC 28301 (910) 401-3288 (office)

## LETTER OF TRANSMITTAL

April 10, 2009

Castlebrook NC, LLC 428 Swan Island Court Fayetteville, NC 282311

ATTN: Mr. Chris Manning

RE: DCP's at lot #22 - Colonial Hills Subdivision

ECS Job # 33:1117

Permits:

Location: Fayetteville, NC

We are enclosing:

Materials Engineering Division Reports

For your use

As requested

ENCL:

Field Report # 1

04/07/2009

Nathan Nallainathan, P.E.

Principal Engineer

**APR 9 2009** 

Miguel A. Santiago, P.E. Branch Manager



## ECS Carolinas, LLP

726 Ramsey Street Suite 3 Fayetteville, NC 28301 (910) 401-3288 (office) (910) 323-0539 (fax)

Project

DCP's at lot #22 - Colonial Hills Subdivision

Location

Fayetteville, NC

Client

Castlebrook NC, LLC - Chris Manning

Project No.

Weather

33:1117

Report No. Day & Date

FIELD REPORT

Tuesday 04/07/2009

50°/ Cloudy

On-Site Time 2.25

0.25

Lab Time

Travel Time\* 1.00

Total 3.50

Re Obs.Time 0.00

Remarks

Trip Charges\*

Tolls/Parking\*

Mileage\*

Time of Arrival Departure

02:45P

05:00P

Chargeable Items

Summary of Services Performed (field test data, locations, elevations & depths are estimates) & individuals Contacted.

The undersigned arrived on site, as requested, to perform Dynamic Cone Penetrometer (DCP) testing at lot#22 in the Colonial Hills Subdivison. Please refer to the attached sketch.

Utilizing a Dynamic Cone Penetrometer (ASTM STP-399) to check the bearing capacity of soil at the aforementioned locations, test results indicated that soils, at the areas and elevations tested, should be capable of supporting a foundation designed for a net allowable soil bearing capacity of 2,000 psf.

Please note that loose soil conditions were encountered at test location No. 4 at depth of -3 ft from existing ground surface elevation. DCP results at this location indicated a bearing capacity of 1500 pounds per square foot.

These results will need to be evaluated by the Structural Engineer of Record to confirm if this bearing capacity will suffice the intended structural design. ECS recommends oversize the intended footing at this location to reduce its contact pressure to the encountered bearing capacity or adjusting the footing bearing elevation to the soils below this layer were a bearing capacity of 2000 psf is achieved.

ECS will return for additional testing when requested.

<sup>\*</sup> Travel time and mileage will be billed in accordance with the contract.

	PROJECT: D	CPS AT	LLS DR	22	FIGURE NO. / JOB NO. / 1/17	
CAROLIMAS  ENGINEERING CONSULTING  SERVICES, LTD.  CALCULATION SHEET	BY: ERROLL	DATE: 4-7-09	APPROVED	D BY:	DATE 4-7-04	
	CohoniAL HILLS DEINE			618	# 3500H	

\*

,



CARO	CAROLINAS	Project: DCP's at lot #22 - Colonial Hills Subdivision  Location:	lot #22 - Colonia	d Hills Subdivis	ion	Project No.  Day/Date:	No. 1117 ate: 04/07/09	
		Fayette	Fayetteville - Cumberland County - NC	d County - NO		Dayin		
		Contractor: None Listed	Listed					
		Size (W	Size (W x H x L)	Footing Bottom Elevation	om Elevation		Required Blow Counts	
Footing Number	Location	Design	Actual	Design	Depth of Undercut (in)	Description of Subgrade Material	# of Blows / increment	Design Bearing Pressure
	43' east and 12'	×	×	N/A	subg.ad	 orange clay	6	
	north from lot #22 mark of south west comer of the					sa <sub>nd</sub>	7-6-6	
1	43' east and 12'	××	×	N/A	-1",	orange clay	6	
	north from lot #22 mark of south west comer of the house lot					sand	8-12-14	
	43' east and 12' north from lot #22	×	×	V.N	-2	gray orange w/ roots	6 8-12-14	
	corner of the house lot			,				
-	43' east and 12' north from lot #22 mark of south west corner of the house lot	×	×	N/A	<b>်</b> ပ္	gray-tan clay	5 15-+25	
_				_	-			

By: Errollvinski Mendez

ECS Carolinas, LLP



Contractor: None Listed	Location:  Fayetteville - Cumberland County - NC -	Project: DCP's at lot #22 - Colonial Hills Subdivision
	Day/Date:	Project No.
	04/07/09	No. 1117

_
orange-yellow
:

ECS Carolinas, LLP



			4			,	ىد				ω_			(	ພ		Footing Number	
willa.	mark in north west	south from lot #22	53' east and 35'	corner	mark in north west	south from lot #22	54' east and 9'	comer	mark in north west	south from lot #22	54' east and 9'	comer	mark in north west	south from lot #22	54' east and 9'		Location	
			××				×				×				×		Design	Size (V
			××				×				×				××		Actual	Size (W x H x L)
			A/N				A/N				A/N				A/N		Design	Footing Bottom Elevation
			be.gdus				-3°.				2" .				-1'-		Depth of Undercut (in)	om Elevation
																		-
		clav	orange-yellow		sand	yellow clay	dark gray			yellow sand	dark gray		3 C C C C C C C C C C C C C C C C C C C	day sand	orange-yellow		Description of Subgrade Material	
		8-6-6	6			7-7-8	9			4-8-10	6			5.5.6	6		# of Blows / increment	Required Blow Counts
												•		- 4.			Design Bearing Pressure	

clay

Š
Errollvinski
Mendez

ECS Carolinas, LLP



4	4	4	4	Footing Number
53' east and 35' south from lot #22 mark in north west corner	53' east and 35' south from lot #22 mark in north west corner	53' east and 35' south from lot #22 mark in north west comer	53' east and 35' south from lot #22 mark in north west corner	Location
×	×	; × ×	××	Size (V Design
× ×	×	×	×	Size (W x H x L)  Actual
	N/A	N/A	NIA	Footing Bott Design
4	<u>ئ</u>	-2'.	-47	Footing Bottom Elevation  Depth of Undercut (in)
			:	Description of Steel Placed
orange-gray clay	orange-gray clay	yellow-tan ciąy	orange-yellow clay	Description of Subgrade Material
10-12-15	4-5-4	6 10-12-12	6-6-6	Required Blow Counts # of Blows / increment
				Design Bearing Pressure

<b>.</b>
Errollvinski Mendez

ECS Cardinas, LLP

PREPARED 4/22/09, 14:00:13 INSPECTION TICKET PAGE INSPECTOR: IVR DATE 4/23/09 Harnett County \_\_\_\_\_\_ \_\_\_\_\_\_ ADDRESS . : 359 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS PH 2 PHONE : (910) 977-2562 CONTRACTOR: R & R ENTERPRISES OF FAY., LLC OWNER . . : ADK PROPERTIES #22 PHONE : PARCEL . .: 03-0507- - -0226- -36-APPL NUMBER: 06-50015938 CP NEW RESIDENTIAL (SFD) DIRECTIONS : COLONIAL HILLS LOT 22. 210 RIGHT ON RAY RD RIGHT ON NURSERY RD LEFT ON DOCS RD ONE MILE ON LEFT. -A.DRIGGERS LAND NOTES: LXMN 7/02/04 COLONIAL HILLS PH 2 LOT#22 SPLIT FROM THE MAIN PARCEL STRUCTURE: 000 000 40X65 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE . . . . . . . SFD WATER SUPPLY . . . . . : UNKNOWN SEPTIC - EXISTING? . . . : NEW \_\_\_\_\_\_\_

PERMIT: CPSF 00 CP \* SFD

REQUESTED INSP DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

B101 01 4/16/09 DT R\*BLDG FOOTING / TEMP SVC POLE VRU #: 001756154

4/16/09 AP 1. Need engineered soil report.

B103 01 4/23/09 TI R\*BLDG FOUND & TEMP SVC POLE VRU #: 001758796

4-239 AP-MP

COMMENTS AND NOTES

Committee to the state of the state of the

PREPARED 4/23/09, 13:59:12
Harnett County INSPECTION TICKET PAGE INSPECTOR: IVR DATE 4/24/09 \_\_\_\_\_ ADDRESS . : 359 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS PH 2 CONTRACTOR : R & R ENTERPRISES OF FAY., LLC PHONE : (910) 977-2562 OWNER . . : ADK PROPERTIES #22 PHONE : PARCEL . . : 03-0507- - -0226- -36-APPL NUMBER: 06-50015938 CP NEW RESIDENTIAL (SFD) \_\_\_\_\_\_ , DIRECTIONS : COLONIAL HILLS LOT 22. 210 RIGHT ON RAY RD RIGHT ON NURSERY RD LEFT ON DOCS RD ONE MILE ON LEFT. -A.DRIGGERS LAND NOTES: LXMN 7/02/04 COLONIAL HILLS PH 2 LOT#22 SPLIT FROM THE MAIN PARCEL STRUCTURE: 000 000 40X65 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE . . . . . . : SFD
WATER SUPPLY . . . . . . : UNKNOWN SEPTIC - EXISTING? . . . . : NEW PERMIT: CPSF 00 CP \* SFD REQUESTED INSP DESCRIPTION

REQUESTED INSP DESCRIPTION

TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

B101 01 4/16/09 DT R\*BLDG FOOTING / TEMP SVC POLE VRU #: 001756154
4/16/09 AP 1. Need engineered soil report.

B103 01 4/23/09 MR R\*BLDG FOUND & TEMP SVC POLE VRU #: 001758796
4/23/09 AP

B105 01 4/24/09 TI R\*OPEN FLOOR VRU #: 001759836

4-249 AP-MA Early Morning if possible. Thanks Gary W. Robinson

COMMENTS AND NOTES

PREPARED 5/07/09, 14:13:30
Harnett County INSPECTION TICKET PAGE INSPECTOR: IVR DATE 5/08/09 ADDRESS . : 359 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS PH 2 CONTRACTOR : R & R ENTERPRISES OF FAY., LLC PHONE : (910) 977-2562 OWNER . . : ADK PROPERTIES #22 PHONE : PARCEL . . : 03-0507- - -0226- -36-APPL NUMBER: 06-50015938 CP NEW RESIDENTIAL (SFD) DIRECTIONS : COLONIAL HILLS LOT 22. 210 RIGHT ON RAY RD RIGHT ON NURSERY RD LEFT ON DOCS RD ONE MILE ON LEFT. -A.DRIGGERS LAND NOTES: LXMN 7/02/04 COLONIAL HILLS PH 2 LOT#22 SPLIT FROM THE MAIN PARCEL STRUCTURE: 000 000 40X65 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X PROPOSED USE . . . . . . : SFD
WATER SUPPLY . . . . . . : UNKNOWN SEPTIC - EXISTING? . . . : NEW PERMIT: CPSF 00 CP \* SFD REQUESTED INSP DESCRIPTION COMPLETED RESULT RESULTS/COMMENTS

TYP/SQ 4/16/09 DT R\*BLDG FOOTING / TEMP SVC POLE VRU #: 001756154 4/16/09 AP 1. Need engineered soil report. 4/23/09 MR R\*BLDG FOUND & TEMP SVC POLE VRU #: 001758796 B101 01 B103 01 4/23/09 AP B105 01 4/24/09 MR R\*OPEN FLOOR VRU #: 001759836 Early Morning if possible. Thanks Gary W. Robinson 4/24/09 AP 5/08/09 R427 02 FOUR TRADE ROUGH IN >2500 VRU #: 001765270  $\mathtt{TI}$ 5,8-9 R427 01 5/08/09 5/07/09 CA

# **HARNETT COUNTY**

Building Inspections Dept. 108 E. Front St. Lillington, NC 27546 910-893-7525

# DO NOT REMOVE

DATE: 05-08-09

PERMIT# 06-50015938

ADDRESS: 359 colonial hills

## **VIOLATIONS:**

1. Fireplace missing

- 2. Firecaulking needed over fireplace
- 3. Smoke detector upstairs wall is in wrong place it must be 2' from return air
- 4. Roof shingles and boots not completed
- 5. Both mbr sinks will need studor vents on final
- 6. Ok to side, but not insulate

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

PREPARED 5/12/09, 13:59:45 Harnett County

INSPECTION TICKET INSPECTOR: IVR

\_\_\_\_\_\_

PAGE

DATE 5/13/09

ADDRESS . : 359 COLONIAL HILLS DR

SUBDIV: COLONIAL HILLS PH 2

CONTRACTOR : R & R ENTERPRISES OF FAY., LLC

PHONE : (910) 977-2562

OWNER . . : ADK PROPERTIES #22

PHONE :

PARCEL . . : 03-0507- - -0226- -36-

APPL NUMBER: 06-50015938 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : COLONIAL HILLS LOT 22. 210 RIGHT ON

RAY RD RIGHT ON NURSERY RD LEFT ON DOCS

RD ONE MILE ON LEFT. -A.DRIGGERS

LAND NOTES: LXMN 7/02/04 COLONIAL HILLS PH 2 LOT#22

SPLIT FROM THE MAIN PARCEL

STRUCTURE: 000 000 40X65 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X

# BEDROOMS . . . . . . :

3.00 PROPOSED USE . . . . . . : SFD

WATER SUPPLY . . . . . : UNKNOWN SEPTIC - EXISTING? . . . : NEW 

PERM]	IT:	CPSF 00 CP *	SFD INSP	DESCRIPTION
TYP/S	3Q	COMPLETED		RESULTS/COMMENTS
B101	01	4/16/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001756154
		4/16/09	AP	1. Need engineered soil report.
B103	01	4/23/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001758796
		4/23/09	AP	
B105	01	4/24/09	MR	R*OPEN FLOOR VRU #: 001759836
		4/24/09	AP	Early Morning if possible. Thanks Gary W. Robinson
R427	02	5/08/09	MR	_FOUR TRADE ROUGH IN >2500
		5/08/09	DA	fireplace missing
			しノ・	firecaulk over fireplace
	-		_	upstairs smoke detector to be 2' from return
				shingles and boots needed
			•	both mbr sinks will need studor vents on final
R427	01	5/08/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001765254
		5/07/09	CA	
R427	03	5/13/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001766807
		5-13-9	AP-MK	
			<u> </u>	

PREPARED 5/14/09, 16:01:38
Harnett County

INSPECTION TICKET

\_\_\_\_\_\_

PAGE

INSPECTOR: IVR

DATE 5/15/09

ADDRESS . : 359 COLONIAL HILLS DR

SUBDIV: COLONIAL HILLS PH 2

CONTRACTOR : R & R ENTERPRISES OF FAY., LLC

PHONE : (910) 977-2562

OWNER . . : ADK PROPERTIES #22

PHONE :

PARCEL . . : 03-0507- - -0226- -36-

APPL NUMBER: 06-50015938 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : COLONIAL HILLS LOT 22. 210 RIGHT ON

RAY RD RIGHT ON NURSERY RD LEFT ON DOCS

RD ONE MILE ON LEFT. -A.DRIGGERS

LAND NOTES: LXMN 7/02/04 COLONIAL HILLS PH 2 LOT#22

SPLIT FROM THE MAIN PARCEL

STRUCTURE: 000 000 40X65 3BR SFD

FLOOD ZONE . . . : FLOOD ZONE X

# BEDROOMS . . . . . . : 3.00 PROPOSED USE . . . . . . . SFD

WATER SUPPLY . . . . . : UNKNOWN SEPTIC - EXISTING? . . . : NEW

PERMIT: CPSF 00 CP * SFD						
	REQUESTED	INSP	DESCRIPTION			
TYP/SQ	COMPLETED	RESULT	RESULTS/COMMENTS			
B101 01	4/16/09	DT	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001756154			
	4/16/09	AP	1. Need engineered soil report.			
B103 01	4/23/09	MR	R*BLDG FOUND & TEMP SVC POLE VRU #: 001758796			
	4/23/09	AP				
B105 01	4/24/09	MR	R*OPEN FLOOR			
	4/24/09	AP	Early Morning if possible. Thanks Gary W. Robinson			
R427 02	5/08/09	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001765270			
	5/08/09	DA	1. fireplace missing			
			2. firecaulk over fireplace			
			3. upstairs smoke detector to be 2' from return			
			4. shingles and boots needed			
			5, both mbr sinks will need studor vents on final			
R427 01	5/08/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001765254			
	5/07/09	CA				
R427 03	5/13/09	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001766807			
	5/13/09	AP				
A814 01	5/15/09	TI	ADDRESS CONFIRMATION VRU #: 001768993			
I129 01	5/15/09	TI	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001769074			
	5-15-9	AP-MK				
		- 0,				

ADDRESS . : 359 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS PH 2 CONTRACTOR : R & R ENTERPRISES OF FAY., LLC PHONE: (910) 977-2562

OWNER . . : ADK PROPERTIES #22 PHONE :

PARCEL . . : 03-0507- - -0226- -36-

APPL NUMBER: 06-50015938 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : COLONIAL HILLS LOT 22. 210 RIGHT ON

RAY RD RIGHT ON NURSERY RD LEFT ON DOCS

RD ONE MILE ON LEFT. -A.DRIGGERS

LAND NOTES: LXMN 7/02/04 COLONIAL HILLS PH 2 LOT#22

SPLIT FROM THE MAIN PARCEL 

STRUCTURE: 000 000 40X65 3BR SFD FLOOD ZONE . . . : FLOOD ZONE X

# BEDROOMS . . . . . . . . . 3.00 PROPOSED USE . . . . . . : SFD

SEPTIC - EXISTING? . . . : NEW WATER SUPPLY . . . . . : UNKNOWN

\_\_\_\_\_\_ PERMIT: CPSF 00 CP \* SFD REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS 4/16/09 DT 4/16/09 AP B101 01 4/16/09 DT R\*BLDG FOOTING / TEMP SVC POLE VRU #: 001756154 4/16/09 AP 1. Need engineered soil report. B103 01 4/23/09 MR R\*BLDG FOUND & TEMP SVC POLE VRU #: 001758796 B101 01 4/23/09 AP 4/24/09 MR 4/24/09 AP R\*OPEN FLOOR VRU #: 001759836 Early Morning if possible. Thanks Gary W. Robinson B105 01 R427 02 5/08/09 MR FOUR TRADE ROUGH IN >2500 VRU #: 001765270 5/08/09 DA 1. fireplace missing 2. firecaulk over fireplace 3. upstairs smoke detector to be 2' from return 4. shingles and boots needed 5, both mbr sinks will need studor vents on final R427 01 5/08/09 TI FOUR TRADE ROUGH IN >2500 VRU #: 001765254 5/07/09 CA R427 03 5/13/09 MR FOUR TRADE ROUGH IN >2500 VRU #: 001766807 5/13/09 AP 5/15/09 TI ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001768993 5/21/09 AP 359 COLONIAL HILLS DR LOT 22 A814 01 5/15/09 TI LILLINGTON 27546 I129 01 5/15/09 MR R\*INSULATION INSPECTION TIME: 17:00 VRU #: 001769074 5/15/09 AP R429 01 7/06/09 TI FOUR TRADE FINAL VRU #: 001790062

35 Crpress Paint

7-6-9 DP-MK

# **HARNETT COUNTY**

Building Inspections Dept. 108 E. Front St. Lillington, NC 27546 910-893-7525

# DO NOT REMOVE

DATE: 07-06-09

2 --- te

PERMIT # 06-50015938

ADDRESS: 359 colonial hills

## **VIOLATIONS:**

1. house numbers needed

- 2. grading at rear not complete
- 3. Plumbing not ready
- 4. Caulk toilets to floor
- 5. Plastic under house missing
- 6. Secondary drain to outside of foundation needed on ahu under house Fee 50

Harnett County Building Department

Mike Rearic cell# (910) 984- 4772

PREPARED 7/07/09; 14:26:34

INSPECTION TICKET

PAGE

3 DATE 7/08/09

\_\_\_\_\_

Harnett\_County

INSPECTOR: IVR

ADDRESS . : 359 COLONIAL HILLS DR

SUBDIV: COLONIAL HILLS PH 2

CONTRACTOR : R & R ENTERPRISES OF FAY., LLC

PHONE: (910) 977-2562

OWNER . . : ADK PROPERTIES #22

PHONE :

PARCEL . . : 03-0507- - -0226- -36-

APPL NUMBER: 06-50015938 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : COLONIAL HILLS LOT 22. 210 RIGHT ON

RAY RD RIGHT ON NURSERY RD LEFT ON DOCS

RD ONE MILE ON LEFT. -A.DRIGGERS

LAND NOTES : LXMN 7/02/04 COLONIAL HILLS PH 2 LOT#22

SPLIT FROM THE MAIN PARCEL

STRUCTURE: 000 000 40X65 3BR SFD

FLOOD ZONE . . . : FLOOD ZONE X

# BEDROOMS . . . . . . : 3.00 PROPOSED USE . . . . . . . . SFD

SEPTIC - EXISTING? . . . : NEW WATER SUPPLY . . . . . : UNKNOWN

PERMIT:	CPSF 00 CP * REQUESTED COMPLETED	INSP	DESCRIPTION RESULTS/COMMENTS
 B101 01	4/16/00		
PT01 01	4/16/09 4/16/09		R*BLDG FOOTING / TEMP SVC POLE VRU #: 001756154
B103 01	4/23/09	MR	1. Need engineered soil report.
PT03 0T	4/23/09	AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001758796
B105 01	4/24/09	MR	R*OPEN FLOOR VRU #: 001759836
2103 01	4/24/09	AP	Early Morning if possible. Thanks Gary W. Robinson
R427 02	5/08/09	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001765270
(42/ 02	5/08/09	DA.	1. fireplace missing
	3/08/03	DA	2. firecaulk over fireplace
			3. upstairs smoke detector to be 2' from return
			4. shingles and boots needed
			5, both mbr sinks will need studor vents on final
R427 01	5/08/09	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001765254
(42) 01	5/07/09	CA	FOOR TRADE ROUGH IN >2500 VRU #: 001/65254
2427 03		MR	FOUR TRADE ROUGH IN >2500 VRU #: 001766807
(427 05	5/13/09	AP	FOOR TRADE ROOM IN >2300 VRO #: 001/86807
A814 01	5/15/09	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001768993
	5/21/09	AP	359 COLONIAL HILLS DR LOT 22
	2,22,03	***	LILLINGTON 27546
129 01	5/15/09	MR	R*INSULATION INSPECTION TIME: 17:00 VRU #: 001769074
	5/15/09	AP	11.00 THOUSE INDICATION 11.10 THE TOTAL TO THE TRANSPORT OF THE TOTAL TRANSPORT OF THE TOTA
429 01	7/06/09	MR	FOUR TRADE FINAL VRU #: 001790062
	7/06/09	DP	T/S: 07/06/2009 08:59 AM MREARIC
	, ,		* house numbers needed
			magnetic from grading at rear is not away from foundation and raise
			the ac units
			3. plumbing not complete
		•	aulk toilets
			> plastic under house
			6. secondary drain to outside of foundation needed on AHu
425 01	7/07/09	MR	FOUR TRADE ROUGH IN VRU #: 001790294
	7/06/09	CA	T/S: 07/06/2009 01:04 PM MREARIC
429 02	7/08/09	TI	FOUR TRADE FINAL TIME: 17:00 VRU #: 001791292
	7,8-9	AP-MP	T/S: 07/07/2009 12:46 PM VBROWN

------ COMMENTS AND NOTES ------

# COUNTY OF HARNETT DEPARTMENT OF BUILDING INSPECTION AND PLANNING/DEVELOPMENT CERTIFICATE OF OCCUPANCY

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: 2-3	Conditional Use Permit No.:Building Permit No.: 06-50015938		
Type of Construction:			
Owner of Building: ADK Properties	Electrical Permit No.:	<u> </u>	
Building Address: 359 Colema Hills	Insulation Permit No.:	1\	
Zoning District:	Plumbing Permit No.:	, , , , , , , , , , , , , , , , , , ,	
Zoning Permit No.:	Mech. Permit No.:	, ,	
Date: 7-8-9	Envir. C.O. No.:		
J. Mily Rearie			
Building Official	Zoning Official		