
ADDRESS . . : 765 COLONIAL HILLS DR
CONTRACTOR :
OWNER . . . : ADK PARTNERS #43
PARCEL . . . : 03-0507- - -0226- -61-
APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
RD ONE MILE ON LEFT. -A.DRIGGERS

SUBDIV: COLONIAL HILLS
PHONE :
PHONE :

STRUCTURE: 000 000 48X54 3BR SFD

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07 <u>4-9-7</u>	TI <u>AP-CE</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483

----- COMMENTS AND NOTES -----

ADDRESS . : 765 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
CONTRACTOR : PHONE :
OWNER . . : ADK PARTNERS #43 PHONE :
PARCEL . . : 03-0507- - -0226- -61-
APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
RD ONE MILE ON LEFT. -A.DRIGGERS

STRUCTURE: 000 000 48X54 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
A814 01	4/16/07	TI	ADDRESS CONFIRMATION VRU #: 001390178
B103 01	4/16/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186

OA JH

----- COMMENTS AND NOTES -----

ADDRESS . : 765 COLONIAL HILLS DR
CONTRACTOR :
OWNER . . : ADK PARTNERS #43
PARCEL . . : 03-0507- - -0226- -61-
APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
RD ONE MILE ON LEFT. -A.DRIGGERS

SUBDIV: COLONIAL HILLS
PHONE :
PHONE :

STRUCTURE: 000 000 48X54 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178
	4/18/07	AP	765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	TI	R*OPEN FLOOR VRU #: 001392996

CAJH not Ready

COMMENTS AND NOTES

ADDRESS . . : 765 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
CONTRACTOR : PHONE :
OWNER . . . : ADK PARTNERS #43 PHONE :
PARCEL . . . : 03-0507- - -0226- -61-
APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
RD ONE MILE ON LEFT. -A.DRIGGERS

STRUCTURE: 000 000 48X54 3BR SFD
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178
	4/18/07	AP	765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	JH	R*OPEN FLOOR VRU #: 001392996
	4/19/07	CA	Not ready
B105 02	4/20/07	TI	R*OPEN FLOOR VRU #: 001394100

DA JV

COMMENTS AND NOTES

ADDRESS . : 765 COLONIAL HILLS DR
CONTRACTOR :
OWNER . . : ADK PARTNERS #43
PARCEL . . : 03-0507- - -0226- -61-
APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
RD ONE MILE ON LEFT. -A.DRIGGERS

SUBDIV: COLONIAL HILLS
PHONE :
PHONE :

STRUCTURE: 000 000 48X54 3BR SFD
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME:17:00 VRU #: 001390178
	4/18/07	AP	765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	JH	R*OPEN FLOOR VRU #: 001392996
	4/19/07	CA	Not ready
B105 02	4/20/07	JH	R*OPEN FLOOR VRU #: 001394100
	4/20/07	DA	1)Need anchor bolts every 6' & 1' from every corner. 2)Center of girder is to be in the center 1/3 of the piers,if you have to pour more footing it needs to be inspected before you pour, or you can get engineer.
B105 03	4/23/07	TI	R*OPEN FLOOR VRU #: 001395065
		AP JV	VOICE MESSAGE LEFT

----- COMMENTS AND NOTES -----

ADDRESS : 765 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
CONTRACTOR : PHONE :
OWNER : ADK PARTNERS #43 PHONE :
PARCEL : 03-0507- - -0226- -61-
APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
RD ONE MILE ON LEFT. -A.DRIGGERS

STRUCTURE: 000 000 48X54 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178
	4/18/07	AP	765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	JH	R*OPEN FLOOR VRU #: 001392996
	4/19/07	CA	Not ready
B105 02	4/20/07	JH	R*OPEN FLOOR VRU #: 001394100
	4/20/07	DA	1)Need anchor bolts every 6' & 1' from every corner. 2)Center of girder is to be in the center 1/3 of the piers,if you have to pour more footing it needs to be inspected before you pour, or you can get engineer.
B105 03	4/23/07	JH	R*OPEN FLOOR VRU #: 001395065
	4/23/07	AP	VOICE MESSAGE LEFT
E207 01	4/26/07	TI	R*ELEC TEMP SERVICE POLE VRU #: 001397553

AP-IVR

COMMENTS AND NOTES

Pole on Lot #42

ADDRESS . : 765 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
 CONTRACTOR : PHONE :
 OWNER . . : ADK PARTNERS #43 PHONE :
 PARCEL . . : 03-0507- - -0226- -61-
 APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. -A.DRIGGERS

STRUCTURE: 000 000 48X54 3BR SFD
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178
	4/18/07	AP	765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	JH	R*OPEN FLOOR VRU #: 001392996
	4/19/07	CA	Not ready
B105 02	4/20/07	JH	R*OPEN FLOOR VRU #: 001394100
	4/20/07	DA	1)Need anchor bolts every 6' & 1' from every corner. 2)Center of girder is to be in the center 1/3 of the piers,if you have to pour more footing it needs to be inspected before you pour, or you can get engineer.
B105 03	4/23/07	JH	R*OPEN FLOOR VRU #: 001395065
	4/23/07	AP	VOICE MESSAGE LEFT
E207 01	4/26/07	MR	R*ELEC TEMP SERVICE POLE VRU #: 001397553
	4/26/07	AP	pole only
R427 01	5/17/07	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001410679

DA-MR

COMMENTS AND NOTES

 ADDRESS : 765 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
 CONTRACTOR : PHONE :
 OWNER : ADK PARTNERS #43 PHONE :
 PARCEL : 03-0507- - -0226- -61-
 APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. -A.DRIGGERS

STRUCTURE: 000 000 48X54 3BR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178
	4/18/07	AP	765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	JH	R*OPEN FLOOR VRU #: 001392996
	4/19/07	CA	Not ready
B105 02	4/20/07	JH	R*OPEN FLOOR VRU #: 001394100
	4/20/07	DA	1)Need anchor bolts every 6' & 1' from every corner. 2)Center of girder is to be in the center 1/3 of the piers,if you have to pour more footing it needs to be inspected before you pour, or you can get engineer.
B105 03	4/23/07	JH	R*OPEN FLOOR VRU #: 001395065
	4/23/07	AP	VOICE MESSAGE LEFT
E207 01	4/26/07	MR	R*ELEC TEMP SERVICE POLE VRU #: 001397553
	4/26/07	AP	pole only
R427 01	5/17/07	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001410679
	5/17/07	DA	1. beams over garage doors not to code,, over-spanned 2. no boots on roof 3. fireblock main plumbing stack 4 nail sole plates on both floors to joists or band @16" with 16# nails on perimeter 5 provide eng. letter on cantilevered section of house over porch,showing support or provide design info 6 block and nail braced section in garage
R427 02	5/22/07	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001413582
		AP.MRL	

----- COMMENTS AND NOTES -----

Sheath inside garage

ADDRESS . . : 765 COLONIAL HILLS DR
 CONTRACTOR :
 OWNER . . : ADK PARTNERS #43
 PARCEL . . : 03-0507- - -0226- -61-
 APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. -A.DRIGGERS

SUBDIV: COLONIAL HILLS
 PHONE :
 PHONE :

STRUCTURE: 000 000 48X54 3BR SFD
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178
	4/18/07	AP	765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	JH	R*OPEN FLOOR VRU #: 001392996
	4/19/07	CA	Not ready
B105 02	4/20/07	JH	R*OPEN FLOOR VRU #: 001394100
	4/20/07	DA	1)Need anchor bolts every 6' & 1' from every corner. 2)Center of girder is to be in the center 1/3 of the piers,if you have to pour more footing it needs to be inspected before you pour, or you can get engineer.
B105 03	4/23/07	JH	R*OPEN FLOOR VRU #: 001395065
	4/23/07	AP	VOICE MESSAGE LEFT
E207 01	4/26/07	MR	R*ELEC TEMP SERVICE POLE VRU #: 001397553
	4/26/07	AP	pole only
R427 01	5/17/07	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001410679
	5/17/07	DA	1. beams over garage doors not to code,, over-spanned 2. no boots on roof 3. fireblock main plumbing stack 4. nail sole plates on both floors to joists or band @16" with 16# nails on perimeter 5 provide eng. letter on cantilevered section of house over porch,showing support or provide design info 6. block and nail braced section in garage
R427 02	5/22/07	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001413582
	5/22/07	AP	sheath inside of garagw door wall
I129 01	5/29/07	TI	R*INSULATION INSPECTION VRU #: 001416833

DA-MR

COMMENTS AND NOTES

ADDRESS : 765 COLONIAL HILLS DR
 CONTRACTOR :
 OWNER : ADK PARTNERS #43
 PARCEL : 03-0507- - -0226- -61-
 APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. -A.DRIGGERS

SUBDIV: COLONIAL HILLS
 PHONE :
 PHONE :

STRUCTURE: 000 000 48X54 3BR SFD
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178
	4/18/07	AP	765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	JH	R*OPEN FLOOR VRU #: 001392996
	4/19/07	CA	Not ready
B105 02	4/20/07	JH	R*OPEN FLOOR VRU #: 001394100
	4/20/07	DA	1)Need anchor bolts every 6' & 1' from every corner. 2)Center of girder is to be in the center 1/3 of the piers,if you have to pour more footing it needs to be inspected before you pour, or you can get engineer.
B105 03	4/23/07	JH	R*OPEN FLOOR VRU #: 001395065
	4/23/07	AP	VOICE MESSAGE LEFT
E207 01	4/26/07	MR	R*ELEC TEMP SERVICE POLE VRU #: 001397553
	4/26/07	AP	pole only
R427 01	5/17/07	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001410679
	5/17/07	DA	1. beams over garage doors not to code,, over-spanned 2. no boots on roof 3. fireblock main plumbing stack 4. nail sole plates on both floors to joists or band @16" with 16# nails on perimeter 5 provide eng. letter on cantilevered section of house over porch,showing support or provide design info 6. block and nail braced section in garage
R427 02	5/22/07	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001413582
	5/22/07	AP	sheath inside of garagw door wall
I129 01	5/29/07	MR	R*INSULATION INSPECTION VRU #: 001416833
	5/29/07	DA	1. no gas pressure on line 2. insulate under AHU platform
I129 02	5/30/07	TI	R*INSULATION INSPECTION VRU #: 001418482

DA-MR

COMMENTS AND NOTES

Gas Pressure not checked
 OK To daywall

ADDRESS : 765 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
 CONTRACTOR : PHONE :
 OWNER : ADK PARTNERS #43 PHONE :
 PARCEL : 03-0507- - -0226- -61-
 APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. -A.DRIGGERS

STRUCTURE: 000 000 48X54 3BR SFD
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178
	4/18/07	AP	✓765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	JH	R*OPEN FLOOR VRU #: 001392996
	4/19/07	CA	Not ready
B105 02	4/20/07	JH	R*OPEN FLOOR VRU #: 001394100
	4/20/07	DA	1)Need anchor bolts every 6' & 1' from every corner. 2)Center of girder is to be in the center 1/3 of the piers,if you have to pour more footing it needs to be inspected before you pour, or you can get engineer.
B105 03	4/23/07	JH	R*OPEN FLOOR VRU #: 001395065
	4/23/07	AP	VOICE MESSAGE LEFT
E207 01	4/26/07	MR	R*ELEC TEMP SERVICE POLE VRU #: 001397553
	4/26/07	AP	pole only
R427 01	5/17/07	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001410679
	5/17/07	DA	1. beams over garage doors not to code,, over-spanned 2. no boots on roof 3. fireblock main plumbing stack 4. nail sole plates on both floors to joists or band @16" with 16# nails on perimeter 5 provide eng. letter on cantilevered section of house over porch,showing support or provide design info 6. block and nail braced section in garage
R427 02	5/22/07	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001413582
	5/22/07	AP	sheath inside of garagw door wall
I129 01	5/29/07	MR	R*INSULATION INSPECTION VRU #: 001416833
	5/29/07	DA	1. no gas pressure on line 2. insulate under AHU platform
I129 02	5/30/07	MR	R*INSULATION INSPECTION VRU #: 001418482
	5/30/07	DA	ok to drywall but must check gas pressure before passing
H824 01	7/10/07	JW	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001444678
	7/10/07	AP	
R431 01	7/24/07	TI	FOUR TRADE FINAL >2500 VRU #: 001452408

DA.MR

ADDRESS : 765 COLONIAL HILLS DR
 CONTRACTOR :
 OWNER : ADK PARTNERS #43
 PARCEL : 03-0507- - -0226- -61-
 APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. -A.DRIGGERS

SUBDIV: COLONIAL HILLS
 PHONE :
 PHONE :

STRUCTURE: 000 000 48X54 3BR SFD
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07	CE	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
	4/09/07	AP	
B103 01	4/16/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186
	4/16/07	DA	1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178
	4/18/07	AP	✓765 Colonial Hills Dr
B103 02	4/18/07	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
	4/18/07	AP	
B105 01	4/19/07	JH	R*OPEN FLOOR VRU #: 001392996
	4/19/07	CA	Not ready
B105 02	4/20/07	JH	R*OPEN FLOOR VRU #: 001394100
	4/20/07	DA	1)Need anchor bolts every 6' & 1' from every corner. 2)Center of girder is to be in the center 1/3 of the piers,if you have to pour more footing it needs to be inspected before you pour, or you can get engineer.
B105 03	4/23/07	JH	R*OPEN FLOOR VRU #: 001395065
	4/23/07	AP	VOICE MESSAGE LEFT
E207 01	4/26/07	MR	R*ELEC TEMP SERVICE POLE VRU #: 001397553
	4/26/07	AP	pole only
R427 01	5/17/07	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001410679
	5/17/07	DA	1. beams over garage doors not to code,, over-spanned 2. no boots on roof 3. fireblock main plumbing stack 4. nail sole plates on both floors to joists or band @16" with 16# nails on perimeter 5 provide eng. letter on cantilevered section of house over porch,showing support or provide design info 6. block and nail braced section in garage
R427 02	5/22/07	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001413582
	5/22/07	AP	sheath inside of garagw door wall
I129 01	5/29/07	MR	R*INSULATION INSPECTION VRU #: 001416833
	5/29/07	DA	1. no gas pressure on line 2. insulate under AHU platform
I129 02	5/30/07	MR	R*INSULATION INSPECTION VRU #: 001418482
	5/30/07	DA	ok to drywall but must check gas pressure before passing
H824 01	7/10/07	JW	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001444678
	7/10/07	AP	
R431 01	7/24/07	MR	FOUR TRADE FINAL >2500 VRU #: 001452408
	7/24/07	DA	1. provide ladder for attic access 2. caulk toilets 3. provide secondary drains on all AHU's to either the pan

ADDRESS . : 765 COLONIAL HILLS DR
CONTRACTOR :
OWNER . . : ADK PARTNERS #43
PARCEL . . : 03-0507- - -0226- -61-
APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)

SUBDIV: COLONIAL HILLS
PHONE :
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R431 02	7/30/07 <u>7/30/07</u>	TI <u>DAH DS</u>	<p>or crawlspace</p> <p>4. insulate plumbing over kitchen.. seen from bonus room access</p> <p>5. clean debris from under house</p> <p>FOUR TRADE FINAL >2500 VRU #: 001456177</p>

----- COMMENTS AND NOTES -----

ADDRESS . : 765 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
 CONTRACTOR : PHONE :
 OWNER . . : ADK PARTNERS #43 PHONE :
 PARCEL . . : 03-0507- - -0226- -61-
 APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 43. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. -A.DRIGGERS

STRUCTURE: 000 000 48X54 3BR SFD
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	4/09/07 4/09/07	CE AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001385483
B103 01	4/16/07 4/16/07	JH DA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001390186 1)Missing anchor bolts @ front & back porches on exterior house wall. 2)Piers are sticking out over footings, the center of the pier shall be in the center 1/3 of the footing.They are mared with a x on top.
A814 01	4/16/07 4/18/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001390178 ✓765 Colonial Hills Dr
B103 02	4/18/07 4/18/07	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001391366
B105 01	4/19/07 4/19/07	JH CA	R*OPEN FLOOR VRU #: 001392996 Not ready
B105 02	4/20/07 4/20/07	JH DA	R*OPEN FLOOR VRU #: 001394100 1)Need anchor bolts every 6' & 1' from every corner. 2)Center of girder is to be in the center 1/3 of the piers,if you have to pour more footing it needs to be inspected before you pour, or you can get engineer.
B105 03	4/23/07 4/23/07	JH AP	R*OPEN FLOOR VRU #: 001395065 VOICE MESSAGE LEFT
E207 01	4/26/07 4/26/07	MR AP	R*ELEC TEMP SERVICE POLE VRU #: 001397553 pole only
R427 01	5/17/07 5/17/07	MR DA	FOUR TRADE ROUGH IN >2500 VRU #: 001410679 1. beams over garage doors not to code,, over-spanned 2. no boots on roof 3. fireblock main plumbing stack 4. nail sole plates on both floors to joists or band @16" with 16# nails on perimeter 5 provide eng. letter on cantilevered section of house over porch,showing support or provide design info 6. block and nail braced section in garage
R427 02	5/22/07 5/22/07	MR AP	FOUR TRADE ROUGH IN >2500 VRU #: 001413582 sheath inside of garagw door wall
I129 01	5/29/07 5/29/07	MR DA	R*INSULATION INSPECTION VRU #: 001416833 1. no gas pressure on line 2. insulate under AHU platform
I129 02	5/30/07 5/30/07	MR DA	R*INSULATION INSPECTION VRU #: 001418482 ok to drywall but must check gas pressure before passing
H824 01	7/10/07 7/10/07	JW AP	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001444678
R431 01	7/24/07 7/24/07	MR DA	FOUR TRADE FINAL >2500 VRU #: 001452408 1. provide ladder for attic access 2. caulk toilets 3. provide secondary drains on all AHU's to either the pan

ADDRESS . . : 765 COLONIAL HILLS DR
CONTRACTOR :
OWNER . . . : ADK PARTNERS #43
PARCEL . . . : 03-0507- - -0226- -61-
APPL NUMBER: 06-50015961 CP NEW RESIDENTIAL (SFD)

SUBDIV: COLONIAL HILLS
PHONE :
PHONE :

TYP/SQ REQUESTED INSP DESCRIPTION
COMPLETED RESULT RESULTS/COMMENTS

or crawlspace

4. insulate plumbing over kitchen.. seen from bonus room
access

5. clean debris from under house

R431 02 7/30/07 DT FOUR TRADE FINAL >2500 VRU #: 001456177

7/30/07 DA AHU in attic has no secondary drain.

R431 03 8/01/07 TI FOUR TRADE FINAL >2500 VRU #: 001457654

8/1/07 AP DT

----- COMMENTS AND NOTES -----

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: <u>Residential</u>	Conditional Use Permit No.: _____
Type of Construction: <u>J</u>	Building Permit No.: _____
Owner of Building: <u>ADK Partners</u>	Electrical Permit No.: _____
Building Address: <u>765 Wood Hills Dr.</u>	Insulation Permit No.: _____
Zoning District: _____	Plumbing Permit No.: _____
Zoning Permit No.: _____	Mech. Permit No.: <u>06-50015961</u>
Date: <u>8/11/07</u>	Envir. C.O. No.: _____

Building Official

Zoning Official