
ADDRESS . : 705 COLONIAL HILLS DR
 CONTRACTOR : R B C HOMES, INC.
 OWNER . . : RBC HOMES #45
 PARCEL . . : 03-0507- - -0226- -63-
 APPL NUMBER: 06-50015963 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 45. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. LOT IS ON CORNER
 OF DOWNING CT AND COLONIAL HILLS DRIVE.
 DRIVEWAY IS OFF OF COLONIAL HILLS
 DRIVE. -A.DRIGGERS

STRUCTURE: 000 000 40X65 3BR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/14/07 <u>3-14-7</u>	TI <u>APCE</u>	R*BLDG FOOTING / TEMP SVC POLE WOULD LIKE INSPECTION IN THE AM.

----- COMMENTS AND NOTES -----

10063

Need fr. dr. around left rear corner

ADDRESS . : 705 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
CONTRACTOR : R B C HOMES, INC. PHONE : (910) 423-3555
OWNER . . : RBC HOMES #45 PHONE : (910) 423-3555
PARCEL . . : 03-0507- - -0226- -63-
APPL NUMBER: 06-50015963 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS LOT 45. 210 RIGHT ON
RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
RD ONE MILE ON LEFT. LOT IS ON CORNER
OF DOWNING CT AND COLONIAL HILLS DRIVE.
DRIVEWAY IS OFF OF COLONIAL HILLS
DRIVE. -A.DRIGGERS

STRUCTURE: 000 000 40X65 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/14/07 3/14/07	CE AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001370055 WOULD LIKE INSPECTION IN THE AM. Install French drain around left rear corner by rough-in inspection. ce
A814 01	3/26/07	TI	ADDRESS CONFIRMATION VRU #: 001377076
B103 01	<u>3/26/07</u> 3-26-7	<u>TI</u> AE-CE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001377084

----- COMMENTS AND NOTES -----

ADDRESS . : 705 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
 CONTRACTOR : R B C HOMES, INC. PHONE : (910) 423-3555
 OWNER . . : RBC HOMES #45 PHONE : (910) 423-3555
 PARCEL . . : 03-0507- - -0226- -63-
 APPL NUMBER: 06-50015963 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 45. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. LOT IS ON CORNER
 OF DOWNING CT AND COLONIAL HILLS DRIVE.
 DRIVEWAY IS OFF OF COLONIAL HILLS
 DRIVE. -A.DRIGGERS

STRUCTURE: 000 000 40X65 3BR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/14/07 3/14/07	CE AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001370055 WOULD LIKE INSPECTION IN THE AM. Install French drain around left rear corner by rough-in inspection. ce
B103 01	3/26/07 3/26/07	CE AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001377084 INSTALL FOUNDATION DRAINAGE AT LEFT REAR CORNER BY NEXT INSPECTION. CE
A814 01	3/26/07 3/26/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001377076 705 colonial hills dr
P309 01	4/05/07 4/09/07	CE DA	R*PLUMB UNDER SLAB VRU #: 001384924 1) Need 3" drain on entire horizontal run of washer drain 2) Install foundation drain at left rear corner per previousinspection 3) Seal around sleeve at building drain
P309 02	4/13/07 " "	TI AP	R*PLUMB UNDER SLAB VRU #: 001388875 <i>J.H.</i> See Attached

 COMMENTS AND NOTES

Property address 705 COLONIAL HILLS DR 03
 PARCEL NUMBER 03-0507 - -0226-63-

Select View Application inquiry

Application Number	Structure/ Sequence	Permit/ Sequence	Insp/ Sequence	Inspector	Request Date	Result/ Date
06 50015963	000 000	CPNP 00	B802 0001	LYM	2/21/07	AP 2/21/07
06 50015963	000 000	CPNP 00	H800 0001	JW	11/01/06	AP 11/09/06
06 50015963	000 000	CPNP 00	H800 0002	JW	3/14/07	AP 3/06/07
06 50015963	000 000	CPSF 00	A814 0001	TI	3/26/07	AP 3/26/07
06 50015963	000 000	CPSF 00	B101 0001	CE	3/14/07	AP 3/14/07
06 50015963	000 000	CPSF 00	B103 0001	CE	3/26/07	AE 3/26/07
06 50015963	000 000	CPSF 00	P309 0001	CE	4/05/07	DA 4/09/07
06 50015963	000 000	CPSF 00	F009 0002	JH	4/13/07	AP 4/13/07

OK Exit Cancel

ADDRESS : 705 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
 CONTRACTOR : R B C HOMES, INC. PHONE : (910) 423-3555
 OWNER : RBC HOMES #45 PHONE : (910) 423-3555
 PARCEL : 03-0507- - -0226- -63-
 APPL NUMBER: 06-50015963 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 45. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. LOT IS ON CORNER
 OF DOWNING CT AND COLONIAL HILLS DRIVE.
 DRIVEWAY IS OFF OF COLONIAL HILLS
 DRIVE. -A.DRIGGERS

STRUCTURE: 000 000 40X65 3BR SFD
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/14/07 3/14/07	CE AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001370055 WOULD LIKE INSPECTION IN THE AM. Install French drain around left rear corner by rough-in inspection. ce
B103 01	3/26/07 3/26/07	CE AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001377084 INSTALL FOUNDATION DRAINAGE AT LEFT REAR CORNER BY NEXT INSPECTION. CE
A814 01	3/26/07 3/26/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001377076 705 colonial hills dr
P309 01	4/05/07 4/09/07	CE DA	R*PLUMB UNDER SLAB VRU #: 001384924 1) Need 3" drain on entire horizontal run of washer drain 2) Install foundation drain at left rear corner per previousinspection 3) Seal around sleeve at building drain
P309 02	4/13/07 4/13/07	JH AP	R*PLUMB UNDER SLAB VRU #: 001388875
B111 01	4/18/07	TI <i>AP JH</i>	R*BLDG SLAB INSP VRU #: 001391697

COMMENTS AND NOTES

TERMINIX
2911 Enterprise Ave.
Fayetteville, NC 28306
Phone #: 910-484-5195
Fax #: 910-223-0734

To: RBC

Attn: Tony

From: Ken

Date: 4-18-07

Number of Pages Including Fax Cover Sheet: _____

Re: _____

Comments: _____

04/18/2007 WED 10:28 FAX

002/006

RE: Clarification on the use of Exterra Bait System as a pre-treat sol... https://mail.insect.com/svc/printer_friendly_bottom.php?passed_ent...

From: "Carl Martin" <cmartin@ncdoi.net>
 Subject: RE: Clarification on the use of Exterra Bait System as a pre-treat solution
 Date: Fri, September 17, 2004 8:01 am
 To: vdavis@insect.com

Vern,

The intent of Section R324.1 is as you describe in the attached letter. If the NC Department of Agriculture approves a product for treatment of new structures for subterranean termite control then the product meets the intent of the code and is acceptable.

Carl Martin
 Building Code Consultant
 Engineering Division
 Office of State Fire Marshal
 N. C. Department of Insurance
 322 Chapanoke Road, Suite 200
 Raleigh, NC 27603
 PO Box 26387, Raleigh, NC 27611
 Tel: 919-661-5880 x221
 Fax: 919-662-4414

Check out our building codes on-line at www.ncbuildingcodes.com. Select "Building Codes" from that page.

-----Original Message-----

From: vdavis@insect.com [mailto:vdavis@insect.com]
 Sent: Thursday, September 16, 2004 3:34 PM
 To: Carl Martin
 Subject: Clarification on the use of Exterra Bait System as a pre-treat solution

Dear Mr. Martin,

Thanks for taking the time to discuss this matter with me today. Please find attached documentation that hopefully will assist in answering the questions posed by building inspectors regarding the use of the Exterra Termite Interception and Baiting System in residential pretreatments.

Vern Davis
 Technical Director

Attachments:

carl martin 2.doc

Size: 38 k

Type: application/msword

Info: carl martin 2.doc

Bait Pretreat validation documents.pdf

04/18/2007 WED 10:29 FAX

003/006

September 16, 2004

Mr. Carl Martin
Office of State Fire Marshal
1202 Mail Service Center
Raleigh, NC 27699-1202

Dear Mr. Martin:

I am writing to you at the request of Troy Davis, service manager at the Terminix Company office in Kill Devil Hills, NC. Mr. Davis had communicated with me several days ago that a building inspector in his area had refused to recognize Ensystem's Exterra Termite Interception and Baiting System as a valid termite pretreatment solution. This is the product that we choose to perform pre-treats with. It has an EPA registration for that purpose and is recognized by the N. C. Department of Agriculture and Consumer Services, Structural Pest Control Division as a sole source termite treatment for pre-treats, as well as, post construction treatment. As a result of this encounter, he obtained your name and described his plight to you.

I am attaching some documentation dating back to 1998 that consists of letters exchanged between Mr. Carl Falco of the Structural Pest Control Division and Mr. William Murchison of the Department of Insurance, their purpose was to clarify the use of this new technology as a "pre-treatment" for termites. You may be interested in checking the Structural Pest Control Division's website for the most current list of termite control products. The URL for that is www.ncagr.com/str-pest/Termiticide_List.html. Additionally, I am attaching a copy of the Labyrinth label, highlighted in the portion referring to termite pretreatment of new structures.

In looking at the online version of the 2002 edition of the Residential Code:

R324.1 Subterranean termite control.

Methods of protection shall be by chemical soil treatment or other methods approved by the North Carolina Department of Agriculture.

From this, I gather that if a product is on the NCDA & CS, Structural Pest Control Division's list of products registered as a sole source for termite control, then it should be allowed by any building inspector. Your help in making this more clear is greatly appreciated. We would like to be able to offer this termite treatment solution to builders and their clients without undue problems as they approach the day for obtaining their certificate of occupancy. Your assistance in this matter is greatly appreciated and will gladly supply additional information if the need arises.

Kindest regards,

Vernon H. Davis, Jr.
Technical Director
Terminix of North Carolina-Nimocks Group

04/18/2007 WED 10:29 FAX

004/006



James A. Graham
Commissioner

North Carolina
Department of Agriculture
Structural Pest Control Division

Carl E. Falco
Director

April 1, 1998

Mr. Bill Murchison
North Carolina Dept. of Insurance
Safety Services Group
410 N. Boylan Avenue
Raleigh, North Carolina 27603-1212

Dear Mr. Murchison:

The purpose of this letter is to provide you with current information concerning methods of termite protection in new construction, other than soil applied liquid termiticides, which are acceptable to this Structural Pest Control Division.

As of this date, there are three termiticide bait products registered for the prevention of subterranean termites. All of these products are acceptable under the North Carolina Structural Pest Control Rules if the licensee provides a warranty for the control of subterranean termites on the entire structure and should therefore be considered acceptable methods of termite protection under R-323.1. These products are:

- The Sentricon® Colony Elimination System using Recruit I® termite bait, EPA Registration No. 62119-272
- FirstLine® GTW Termite Bait Station, EPA Registration No. 279-3170
- Exterra® Termite Interception and Baiting System using Labyrinth® Termite Bait, EPA Registration No. 68850-2

FirstLine® GT, previously included in this group, is not labeled for prevention of subterranean termites at this time and, therefore, would not be appropriate for the protection of new construction unless already infested by termites.

If you have any questions concerning any of these products please feel free to contact me.

Sincerely,

Carl E. Falco
Director

E-mail: carl_falco@ncdemail.agr.state.nc.us

Post Office Box 27647 Raleigh, North Carolina 27611 • (919) 733-6160 FAX (919) 733-0633

An Equal Opportunity Affirmative Action Employer

04/18/2007 WED 10:33 FAX

005/006

JUL 12 2002 07:17 AM



DEPARTMENT OF INSURANCE

State of North Carolina

P.O. BOX 34987

RALEIGH, N.C. 27611

COMMISSIONER OF INSURANCE

January 14, 1998

ENGINEERING DIVISION
(919) 733-5801

Mr. Carol E. Falco
N.C. DEPARTMENT OF AGRICULTURE
Structural Pest Control Division
P.O. Box 26747
Raleigh, NC 27611

RE: VOLUME VII SECTION 323.1

Dear Mr. Falco:

This letter is in response to your letter of January 9, 1998, concerning the exception in Volume VII Section R-323.1.

After looking thru some earlier codes, I believe this exception was written to prohibit the classification, by the building official, of the slab on grade as a physical barrier to termites, such as classification would have allowed the use of a slab on grade without any soil treatment. Because of other changes in Section R-23.1 the exception is confusing.

My interpretation of Section R-323.1 is the local inspection department can and should accept any method of protection from termites approved by the North Carolina Department of Agriculture.

I plan to submit a proposed code change to eliminate the confusing wording from R-323.1.

If you have any questions, please call me.

Sincerely,
William W. Murchison

William W. Murchison, P.E.
Code Consultant

WWM/dy

AN EQUAL OPPORTUNITY/AFFIRMATIVE ACTION EMPLOYER



07-11-02 04:18

RECEIVED FROM:

9.02

04/18/2007 WED 10:34 FAX

006/006

Subterranean Termite Soil Treatment Builder's Guarantee

OMB Approval No. 2502-0525
(exp. 11/30/2008)

This form is completed by the builder.

Public reporting burden for this collection of information is estimated to average 5 minutes per response, including the time for reviewing instructions, searching existing data sources, gathering and maintaining the data needed, and completing and reviewing the collection of information. This information is mandatory and is required to obtain insurance. HUD may not collect this information, and you are not required to complete this form, unless it displays a currently valid OMB control number. Section 24 CFR 200.926(b)(3) requires that the sites for HUD insured structures must be free of termite hazards. This information collection requires a licensed Pest Control company to provide the builder a record of specific treatment information in those cases when the soil treatment method is used for prevention of subterranean termite infestation. When applicable, form HUD-NPCA-99-B must accompany the form HUD-NPCA-99-A. Builders, pest control companies, mortgage lenders, homebuyers, and HUD as a record of treatment for specific homes will use the information collected. The information is not considered confidential.

This form is submitted for proposed (new) construction cases when soil treatment for prevention of subterranean termite infestation is specified by the builder or required by the lender, the architect, FHA or VA.

This form is to be completed by the builder. This guarantee is issued by the builder to the buyer. This guarantee is not to be considered as a waiver of, or in place of, any legal rights or remedies that the buyer may have against the builder.

FHA/VA Case No.: _____
Location of Structure(s) (Street Address, or Legal Description, City, State and Zip): _____

Buyer's Name: _____

The undersigned builder hereby certifies that a State licensed or otherwise authorized pest control company (where required by State law) was contracted to treat the property at the location referenced above for subterranean termites. The builder further certifies that the contract with the pest control company required the treatment materials and methods used to be in conformance with all applicable State and Federal requirements. All work required by the contract has been completed. Where not prohibited by applicable State requirements, the buyer, for an additional fee payable to the pest control company, may extend the protection against subterranean termites. Contact the pest control company listed on the attachment for further information.

The builder hereby guarantees that, if subterranean termite infestation should occur within one year from the date of closing, the builder will ensure that a licensed or otherwise State authorized pest control company (where required by State law) or other qualified licensed pest control company will further treat as necessary in the infested area to control infestations in the structure. This further treatment will be without cost to the buyer. If permitted by State law, the buyer may contract directly, at the buyer's expense, with a pest control company to inspect the property on a periodic basis and/or use EPA registered products to control the infestation. The builder will not be responsible for guaranteeing such additional treatment. The builder further agrees to repair all damage by subterranean termites within the one-year builder's warranty period. This guarantee does not apply to additions or alterations that are made by the buyer, which affects the original structure or treatment. Examples include, but are not limited to, landscaping and mulch alterations, which disturb the treated area and create new subterranean termite hazards, or interfere with the control measures.

If within the guarantee period the builder questions the validity of a claim by the buyer, the claim will be investigated by an unbiased expert mutually agreeable to the buyer and builder. The report of the expert will be accepted as the basis for disposition of the claim. The non-prevailing party will pay the cost of any inspections made to investigate the claim. For further information, contact your State structural pest control regulatory agency.

Type of Treatment: Bait System Wood Soil (HUD-NPCA-99-B required)
Note: Appropriate treatment record must be attached and listed.

Attachments: _____

Builder's Company Name: _____ Phone No.: _____

Authorized Signaturer: _____ Date: _____

Consumer Maintenance Advisory regarding Integrated Pest Management for Prevention of Wood Destroying Insects. Information regarding prevention of wood destroying insect infestation is helpful to any property owner interested in protecting the structure from infestation. Any structure can be attacked by wood destroying insects. Particular maintenance should include measures to minimize possibilities of infestation in and around a structure. Factors which may lead to infestation from wood destroying insects include foam insulation at foundation, ground-wood contact, heavy grade, growwood against structure, insufficient ventilation, moisture, wood debris in crawl space, wood mulch, tree branches touching structures, landscape timbers, and wood rot. Should these or other such conditions exist, corrective maintenance should be taken by the owner in order to reduce the chances of infestation by wood destroying insects, and the need for treatment.

An original and one copy of this guarantee are to be prepared by the builder and sent to the lender. The lender provides one copy to the buyer at closing and includes a copy in the VA loan package or HUD insurance case binder. The builder sends one copy to the licensed pest control company which performed the treatment.

Attached is a copy of the state authorized pest control company's New Construction Subterranean Termite Soil Treatment Record, HUD-NPCA-99-B.
Warning: HUD will prosecute false claims and statements. Conviction may result in criminal and/or civil penalties. (18 U.S.C. 1001, 1010, 1012-31 U.S.C. 3729, 3922)

INSPECTION TICKET
INSPECTOR: IVR

PREPARED 5/17/07, 13:58:06
Harnett County

SUBDIV: COLONIAL HILLS
PHONE : (910) 423-3555
PHONE : (910) 423-3555

ADDRESS . . : 705 COLONIAL HILLS DR
CONTRACTOR : R B C HOMES, INC.
OWNER . . . : RBC HOMES #45
PARCEL . . . : 03-0507- - -0226- -63-
APPL NUMBER: 06-50015963 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS LOT 45. 210 RIGHT ON
RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
RD ONE MILE ON LEFT. LOT IS ON CORNER
OF DOWNING CT AND COLONIAL HILLS DRIVE.
DRIVEWAY IS OFF OF COLONIAL HILLS
DRIVE. -A.DRIGGERS

STRUCTURE: 000 000 40X65 3BR SFD
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/14/07 3/14/07	CE AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001370055 WOULD LIKE INSPECTION IN THE AM. Install French drain around left rear corner by rough-in inspection. ce
B103 01	3/26/07 3/26/07	CE AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001377084 INSTALL FOUNDATION DRAINAGE AT LEFT REAR CORNER BY NEXT INSPECTION. CE
A814 01	3/26/07 3/26/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001377076 705 colonial hills dr
P309 01	4/05/07 4/09/07	CE DA	R*PLUMB UNDER SLAB VRU #: 001384924 1) Need 3" drain on entire horizontal run of washer drain 2) Install foundation drain at left rear corner per previousinspection 3) Seal around sleeve at building drain
P309 02	4/13/07 4/13/07	JH AP	R*PLUMB UNDER SLAB VRU #: 001388875
B111 01	4/18/07 4/18/07	JH AP	R*BLDG SLAB INSP VRU #: 001391697 Need verification of termite treatment alternet method by roughin.
R425 01	5/18/07	TI	FOUR TRADE ROUGH IN VRU #: 001412055

DA-MR

COMMENTS AND NOTES

ok to S+Ins.
check hole under tub on insul.

ADDRESS : 705 COLONIAL HILLS DR
 CONTRACTOR : R B C HOMES, INC.
 OWNER : RBC HOMES #45
 PARCEL : 03-0507- - -0226- -63-
 APPL NUMBER: 06-50015963 CP NEW RESIDENTIAL (SFD)

SUBDIV: COLONIAL HILLS
 PHONE : (910) 423-3555
 PHONE : (910) 423-3555

DIRECTIONS : COLONIAL HILLS LOT 45. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. LOT IS ON CORNER
 OF DOWNING CT AND COLONIAL HILLS DRIVE.
 DRIVEWAY IS OFF OF COLONIAL HILLS
 DRIVE. -A.DRIGGERS

STRUCTURE: 000 000 40X65 3BR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/14/07 3/14/07	CE AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001370055 WOULD LIKE INSPECTION IN THE AM. Install French drain around left rear corner by rough-in inspection. ce
B103 01	3/26/07 3/26/07	CE AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001377084 INSTALL FOUNDATION DRAINAGE AT LEFT REAR CORNER BY NEXT INSPECTION. CE
A814 01	3/26/07 3/26/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001377076 705 colonial hills dr
P309 01	4/05/07 4/09/07	CE DA	R*PLUMB UNDER SLAB VRU #: 001384924 1) Need 3" drain on entire horizontal run of washer drain 2) Install foundation drain at left rear corner per previous inspection 3) Seal around sleeve at building drain
P309 02	4/13/07 4/13/07	JH AP	R*PLUMB UNDER SLAB VRU #: 001388875
B111 01	4/18/07 4/18/07	JH AP	R*BLDG SLAB INSP VRU #: 001391697 Need verification of termite treatment alternet method by roughin.
R425 01	5/18/07 5/18/07	MR DA	FOUR TRADE ROUGH IN VRU #: 001412055 fill hole under tub --OK to insul. and side
I129 01	5/22/07	TI	R*INSULATION INSPECTION VRU #: 001413970
R425 02	5/22/07	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001414002

AP-MR
AP-MR

COMMENTS AND NOTES

ADDRESS . : 705 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
CONTRACTOR : R B C HOMES, INC. PHONE : (910) 423-3555
OWNER . . : RBC HOMES #45 PHONE : (910) 423-3555
PARCEL . . : 03-0507- - -0226- -63-
APPL NUMBER: 06-50015963 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : COLONIAL HILLS LOT 45. 210 RIGHT ON
RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
RD ONE MILE ON LEFT. LOT IS ON CORNER
OF DOWNING CT AND COLONIAL HILLS DRIVE.
DRIVEWAY IS OFF OF COLONIAL HILLS
DRIVE. -A.DRIGGERS

STRUCTURE: 000 000 40X65 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/14/07 3/14/07	CE AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001370055 WOULD LIKE INSPECTION IN THE AM. Install French drain around left rear corner by rough-in inspection. ce
B103 01	3/26/07 3/26/07	CE AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001377084 INSTALL FOUNDATION DRAINAGE AT LEFT REAR CORNER BY NEXT INSPECTION. CE
A814 01	3/26/07 3/26/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001377076 ✓705 colonial hills dr
P309 01	4/05/07 4/09/07	CE DA	R*PLUMB UNDER SLAB VRU #: 001384924 1) Need 3" drain on entire horizontal run of washer drain 2) Install foundation drain at left rear corner per previousinspection 3) Seal around sleeve at building drain
P309 02	4/13/07 4/13/07	JH AP	R*PLUMB UNDER SLAB VRU #: 001388875
B111 01	4/18/07 4/18/07	JH AP	R*BLDG SLAB INSP VRU #: 001391697 Need verification of termite treatment alternet method by roughin.
R425 01	5/18/07 5/18/07	MR DA	FOUR TRADE ROUGH IN VRU #: 001412055 fill hole under tub --OK to insul. and side
I129 01	5/22/07 5/22/07	MR AP	R*INSULATION INSPECTION VRU #: 001413970
R425 02	5/22/07 5/22/07	MR AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001414002
H824 01	5/23/07 5/23/07	JW AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001416957
R429 01	6/29/07	TI	FOUR TRADE FINAL VRU #: 001437656

DA-MR

COMMENTS AND NOTES

ADDRESS . : 705 COLONIAL HILLS DR SUBDIV: COLONIAL HILLS
 CONTRACTOR : R B C HOMES, INC. PHONE : (910) 423-3555
 OWNER . . : RBC HOMES #45 PHONE : (910) 423-3555
 PARCEL . . : 03-0507- - -0226- -63-
 APPL NUMBER: 06-50015963 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 45. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. LOT IS ON CORNER
 OF DOWNING CT AND COLONIAL HILLS DRIVE.
 DRIVEWAY IS OFF OF COLONIAL HILLS
 DRIVE. -A.DRIGGERS

STRUCTURE: 000 000 40X65 3BR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/14/07 3/14/07	CE AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001370055 WOULD LIKE INSPECTION IN THE AM. Install French drain around left rear corner by rough-in inspection. ce
B103 01	3/26/07 3/26/07	CE AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001377084 INSTALL FOUNDATION DRAINAGE AT LEFT REAR CORNER BY NEXT INSPECTION. CE
A814 01	3/26/07 3/26/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001377076 ✓705 colonial hills dr
P309 01	4/05/07 4/09/07	CE DA	R*PLUMB UNDER SLAB VRU #: 001384924 1) Need 3" drain on entire horizontal run of washer drain 2) Install foundation drain at left rear corner per previousinspection 3) Seal around sleeve at building drain
P309 02	4/13/07 4/13/07	JH AP	R*PLUMB UNDER SLAB VRU #: 001388875
B111 01	4/18/07 4/18/07	JH AP	R*BLDG SLAB INSP VRU #: 001391697 Need verification of termite treatment alternet method by roughin.
R425 01	5/18/07 5/18/07	MR DA	FOUR TRADE ROUGH IN VRU #: 001412055 fill hole under tub --OK to insul. and side
I129 01	5/22/07 5/22/07	MR AP	R*INSULATION INSPECTION VRU #: 001413970
R425 02	5/22/07 5/22/07	MR AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001414002
H824 01	5/23/07 5/23/07	JW AP	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001416957
R429 01	6/29/07 6/29/07	MR DA	FOUR TRADE FINAL VRU #: 001437656 1. no house numbers 2. caulk around toilets 3. bath fans not installed 4. no a/c vent in kitchen 5. handrail at front steps will not support 200# 6. neutral not bonded to ground at main 7. caulk around exposed romex behind the AC disconnect and wire the ac condenser 8. grading must slope away from house
R429 02	7/02/07	TI CA-MR	FOUR TRADE FINAL VRU #: 001439116

ADDRESS : 705 COLONIAL HILLS DR
 SUBDIV: COLONIAL HILLS
 CONTRACTOR : R B C HOMES, INC. PHONE : (910) 423-3555
 OWNER : RBC HOMES #45 PHONE : (910) 423-3555
 PARCEL : 03-0507- - -0226- -63-
 APPL NUMBER: 06-50015963 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : COLONIAL HILLS LOT 45. 210 RIGHT ON
 RAY RD RIGHT ON NURSERY RD LEFT ON DOCS
 RD ONE MILE ON LEFT. LOT IS ON CORNER
 OF DOWNING CT AND COLONIAL HILLS DRIVE.
 DRIVEWAY IS OFF OF COLONIAL HILLS
 DRIVE. -A.DRIGGERS

STRUCTURE: 000 000 40X65 3BR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	3/14/07 3/14/07	CE AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001370055 WOULD LIKE INSPECTION IN THE AM. Install French drain around left rear corner by rough-in inspection. ce
B103 01	3/26/07 3/26/07	CE AE	R*BLDG FOUND & TEMP SVC POLE VRU #: 001377084 INSTALL FOUNDATION DRAINAGE AT LEFT REAR CORNER BY NEXT INSPECTION. CE
A814 01	3/26/07 3/26/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001377076 705 colonial hills dr
P309 01	4/05/07 4/09/07	CE DA	R*PLUMB UNDER SLAB VRU #: 001384924 1) Need 3" drain on entire horizontal run of washer drain 2) Install foundation drain at left rear corner per previous inspection 3) Seal around sleeve at building drain
P309 02	4/13/07 4/13/07	JH AP	R*PLUMB UNDER SLAB VRU #: 001388875
B111 01	4/18/07 4/18/07	JH AP	R*BLDG SLAB INSP VRU #: 001391697 Need verification of termite treatment alternet method by roughin.
R425 01	5/18/07 5/18/07	MR DA	FOUR TRADE ROUGH IN VRU #: 001412055 fill hole under tub --OK to insul. and side
I129 01	5/22/07 5/22/07	MR AP	R*INSULATION INSPECTION VRU #: 001413970
R425 02	5/22/07 5/22/07	MR AP	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001414002
H824 01	5/23/07 5/23/07	JW AP	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001416957
R429 01	6/29/07 6/29/07	MR DA	FOUR TRADE FINAL VRU #: 001437656 1. no house numbers 2. caulk around toilets 3. bath fans not installed 4. no a/c vent in kitchen 5. handrail at front steps will not support 200# 6. neutral not bonded to ground at main 7. caulk around exposed romex behind the AC disconnect and wire the ac condenser 8. grading must slope away from house
R429 02	7/02/07 7/02/07	TI CA	FOUR TRADE FINAL VRU #: 001439116
R429 03	7/03/07	TI	FOUR TRADE FINAL VRU #: 001439843

AP-MR

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: <u>Res.</u>	Conditional Use Permit No.: _____
Type of Construction: <u>II</u>	Building Permit No.: <u>06-50019963</u>
Owner of Building: <u>RBC</u>	Electrical Permit No.: <u>"</u>
Building Address: <u>705 Colonial Hills</u>	Insulation Permit No.: <u>11</u>
Zoning District: _____	Plumbing Permit No.: <u>11</u>
Zoning Permit No.: _____	Mech. Permit No.: <u>11</u>
Date: <u>7-3-7</u>	Envir. C.O. No.: _____
<u>Walter Renna</u> Building Official	_____ Zoning Official