
ADDRESS . : 202 BENDAMOORE CT
CONTRACTOR : CURRIN BUILDERS INC
OWNER . . : CURRIN BUILDERS #28
PARCEL . . : 08-0653- - -0030- -28-
APPL NUMBER: 07-50016567 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : DEXTERFIELD LOT 28. TAKE 401 TO FUQUAY
LEFT ON CHALYBEATE RD GO 1/2 MILE LEFT
INTO SUBDIVISION. LOT ON BENDAMOORE
CT. -A.DRIGGERS

STRUCTURE: 000 000 56X50 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440159
	7/03/07	AP	
B103 01	7/10/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001442825
	<u>7/10/07</u>	<u>DA DT</u>	

----- COMMENTS AND NOTES -----

ADDRESS . . : 202 BRENDAMOORE CT
 CONTRACTOR : CURRIN BUILDERS INC
 OWNER . . . : CURRIN BUILDERS #28
 PARCEL . . . : 08-0653- - -0030- -28-
 APPL NUMBER: 07-50016567 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : DEXTERFIELD LOT 28. TAKE 401 TO FUQUAY
 LEFT ON CHALYBEATE RD GO 1/2 MILE LEFT
 INTO SUBDIVISION. LOT ON BRENDAMOORE
 CT. -A.DRIGGERS

SUBDIV: DEXTERFIELD
 PHONE : (919) 639-6989
 PHONE : (919) 639-6989

STRUCTURE: 000 000 56X50 3BR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440159
	7/03/07	AP	
B103 01	7/10/07	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001442825
	7/10/07	DA	Two inch projection not met in areas identified on plans. Piers not on center third of footers identified on plans. Add cement tied in by rebar or get an engineer report addressing necessary areas.
B103 02	7/11/07	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001444011
	<u>7-11-07</u>	<u>ADBS</u>	

----- COMMENTS AND NOTES -----

Linda - 910-864-8787

Wanna in Kipling

ADDRESS . : 202 BRENAMOORE CT SUBDIV: DEXTERFIELD
CONTRACTOR : CURRIN BUILDERS INC PHONE : (919) 639-6989
OWNER . . : CURRIN BUILDERS #28 PHONE : (919) 639-6989
PARCEL . . : 08-0653- - -0030- -28-
APPL NUMBER: 07-50016567 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : DEXTERFIELD LOT 28. TAKE 401 TO FUQUAY
LEFT ON CHALYBEATE RD GO 1/2 MILE LEFT
INTO SUBDIVISION. LOT ON BRENAMOORE
CT. -A.DRIGGERS

STRUCTURE: 000 000 56X50 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440159
	7/03/07	AP	
B103 01	7/10/07	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001442825
	7/10/07	DA	Two inch projection not met in areas identified on plans. Piers not on center third of footers identified on plans. Add cement tied in by rebar or get an engineer report addressing necessary areas.
B103 02	7/11/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001444011
	7/11/07	AP	
B105 01	7/13/07	TI	R*OPEN FLOOR VRU #: 001445136
	<u>7.13.07</u>	<u>AEBS</u>	

----- COMMENTS AND NOTES -----

ADDRESS . : 202 BENDAMOORE CT SUBDIV: DEXTERFIELD
CONTRACTOR : CURRIN BUILDERS INC PHONE : (919) 639-6989
OWNER . . : CURRIN BUILDERS #28 PHONE : (919) 639-6989
PARCEL . . : 08-0653- - -0030- -28-
APPL NUMBER: 07-50016567 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : DEXTERFIELD LOT 28. TAKE 401 TO FUQUAY
LEFT ON CHALYBEATE RD GO 1/2 MILE LEFT
INTO SUBDIVISION. LOT ON BENDAMOORE
CT. -A.DRIGGERS

STRUCTURE: 000 000 56X50 3BR SFD
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440159
	7/03/07	AP	
B103 01	7/10/07	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001442825
	7/10/07	DA	Two inch projection not met in areas identified on plans. Piers not on center third of footers identified on plans. Add cement tied in by rebar or get an engineer report addressing necessary areas.
B103 02	7/11/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001444011
	7/11/07	AP	
B105 01	7/13/07	BS	R*OPEN FLOOR VRU #: 001445136
	7/13/07	AE	1. Install nuts and washers on greenplate to right of front porch. 2. Double missing behind garage wall. 3. Need hangers at joist to double connection over access hole. Will check at rough in
A814 01	7/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001444020
	7/24/07	AP	202 BRendermoore Ct Lot 28
R425 01	8/14/07	TI	FOUR TRADE ROUGH IN VRU #: 001466648

8.14.07 DABS

----- COMMENTS AND NOTES -----

ADDRESS . : 202 BRENDAMOORE CT SUBDIV: DEXTERFIELD
 CONTRACTOR : CURRIN BUILDERS INC PHONE : (919) 639-6989
 OWNER . . : CURRIN BUILDERS #28 PHONE : (919) 639-6989
 PARCEL . . : 08-0653- - -0030- -28-
 APPL NUMBER: 07-50016567 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : DEXTERFIELD LOT 28. TAKE 401 TO FUQUAY
 LEFT ON CHALYBEATE RD GO 1/2 MILE LEFT
 INTO SUBDIVISION. LOT ON BRENDAMOORE
 CT. -A.DRIGGERS

STRUCTURE: 000 000 56X50 3BR SFD
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440159
	7/03/07	AP	
B103 01	7/10/07	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001442825
	7/10/07	DA	Two inch projection not met in areas identified on plans. Piers not on center third of footers identified on plans. Add cement tied in by rebar or get an engineer report addressing necessary areas.
B103 02	7/11/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001444011
	7/11/07	AP	
B105 01	7/13/07	BS	R*OPEN FLOOR VRU #: 001445136
	7/13/07	AE	1. Install nuts and washers on greenplate to right of front porch. 2. Double missing behind garage wall. 3. Need hangers at joist to double connection over access hole. Will check at rough in
A814 01	7/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001444020
	7/24/07	AP	202 BRendermoore Ct Lot 28
R425 01	8/14/07	BS	FOUR TRADE ROUGH IN VRU #: 001466648
	8/14/07	DA	1. Rodent proof 2. HVAC nail plates 3. Apply missing firecaulk 4. Attic kneewall to support all rafters and have brace 5. Leak at kitchen to 3"drain connection. ok to side/insulate
I129 01	8/20/07	TI	R*INSULATION INSPECTION VRU #: 001469850
	<u>8/20/07</u>	<u>APBS</u>	
R425 02	8/20/07	TI	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001470236
	<u>8/20/07</u>	<u>TI</u>	

COMMENTS AND NOTES

ADDRESS : 202 BRENDAMOORE CT SUBDIV: DEXTERFIELD
 CONTRACTOR : CURRIN BUILDERS INC PHONE : (919) 639-6989
 OWNER : CURRIN BUILDERS #28 PHONE : (919) 639-6989
 PARCEL : 08-0653- - -0030- -28-
 APPL NUMBER: 07-50016567 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : DEXTERFIELD LOT 28. TAKE 401 TO FUQUAY
 LEFT ON CHALYBEATE RD GO 1/2 MILE LEFT
 INTO SUBDIVISION. LOT ON BRENDAMOORE
 CT. -A.DRIGGERS

STRUCTURE: 000 000 56X50 3BR SFD
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440159
	7/03/07	AP	
B103 01	7/10/07	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001442825
	7/10/07	DA	Two inch projection not met in areas identified on plans. Piers not on center third of footers identified on plans. Add cement tied in by rebar or get an engineer report addressing necessary areas.
B103 02	7/11/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001444011
	7/11/07	AP	
B105 01	7/13/07	BS	R*OPEN FLOOR VRU #: 001445136
	7/13/07	AE	1. Install nuts and washers on greenplate to right of front porch. 2. Double missing behind garage wall. 3. Need hangers at joist to double connection over access hole. Will check at rough in
A814 01	7/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001444020
	7/24/07	AP	202 Barendamoore Ct Lot 28
R425 01	8/14/07	BS	FOUR TRADE ROUGH IN VRU #: 001466648
	8/14/07	DA	1. Rodent proof 2. HVAC nail plates 3. Apply missing firecaulk 4. Attic kneewall to support all rafters and have brace 5. Leak at kitchen to 3" drain connection. ok to side/insulate
I129 01	8/20/07	BS	R*INSULATION INSPECTION VRU #: 001469850
	8/20/07	AP	
R425 02	8/20/07	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001470236
	8/20/07	AP	
H824 01	11/16/07	JM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001522168
	11/16/07	AP	
R225 01	4/08/08	TI	TWO TRADE ROUGH IN VRU #: 001589365
	4/08/08	CA	ROUGH IN FOR BOUNS ROOM AREA
R429 01	4/11/08	TI	FOUR TRADE FINAL VRU #: 001589290

DA-M/R

COMMENTS AND NOTES

Hand Rail

ADDRESS : 202 BRENDAMOORE CT
 CONTRACTOR : CURRIN BUILDERS INC
 OWNER : CURRIN BUILDERS #28
 PARCEL : 08-0653- - -0030- -28-
 APPL NUMBER: 07-50016567 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : DEXTERFIELD LOT 28. TAKE 401 TO FUQUAY
 LEFT ON CHALYBEATE RD GO 1/2 MILE LEFT
 INTO SUBDIVISION. LOT ON BRENDAMOORE
 CT. -A.DRIGGERS
 PREMISE# 06647697

SUBDIV: DEXTERFIELD
 PHONE : (919) 639-6989
 PHONE : (919) 639-6989

STRUCTURE: 000 000 56X50 3BR SFD
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	7/03/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001440159
	7/03/07	AP	
B103 01	7/10/07	DT	R*BLDG FOUND & TEMP SVC POLE VRU #: 001442825
	7/10/07	DA	Two inch projection not met in areas identified on plans. Piers not on center third of footers identified on plans. Add cement tied in by rebar or get an engineer report addressing necessary areas.
B103 02	7/11/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001444011
	7/11/07	AP	
B105 01	7/13/07	BS	R*OPEN FLOOR VRU #: 001445136
	7/13/07	AE	1. Install nuts and washers on greenplate to right of front porch. 2. Double missing behind garage wall. 3. Need hangers at joist to double connection over access hole. Will check at rough in
A814 01	7/16/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001444020
	7/24/07	AP	202 Brendamoore Ct Lot 28
R425 01	8/14/07	BS	FOUR TRADE ROUGH IN VRU #: 001466648
	8/14/07	DA	1. Rodent proof 2. HVAC nail plates 3. Apply missing firecaulk 4. Attic kneewall to support all rafters and have brace 5. Leak at kitchen to 3"drain connection. ok to side/insulate
I129 01	8/20/07	BS	R*INSULATION INSPECTION VRU #: 001469850
	8/20/07	AP	
R425 02	8/20/07	BS	FOUR TRADE ROUGH IN TIME: 17:00 VRU #: 001470236
	8/20/07	AP	
H824 01	11/16/07	JM	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001522168
	11/16/07	AP	
R225 01	4/08/08	TI	TWO TRADE ROUGH IN VRU #: 001589365
	4/08/08	CA	ROUGH IN FOR BOUNS ROOM AREA
R429 01	4/11/08	MR	FOUR TRADE FINAL VRU #: 001589290
	4/11/08	DA	hand rail needed at front steps
R429 02	4/15/08	TI	FOUR TRADE FINAL VRU #: 001593227

4-15-08 APBS

COMMENTS AND NOTES

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: SFD
Type of Construction: IV
Owner of Building: Current Builders
Building Address: 202 Boardman Court
Zoning District: _____
Zoning Permit No.: N/A
Date: 4-15-08
Brad Sutter
Building Official

Conditional Use Permit No.: _____
Building Permit No.: _____
Electrical Permit No.: _____
Insulation Permit No.: _____
Plumbing Permit No.: _____
Mech. Permit No.: 07-5-16507
Envir. C.O. No.: _____
Zoning Official