

ADDRESS : 10 ALVIS CT SUBDIV: DEXTERFIELD
CONTRACTOR : RAYNOR BUILDERS INC PHONE : (919) 639-3012
OWNER : ATKINS PLACE LLC #52 PHONE :
PARCEL : 08-0653- - -0030- -52-
APPL NUMBER: 07-50016994 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : 401 N 6 MILES LEFT ON CHALYBEATS RD S/D
IS 1/4 MILE ON LEFT LOT 52 JB
T/S: 11/06/2012 12:46 PM VBROWN ----
PREMIS NUMBER 18458055

STRUCTURE: 000 000 55X60 3BDR
FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : SEWER

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/26/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001632647
	6/26/08	AP	
B103 01	7/24/08	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001648070
	7/24/08	AE	damproof and leave open
A814 01	7/24/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001648054
	7/25/08	AP	10 ALVIS CT LOT 52
E207 01	11/06/12	BS	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002299857
	11/06/12	AP	T/S: November 06, 2012 11:27 AM BSUTTON ----- no premise number
B105 01	11/16/12	BS	R*OPEN FLOOR VRU #: 002302920
	11/16/12	AE	T/S: November 16, 2012 08:53 AM BSUTTON ----- Rear porch band must be through bolted to house band. Ok to cover floor on house and frame, do not cover rear porch band before rough ins
R425 01	11/30/12	BS	FOUR TRADE ROUGH IN VRU #: 002310100
	11/30/12	DA	T/S: November 30, 2012 01:48 PM BSUTTON ----- Roofing must be installed for rough in inspection, as well as all roof flashing. No inspection done
R425 02	12/04/12	BS	FOUR TRADE ROUGH IN VRU #: 002311288
	12/04/12	DA	T/S: December 04, 2012 11:16 AM BSUTTON ----- Repair floor joist cut for plumbing. 2.No uplift on girder truss at front of house. 3. Front bedroom has no window that meets egress requirements.
R425 03	12/14/12	KS	FOUR TRADE ROUGH IN VRU #: 002316283
	12/14/12	AP	T/S: 12/14/2012 02:21 PM KSLATTUM -----
I129 01	12/18/12	BS	R*INSULATION INSPECTION VRU #: 002317558
	12/18/12	AP	T/S: December 18, 2012 09:53 AM BSUTTON -----
H824 01	1/11/13	BM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002327641
	1/11/13	AP	T/S: 01/15/2013 10:30 AM SSTEWARD ----- T/S: 01/15/2013 10:30 AM SSTEWARD -----
E209 01	2/13/13	BS	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002338150
	2/13/13	AP	T/S: February 13, 2013 02:06 PM BSUTTON -----
R429 01	3/07/13	TI	FOUR TRADE FINAL VRU #: 002348169

3-7-3 DAB

COMMENTS AND NOTES

ADDRESS : 10 ALVIS CT SUBDIV: DEXTERFIELD
 CONTRACTOR : RAYNOR BUILDERS INC PHONE : (919) 639-3012
 OWNER : ATKINS PLACE LLC #52 PHONE :
 PARCEL : 08-0653- - -0030- -52-
 APPL NUMBER: 07-50016994 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : 401 N 6 MILES LEFT ON CHALYBEATS RD S/D
 IS 1/4 MILE ON LEFT LOT 52 JB
 T/S: 11/06/2012 12:46 PM VBROWN ----
 PREMIS NUMBER 18458055

STRUCTURE: 000 000 55X60 3BDR
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : SEWER

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	6/26/08	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001632647
	6/26/08	AP	
B103 01	7/24/08	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001648070
	7/24/08	AE	damp proof and leave open
A814 01	7/24/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001648054
	7/25/08	AP	10 ALVIS CT LOT 52
E207 01	11/06/12	BS	R*ELEC TEMP SERVICE POLE TIME: 17:00 VRU #: 002299857
	11/06/12	AP	T/S: November 06, 2012 11:27 AM BSUTTON ----- no premise number
B105 01	11/16/12	BS	R*OPEN FLOOR VRU #: 002302920
	11/16/12	AE	T/S: November 16, 2012 08:53 AM BSUTTON ----- Rear porch band must be through bolted to house band. Ok to cover floor on house and frame, do not cover rear porch band before rough ins
R425 01	11/30/12	BS	FOUR TRADE ROUGH IN VRU #: 002310100
	11/30/12	DA	T/S: November 30, 2012 01:48 PM BSUTTON ----- Roofing must be installed for rough in inspection, as well as all roof flashing. No inspection done
R425 02	12/04/12	BS	FOUR TRADE ROUGH IN VRU #: 002311288
	12/04/12	DA	T/S: December 04, 2012 11:16 AM BSUTTON ----- Repair floor joist cut for plumbing. 2.No uplift on girder truss at front of house. 3. Front bedroom has no window that meets egress requirements.
R425 03	12/14/12	KS	FOUR TRADE ROUGH IN VRU #: 002316283
	12/14/12	AP	T/S: 12/14/2012 02:21 PM KSLATTUM -----
I129 01	12/18/12	BS	R*INSULATION INSPECTION VRU #: 002317558
	12/18/12	AP	T/S: December 18, 2012 09:53 AM BSUTTON -----
H824 01	1/11/13	BM	ENVR. OPERATIONS PERMIT TIME: 17:00 VRU #: 002327641
	1/11/13	AP	T/S: 01/15/2013 10:30 AM SSTEWARD ----- T/S: 01/15/2013 10:30 AM SSTEWARD -----
E209 01	2/13/13	BS	R*ELEC TEMP POWER CERT TIME: 17:00 VRU #: 002338150
	2/13/13	AP	T/S: February 13, 2013 02:06 PM BSUTTON -----
R429 01	3/07/13	BS	FOUR TRADE FINAL VRU #: 002348169
	3/07/13	DA	T/S: March 07, 2013 01:10 PM BSUTTON ----- Doors locked. No code for realtor lock. Please leave the code for the inspector if doors will be locked

PREPARED 3/08/13, 14:05:45
Harnett County

INSPECTION TICKET
INSPECTOR: IVR

PAGE 2
DATE 3/11/13

ADDRESS . . : 10 ALVIS CT
CONTRACTOR : RAYNOR BUILDERS INC
OWNER . . : ATKINS PLACE LLC #52
PARCEL . . : 08-0653- - -0030- -52-
APPL NUMBER: 07-50016994 CP NEW RESIDENTIAL (SFD)

SUBDIV: DEXTERFIELD
PHONE : (919) 639-3012
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 02	3/11/13 <u>3-11-13</u>	TI <u>DABS</u>	FOUR TRADE FINAL TIME: 17:00 VRU #: 002349702 T/S: 03/08/2013 11:26 AM DJOHNSON

COMMENTS AND NOTES