

Code:

☐ Mixed[illegible]

Description	Initial System	Repair System
available Space (.1945)	✓	✓
ystem Type(s)	CON	CON
ite LTAR	7	7

Others Present:

- VERIFY LAYOUT AFTER LOT CLEARED


COMMENTS: _____

LANDSCAPE POSITIONS	GROUP	TEXTURES	.1955 LTAR	CONSISTENCE MOIST	WET
R-RIDGE	I	S-SAND	1.2 - 0.8	VFR-VERY FRIABLE	NS-NON-STICKY
S-SHOULDER SLOPE		LS-LOAMY SAND			
L-LINEAR SLOPE	II	SL-SANDY LOAM	0.8 - 0.6	FR-FRIABLE	SS-SLIGHTLY STICKY
FS-FOOT SLOPE		L-LOAM			
N-NOSE SLOPE	III	SI-SILT-	0.6 - 0.3	FI-FIRM	S-STICKY
H-HEAD SLOPE		SIL-SILT LOAM			
CC-CONCLAVE SLOPE		CL-CLAY LOAM			
CV-CONVEX SLOPE		SCL-SANDY CLAY LOAM			
T-TERRACE		SICL-SILTY CLAY LOAM			
FP-FLOOD PLAN					
	IV	SIC-SILTY CLAY	0.4 - 0.1	EFI-EXTREMELY FIRM	VS-VERY STICKY
		C-CLAY			
		SC-SANDY CLAY			

STRUCTURE
 SG-SINGLE GRAIN
 M-MASSIVE
 CR-CRUMB
 GR-GRANULAR
 SBK-SUBANGULAR BLOCKY
 ABK-ANGULAR BLOCKY
 PL-PLATY
 PR-PRISMATIC

MINERALOGY
 SLIGHTLY EXPANSIVE
 EXPANSIVE

Show profile locations and other site features (dimensions, reference or benchmark, and North).



SECTION

NURSERY RD. (60' R/W)

10x70 SIGHT TRIANGLE (TYP.)

PARKVIEW

LANE

SPR
TOL
NER

SITE PLAN APPROVAL

DISTRICT Area 2 USE SED

#BEDROOMS 4

Date

Zoning Administrator

19074 S.F.±
(0.46 AC.±)

16242 S.F.±
(0.37 AC.±)

15590 S.F.±
(0.35 AC.±)

15662 S.F.±
(0.36 AC.±)

15872 S.F.±
(0.36 AC.±)

15727 S.F.±
(0.36 AC.±)

NIS

S 89°55'20" E

N 61°4'12" W

81.78'

89.61'

85.47'

185.42'

88.76'

16242 S.F.±
(0.37 AC.±)

15590 S.F.±
(0.35 AC.±)

19074 S.F.±
(0.46 AC.±)

16242 S.F.±
(0.37 AC.±)

15590 S.F.±
(0.35 AC.±)

15662 S.F.±
(0.36 AC.±)

15872 S.F.±
(0.36 AC.±)

15727 S.F.±
(0.36 AC.±)

NIS

S 89°55'20" E

N 61°4'12" W

81.78'

89.61'

85.47'

185.42'

88.76'

16242 S.F.±
(0.37 AC.±)

15590 S.F.±
(0.35 AC.±)

19074 S.F.±
(0.46 AC.±)

16242 S.F.±
(0.37 AC.±)

15590 S.F.±
(0.35 AC.±)

15662 S.F.±
(0.36 AC.±)

15872 S.F.±
(0.36 AC.±)

15727 S.F.±
(0.36 AC.±)