

ADDRESS : 110 ALVIS CT
CONTRACTOR : RAYNOR BUILDERS INC
OWNER : ATKINS PLACE LLC
PARCEL : 08-0653- - -0030- -46-
APPL NUMBER: 07-50018756 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 401 N 8 MILE TURN LEFT ON CHALYBEATE
S/D IS ON LEFT LOT 46 JB

SUBDIV: DEXTERFIELD
PHONE : (919) 639-3012
PHONE :

STRUCTURE: 000 000 50X60 4BDR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/07 <u>11-14</u>	TI <u>DA</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001519985

----- COMMENTS AND NOTES -----

ADDRESS . . : 110 ALVIS CT SUBDIV: DEXTERFIELD
CONTRACTOR : RAYNOR BUILDERS INC PHONE : (919) 639-3012
OWNER . . . : ATKINS PLACE LLC PHONE :
PARCEL . . . : 08-0653- - -0030- -46-
APPL NUMBER: 07-50018756 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 401 N 8 MILE TURN LEFT ON CHALYBEATE
S/D IS ON LEFT LOT 46 JB

STRUCTURE: 000 000 50X60 4BDR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/07 11/14/07	KS DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001519985 Soil not suitable for footing. Need engineers corection prior to pouring,
B101 02	11/20/07 <u>11-20-07</u>	TI <u>APBS</u>	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001522622 premis # 76813663 for temp power

----- COMMENTS AND NOTES -----

W-L Soil Testing

Date: 11-20-07			Bill to: RAYMOND BLDGS			
Project #:			Address: RAYMOND BLDGS			
Telephone #:			City, State, Zip:			
County: HENRIT			Made for: RAYMOND BLDGS			
Temperature:			Weather:			
Mileage Out	Mileage in	Total Miles	Time Out	Time in	Total Time	Crew #

Re inspecting Lot 46 at
 Dexter Field Rd, Found that
 Footing had been under cut to
 Recommended depth & Back Filled
 with F 57 stone
 Wm L
 FOR JORDAN TOWN

ADDRESS . . : 110 ALVIS CT
CONTRACTOR : RAYNOR BUILDERS INC
OWNER . . . : ATKINS PLACE LLC
PARCEL . . . : 08-0653- - -0030- -46-
APPL NUMBER: 07-50018756 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 401 N 8 MILE TURN LEFT ON CHALYBEATE
S/D IS ON LEFT LOT 46 JB

SUBDIV: DEXTERFIELD
PHONE : (919) 639-3012
PHONE :

STRUCTURE: 000 000 50X60 4BDR

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 4.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/07 11/14/07	KS DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001519985 Soil not suitable for footing. Need engineers corection prior to pouring,
B101 02	11/20/07 11/20/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001522622 premis # 76813663 for temp power
A814 01	11/29/07	TI	ADDRESS CONFIRMATION VRU #: 001526748
B103 01	11/29/07 <u>11-29-07</u>	TI <u>APBS</u>	R*BLDG FOUND & TEMP SVC POLE VRU #: 001526755

----- COMMENTS AND NOTES -----

ADDRESS : 110 ALVIS CT
CONTRACTOR : RAYNOR BUILDERS INC
OWNER : ATKINS PLACE LLC
PARCEL : 08-0653- - -0030- -46-
APPL NUMBER: 07-50018756 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : 401 N 8 MILE TURN LEFT ON CHALYBEATE
S/D IS ON LEFT LOT 46 JB

SUBDIV: DEXTERFIELD
PHONE : (919) 639-3012
PHONE :

STRUCTURE: 000 000 50X60 4BDR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/07 11/14/07	KS DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001519985 Soil not suitable for footing. Need engineers corection prior to pouring,
B101 02	11/20/07 11/20/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001522622 premis # 76813663 for temp power
B103 01	11/29/07 11/29/07	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001526755 be sure to remove all organics from crawl space.
A814 01	11/29/07 11/29/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001526748 110 ALVIS CT
B105 01	12/03/07	TI	R*OPEN FLOOR VRU #: 001528298

12-3-07 APB

COMMENTS AND NOTES

ADDRESS . : 110 ALVIS CT
 CONTRACTOR : RAYNOR BUILDERS INC
 OWNER . . : ATKINS PLACE LLC
 PARCEL . . : 08-0653- - -0030- -46-
 APPL NUMBER: 07-50018756 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 401 N 8 MILE TURN LEFT ON CHALYBEATE
 S/D IS ON LEFT LOT 46 JB

SUBDIV: DEXTERFIELD
 PHONE : (919) 639-3012
 PHONE :

STRUCTURE: 000 000 50X60 4BDR
 FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/07 11/14/07	KS DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001519985 Soil not suitable for footing. Need engineers corection prior to pouring,
B101 02	11/20/07 11/20/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001522622 premis # 76813663 for temp power
B103 01	11/29/07 11/29/07	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001526755 be sure to remove all organics from crawl space.
A814 01	11/29/07 11/29/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001526748 110 ALVIS CT
B105 01	12/03/07 12/03/07	BS AP	R*OPEN FLOOR VRU #: 001528298
H824 01	12/10/07 12/10/07	BM DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001533785 BRYAN WROTE OP FOR WRONG LOT #, THEREFORE LOT 46 WAS FINALED IN ERROR. ADDED ENVH OPERATIONS STEP TODAY TO CORRECT THIS AND ALSO DELETED THE OP THAT WAS SCANNED UNDER THE SAME HTE # FOR LOT 46.
H824 02	12/14/07	TI	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001535723
R427 02	12/21/07 12/21/07	BS CA	FOUR TRADE ROUGH IN >2500 VRU #: 001539204 Can you come after 2 p.m. If not reschedule for thursday. Thanks (Merry Christmas) Craig
R427 01	12/21/07 12/21/07	BS CA	FOUR TRADE ROUGH IN >2500 VRU #: 001539196 Can you come after 2 p.m. If not reschedule for thursday. Thanks (Merry Christmas) Craig
R427 03	12/28/07 <u>12-28-07</u>	TI <u>DABS</u>	FOUR TRADE ROUGH IN >2500 VRU #: 001540178

COMMENTS AND NOTES

ADDRESS : 110 ALVIS CT
 CONTRACTOR : RAYNOR BUILDERS INC
 OWNER : ATKINS PLACE LLC
 PARCEL : 08-0653- - -0030- -46-
 APPL NUMBER: 07-50018756 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 401 N 8 MILE TURN LEFT ON CHALYBEATE
 S/D IS ON LEFT LOT 46 JB

SUBDIV: DEXTERFIELD
 PHONE : (919) 639-3012
 PHONE :

STRUCTURE: 000 000 50X60 4BDR

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 4.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/07	KS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001519985
	11/14/07	DA	Soil not suitable for footing. Need engineers corection prior to pouring,
B101 02	11/20/07	BS	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001522622
	11/20/07	AP	premis # 76813663 for temp power
B103 01	11/29/07	BS	R*BLDG FOUND & TEMP SVC POLE VRU #: 001526755
	11/29/07	AP	be sure to remove all organics from crawl space.
A814 01	11/29/07	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001526748
	11/29/07	AP	110 ALVIS CT
B105 01	12/03/07	BS	R*OPEN FLOOR VRU #: 001528298
	12/03/07	AP	
H824 01	12/10/07	BM	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001533785
	12/10/07	DA	BRYAN WROTE OP FOR WRONG LOT #, THEREFORE LOT 46 WAS FINALED IN ERROR. ADDED ENVH OPERATIONS STEP TODAY TO CORRECT THIS AND ALSO DELETED THE OP THAT WAS SCANNED UNDER THE SAME HTE # FOR LOT 46.
H824 02	12/14/07	TI	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001535723
R427 02	12/21/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001539204
	12/21/07	CA	Can you come after 2 p.m. If not reschedule for thursday. Thanks (Merry Christmas) Craig
R427 01	12/21/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001539196
	12/21/07	CA	Can you come after 2 p.m. If not reschedule for thursday. Thanks (Merry Christmas) Craig
R427 03	12/28/07	BS	FOUR TRADE ROUGH IN >2500 VRU #: 001540178
	12/28/07	DA	1. No water in dwv or shower pan. 2. Connect all bath fans to their vents. 3. Electrical not firestopped in most areas of house. 4. Double 2x10 above ceiling joists upstairs supporting valley stiffknees should be 10 ft long, nailed together like a header and standing upright. Brace it off to prevent rotation.5. Remove rock fill on front porch down to foundation and flash porch wall. do not side/ DO NOT INSULATE
R427 04	1/02/08	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001541259

1-2 AP
 KS

ADDRESS : 110 ALVIS CT SUBDIV: DEXTERFIELD
CONTRACTOR : RAYNOR BUILDERS INC PHONE : (919) 639-3012
OWNER : ATKINS PLACE LLC PHONE :
PARCEL : 08-0653- - -0030- -46-
APPL NUMBER: 07-50018756 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : 401 N 8 MILE TURN LEFT ON CHALYBEATE
S/D IS ON LEFT LOT 46 JB

STRUCTURE: 000 000 50X60 4BDR
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/07 11/14/07	KS DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001519985 Soil not suitable for footing. Need engineers corection prior to pouring,
B101 02	11/20/07 11/20/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001522622 premis # 76813663 for temp power
B103 01	11/29/07 11/29/07	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001526755 be sure to remove all organics from crawl space.
A814 01	11/29/07 11/29/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001526748 110 ALVIS CT
B105 01	12/03/07 12/03/07	BS AP	R*OPEN FLOOR VRU #: 001528298
H824 01	12/10/07 12/10/07	BM DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001533785 BRYAN WROTE OP FOR WRONG LOT #, THEREFORE LOT 46 WAS FINALED IN ERROR. ADDED ENVH OPERATIONS STEP TODAY TO CORRECT THIS AND ALSO DELETED THE OP THAT WAS SCANNED UNDER THE SAME HTE # FOR LOT 46.
H824 02	12/14/07	TI	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001535723
R427 02	12/21/07 12/21/07	BS CA	FOUR TRADE ROUGH IN >2500 VRU #: 001539204 Can you come after 2 p.m. If not reschedule for thursday. Thanks (Merry Christmas) Craig
R427 01	12/21/07 12/21/07	BS CA	FOUR TRADE ROUGH IN >2500 VRU #: 001539196 Can you come after 2 p.m. If not reschedule for thursday. Thanks (Merry Christmas) Craig
R427 03	12/28/07 12/28/07	BS DA	FOUR TRADE ROUGH IN >2500 VRU #: 001540178 1. No water in dwv or shower pan. 2. Connect all bath fans to their vents. 3. Electrical not firestopped in most areas of house. 4. Double 2x10 above ceiling joists upstairs supporting valley stiffknees should be 10 ft long, nailed together like a header and standing upright. Brace it off to prevent rotation.5. Remove rock fill on front porch down to foundation and flash porch wall. do not side/ DO NOT INSULATE
R427 04	1/02/08 1/02/08	KS AP	FOUR TRADE ROUGH IN >2500 VRU #: 001541259
I129 01	1/07/08 <u>1-7-08</u>	TI <u>APBS</u>	R*INSULATION INSPECTION VRU #: 001543073

ADDRESS : 110 ALVIS CT
 CONTRACTOR : RAYNOR BUILDERS INC
 OWNER : ATKINS PLACE LLC
 PARCEL : 08-0653- - -0030- -46-
 APPL NUMBER: 07-50018756 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : 401 N 8 MILE TURN LEFT ON CHALYBEATE
 S/D IS ON LEFT LOT 46 JB

SUBDIV: DEXTERFIELD
 PHONE : (919) 639-3012
 PHONE :

STRUCTURE: 000 000 50X60 4BDR
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	11/14/07 11/14/07	KS DA	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001519985 Soil not suitable for footing. Need engineers corection prior to pouring,
B101 02	11/20/07 11/20/07	BS AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001522622 premis # 76813663 for temp power
B103 01	11/29/07 11/29/07	BS AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001526755 be sure to remove all organics from crawl space.
A814 01	11/29/07 11/29/07	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001526748 110 ALVIS CT
B105 01	12/03/07 12/03/07	BS AP	R*OPEN FLOOR VRU #: 001528298
H824 01	12/10/07 12/10/07	BM DA	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001533785 BRYAN WROTE OP FOR WRONG LOT #, THEREFORE LOT 46 WAS FINALED IN ERROR. ADDED ENVH OPERATIONS STEP TODAY TO CORRECT THIS AND ALSO DELETED THE OP THAT WAS SCANNED UNDER THE SAME HTE # FOR LOT 46.
H824 02	12/14/07 2/29/08	BM AP	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001535723
R427 02	12/21/07 12/21/07	BS CA	FOUR TRADE ROUGH IN >2500 VRU #: 001539204 Can you come after 2 p.m. If not reschedule for thursday. Thanks (Merry Christmas) Craig
R427 01	12/21/07 12/21/07	BS CA	FOUR TRADE ROUGH IN >2500 VRU #: 001539196 Can you come after 2 p.m. If not reschedule for thursday. Thanks (Merry Christmas) Craig
R427 03	12/28/07 12/28/07	BS DA	FOUR TRADE ROUGH IN >2500 VRU #: 001540178 1. No water in dwv or shower pan. 2. Connect all bath fans to their vents. 3. Electrical not firestopped in most areas of house. 4. Double 2x10 above ceiling joists upstairs supporting valley stiffknees should be 10 ft long, nailed together like a header and standing upright. Brace it off to prevent rotation.5. Remove rock fill on front porch down to foundation and flash porch wall. do not side/ DO NOT INSULATE
R427 04	1/02/08 1/02/08	KS AP	FOUR TRADE ROUGH IN >2500 VRU #: 001541259
I129 01	1/07/08 1/07/08	BS AP	R*INSULATION INSPECTION VRU #: 001543073
R431 01	2/25/08 2/26/08	KS CA	FOUR TRADE FINAL >2500 VRU #: 001567551 Operations permit not approved
R431 02	3/03/08 2/29/08	TI CA	FOUR TRADE FINAL >2500 VRU #: 001570936 CANCELLED NO OPERATION PERMIT. NJT 02/29/08
R431 03	3/04/08	TI	FOUR TRADE FINAL >2500 VRU #: 001571694

3.4.08
~~IVR~~
 R2 AP

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF COMPLIANCE**

This certificate issued pursuant to the requirements of Section 307 of the North Carolina Administration Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential
Type of Construction: IV B
Owner of Building: Rayna Builders
Building Address: 110 Alvis Ct.
Zoning District: _____
Zoning Permit No.: _____
Date: 4-4-08
Ken Stahl
Building Official

Conditional Use Permit No.: _____
Building Permit No.: _____
Electrical Permit No.: _____
Insulation Permit No.: _____
Plumbing Permit No.: _____
Mech. Permit No.: _____
Envir. C.O. No.: _____
Zoning Official