

ADDRESS . . : 184 SONORA DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER . . . : WOODSHIRE PARTNERS LLC #229
PARCEL . . . : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
LEMUEL BLACK S/D ON LEFT.JD

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	TI	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971

AP JH

T-pole passed

COMMENTS AND NOTES

ADDRESS . : 184 SONORA DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER . . : WOODSHIRE PARTNERS LLC #229 PHONE :
PARCEL . . : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931

APJV

----- COMMENTS AND NOTES -----

ADDRESS . . : 184 SONORA DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER . . . : WOODSHIRE PARTNERS LLC #229
PARCEL . . . : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
LEMUEL BLACK S/D ON LEFT.JD

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	TI	R*PLUMB UNDER SLAB VRU #: 001570909

AP JH

COMMENTS AND NOTES

ADDRESS : 184 SONORA DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER : WOODSHIRE PARTNERS LLC #229 PHONE :
PARCEL : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)

DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	JH	R*PLUMB UNDER SLAB VRU #: 001570909
	3/03/08	AP	
A814 01	3/04/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145
	2/28/08	AP	184 SONORA DR LOT 229
B105 01	3/05/08	TI	R*OPEN FLOOR VRU #: 001571884
	3/04/08	CA	This Will Be A Slab Inspection.
B111 01	3/05/08	TI	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445

3/5/08 DA DT

COMMENTS AND NOTES

ADDRESS . : 184 SONORA DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER . . : WOODSHIRE PARTNERS LLC #229 PHONE :
PARCEL . . : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	JH	R*PLUMB UNDER SLAB VRU #: 001570909
	3/03/08	AP	
A814 01	3/04/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145
	2/28/08	AP	184 SONORA DR LOT 229
B105 01	3/05/08	TI	R*OPEN FLOOR VRU #: 001571884
	3/04/08	CA	This Will Be A Slab Inspection.
B111 01	3/05/08	TI	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445
	3/05/08	DA	1. No building plans on site.
B111 02	3/07/08	TI	R*BLDG SLAB INSP VRU #: 001573203
	3/7/08	AP DT	

COMMENTS AND NOTES

ADDRESS . : 184 SONORA DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER . . : WOODSHIRE PARTNERS LLC #229 PHONE :
PARCEL . . : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	JH	R*PLUMB UNDER SLAB VRU #: 001570909
	3/03/08	AP	
A814 01	3/04/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145
	2/28/08	AP	184 SONORA DR LOT 229
B105 01	3/05/08	TI	R*OPEN FLOOR VRU #: 001571884
	3/04/08	CA	This Will Be A Slab Inspection.
B111 01	3/05/08	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445
	3/05/08	DA	1. No building plans on site.
B111 02	3/07/08	DT	R*BLDG SLAB INSP VRU #: 001573203
	3/07/08	AP	
R425 01	3/31/08	TI	FOUR TRADE ROUGH IN VRU #: 001585216

Op JH

----- COMMENTS AND NOTES -----

ADDRESS : 184 SONORA DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC #229
PARCEL : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
LEMUEL BLACK S/D ON LEFT.JD

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08 2/15/08	JH AP	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971 t-pole passed
B103 01	2/22/08 2/21/08	TI CA	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138 VOICE MESSAGE LEFT
B103 02	2/26/08 2/26/08	JH AP	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
P309 01	3/03/08 3/03/08	JH AP	R*PLUMB UNDER SLAB VRU #: 001570909
A814 01	3/04/08 2/28/08	TI AP	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145 184 SONORA DR LOT 229
B105 01	3/05/08 3/04/08	TI CA	R*OPEN FLOOR VRU #: 001571884 This Will Be A Slab Inspection.
B111 01	3/05/08 3/05/08	DT DA	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445 1. No building plans on site.
B111 02	3/07/08 3/07/08	DT AP	R*BLDG SLAB INSP VRU #: 001573203
R425 01	3/31/08 3/31/08	JH DP	FOUR TRADE ROUGH IN VRU #: 001585216 1)Missing nails in floor truss hangers in garage. 2)Missing 1 lvl in garage @ floor truss. 3)Need @ least 2 jack studs under ends of lvls in back left corner of garage. 4)Fire caulk @ top plate behind water heater . 5)roof boots need to be on . 6)Missing studs behind all tubs & showers upstairs. 7)Nail all roof girder truss per drawings. 8)All hanger nails in 45degree angle holes need to be nail with @ least a 10D common nail. 9)Missing uplift clips on E1 truss. 10)Need 2 2x12 for headers over triple windows with 2 jack studs.
R425 02	4/07/08 4/7/08	TI DP DT	FOUR TRADE ROUGH IN VRU #: 001588892

COMMENTS AND NOTES

ADDRESS : 184 SONORA DR
 CONTRACTOR : CAVINESS LAND DEVELOPMENT
 OWNER : WOODSHIRE PARTNERS LLC #229
 PARCEL : 01-0536-06- -0028- -69-
 APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
 LEMUEL BLACK S/D ON LEFT.JD

SUBDIV: WOODSHIRE PH 5
 PHONE : (919) 481-0503
 PHONE :

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	JH	R*PLUMB UNDER SLAB VRU #: 001570909
	3/03/08	AP	
A814 01	3/04/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145
	2/28/08	AP	184 SONORA DR LOT 229
B105 01	3/05/08	TI	R*OPEN FLOOR VRU #: 001571884
	3/04/08	CA	This Will Be A Slab Inspection.
B111 01	3/05/08	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445
	3/05/08	DA	1. No building plans on site.
B111 02	3/07/08	DT	R*BLDG SLAB INSP VRU #: 001573203
	3/07/08	AP	
R425 01	3/31/08	JH	FOUR TRADE ROUGH IN VRU #: 001585216
	3/31/08	DP	1)Missing nails in floor truss hangers in garage. 2)Missing 1 lvl in garage @ floor truss. 3)Need @ least 2 jack studs under ends of lvls in back left corner of garage. 4)Fire caulk @ top plate behind water heater . 5)roof boots need to be on . 6)Missing studs behind all tubs & showers upstairs. 7)Nail all roof girder truss per drawings. 8)All hanger nails in 45degree angle holes need to be nail with @ least a 10D common nail. 9)Missing uplift clips on E1 truss. 10)Need 2 2x12 for headers over triple windows with 2 jack studs.
R425 02	4/07/08	DT	FOUR TRADE ROUGH IN VRU #: 001588892
	4/07/08	DP	LVL's still missing jack studs. No truss documents in box
R427 01	4/09/08	TI	FOUR TRADE ROUGH IN >2500 VRU #: 001590439

AP-MR

COMMENTS AND NOTES

ADDRESS . : 184 SONORA DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER . . : WOODSHIRE PARTNERS LLC #229 PHONE :
PARCEL . . : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
FLOOD ZONE . . . : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	JH	R*PLUMB UNDER SLAB VRU #: 001570909
	3/03/08	AP	
A814 01	3/04/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145
	2/28/08	AP	184 SONORA DR LOT 229
B105 01	3/05/08	TI	R*OPEN FLOOR VRU #: 001571884
	3/04/08	CA	This Will Be A Slab Inspection.
B111 01	3/05/08	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445
	3/05/08	DA	1. No building plans on site.
B111 02	3/07/08	DT	R*BLDG SLAB INSP VRU #: 001573203
	3/07/08	AP	
R425 01	3/31/08	JH	FOUR TRADE ROUGH IN VRU #: 001585216
	3/31/08	DP	1)Missing nails in floor truss hangers in garage. 2)Missing 1 lvl in garage @ floor truss. 3)Need @ least 2 jack studs under ends of lvls in back left corner of garage. 4)Fire caulk @ top plate behind water heater . 5)roof boots need to be on . 6)Missing studs behind all tubs & showers upstairs. 7)Nail all roof girder truss per drawings. 8)All hanger nails in 45degree angle holes need to be nail with @ least a 10D common nail. 9)Missing uplift clips on E1 truss. 10)Need 2 2x12 for headers over triple windows with 2 jack studs.
R425 02	4/07/08	DT	FOUR TRADE ROUGH IN VRU #: 001588892
	4/07/08	DP	LVL's still missing jack studs. No truss documents in box
R427 01	4/09/08	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001590439
	4/09/08	AP	
I129 01	4/11/08	TI	R*INSULATION INSPECTION VRU #: 001591897

AP JH

ADDRESS : 184 SONORA DR SUBDIV: WOODSHIRE PH 5
 CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
 OWNER : WOODSHIRE PARTNERS LLC #229 PHONE :
 PARCEL : 01-0536-06- -0028- -69-
 APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
 LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
 FLOOD ZONE : FLOOD ZONE X

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	JH	R*PLUMB UNDER SLAB VRU #: 001570909
	3/03/08	AP	
A814 01	3/04/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145
	2/28/08	AP	✓ 184 SONORA DR LOT 229
B105 01	3/05/08	TI	R*OPEN FLOOR VRU #: 001571884
	3/04/08	CA	This Will Be A Slab Inspection.
B111 01	3/05/08	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445
	3/05/08	DA	1. No building plans on site.
B111 02	3/07/08	DT	R*BLDG SLAB INSP VRU #: 001573203
	3/07/08	AP	
R425 01	3/31/08	JH	FOUR TRADE ROUGH IN VRU #: 001585216
	3/31/08	DP	1)Missing nails in floor truss hangers in garage. 2)Missing 1 lvl in garage @ floor truss. 3)Need @ least 2 jack studs under ends of lvls in back left corner of garage. 4)Fire caulk @ top plate behind water heater . 5)roof boots need to be on . 6)Missing studs behind all tubs & showers upstairs. 7)Nail all roof girder truss per drawings. 8)All hanger nails in 45degree angle holes need to be nail with @ least a 10D common nail. 9)Missing uplift clips on E1 truss. 10)Need 2 2x12 for headers over triple windows with 2 jack studs.
R425 02	4/07/08	DT	FOUR TRADE ROUGH IN VRU #: 001588892
	4/07/08	DP	LVL's still missing jack studs. No truss documents in box
R427 01	4/09/08	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001590439
	4/09/08	AP	
I129 01	4/11/08	JH	R*INSULATION INSPECTION VRU #: 001591897
	4/11/08	AP	
H824 01	6/18/08	JW	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001629187
	6/18/08	AP	
R429 01	9/03/08	TI	FOUR TRADE FINAL VRU #: 001671060

IVR

ADDRESS : 184 SONORA DR SUBDIV: WOODSHIRE PH 5
CONTRACTOR : CAVINESS LAND DEVELOPMENT PHONE : (919) 481-0503
OWNER : WOODSHIRE PARTNERS LLC #229 PHONE :
PARCEL : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)

FLOOD ZONE : FLOOD ZONE X
BEDROOMS : 3.00 PROPOSED USE : SFD
SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	JH	R*PLUMB UNDER SLAB VRU #: 001570909
	3/03/08	AP	
A814 01	3/04/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145
	2/28/08	AP	184 SONORA DR LOT 229
B105 01	3/05/08	TI	R*OPEN FLOOR VRU #: 001571884
	3/04/08	CA	This Will Be A Slab Inspection.
B111 01	3/05/08	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445
	3/05/08	DA	1. No building plans on site.
B111 02	3/07/08	DT	R*BLDG SLAB INSP VRU #: 001573203
	3/07/08	AP	
R425 01	3/31/08	JH	FOUR TRADE ROUGH IN VRU #: 001585216
	3/31/08	DP	1)Missing nails in floor truss hangers in garage. 2)Missing 1 lvl in garage @ floor truss. 3)Need @ least 2 jack studs under ends of lvls in back left corner of garage. 4)Fire caulk @ top plate behind water heater . 5)roof boots need to be on . 6)Missing studs behind all tubs & showers upstairs. 7)Nail all roof girder truss per drawings. 8)All hanger nails in 45degree angle holes need to be nail with @ least a 10D common nail. 9)Missing uplift clips on E1 truss. 10)Need 2 2x12 for headers over triple windows with 2 jack studs.
R425 02	4/07/08	DT	FOUR TRADE ROUGH IN VRU #: 001588892
	4/07/08	DP	LVL's still missing jack studs. No truss documents in box
R427 01	4/09/08	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001590439
	4/09/08	AP	
I129 01	4/11/08	JH	R*INSULATION INSPECTION VRU #: 001591897
	4/11/08	AP	
H824 01	6/18/08	JW	ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001629187
	6/18/08	AP	

ADDRESS . : 184 SONORA DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER . . : WOODSHIRE PARTNERS LLC #229
PARCEL . . : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

REQUESTED INSP DESCRIPTION
TYP/SQ COMPLETED RESULT RESULTS/COMMENTS

R429 01 9/03/08 JH FOUR TRADE FINAL VRU #: 001671060
9/03/08 DP 1) Exhaust fan in half bath not wired.
2) Missing light & switch in closet in front left bedroom
upstairs.
3) window in stairway not tempered.
4) Outside faucet on front of house not attached to house.
5) Breaker for condensing unit on side of house to big.
R431 01 9/04/08 TI FOUR TRADE FINAL >2500 VRU #: 001671874
9/14/08 SA DI

----- COMMENTS AND NOTES -----

ADDRESS : 184 SONORA DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER : WOODSHIRE PARTNERS LLC #229
PARCEL : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 01	9/03/08 9/03/08	JH DP	FOUR TRADE FINAL VRU #: 001671060 1) Exhaust fan in half bath not wired. 2) Missing light & switch in closet in front left bedroom upstairs. 3) window in stairway not tempered. 4) Outside faucet on front of house not attached to house. 5) Breaker for condensing unit on side of house to big.
R431 01	9/04/08 9/04/08	DT CA	FOUR TRADE FINAL >2500 VRU #: 001671874
R429 02	9/10/08	TI DP-MR	FOUR TRADE FINAL VRU #: 001674904

COMMENTS AND NOTES

ADDRESS : 184 SONORA DR
 CONTRACTOR : CAVINESS LAND DEVELOPMENT
 OWNER : WOODSHIRE PARTNERS LLC #229
 PARCEL : 01-0536-06- -0028- -69-
 APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
 LEMUEL BLACK S/D ON LEFT.JD

SUBDIV: WOODSHIRE PH 5
 PHONE : (919) 481-0503
 PHONE :

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)

FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	JH	R*PLUMB UNDER SLAB VRU #: 001570909
	3/03/08	AP	
A814 01	3/04/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145
	2/28/08	AP	✓184 SONORA DR LOT 229
B105 01	3/05/08	TI	R*OPEN FLOOR VRU #: 001571884
	3/04/08	CA	This Will Be A Slab Inspection.
B111 01	3/05/08	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445
	3/05/08	DA	1. No building plans on site.
B111 02	3/07/08	DT	R*BLDG SLAB INSP VRU #: 001573203
	3/07/08	AP	
R425 01	3/31/08	JH	FOUR TRADE ROUGH IN VRU #: 001585216
	3/31/08	DP	1)Missing nails in floor truss hangers in garage. 2)Missing 1 lvl in garage @ floor truss. 3)Need @ least 2 jack studs under ends of lvls in back left corner of garage. 4)Fire caulk @ top plate behind water heater . 5)roof boots need to be on . 6)Missing studs behind all tubs & showers upstairs. 7)Nail all roof girder truss per drawings. 8)All hanger nails in 45degree angle holes need to be nail with @ least a 10D common nail. 9)Missing uplift clips on E1 truss. 10)Need 2 2x12 for headers over triple windows with 2 jack studs.
R425 02	4/07/08	DT	FOUR TRADE ROUGH IN VRU #: 001588892
	4/07/08	DP	LVL's still missing jack studs. No truss documents in box
R427 01	4/09/08	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001590439
	4/09/08	AP	
I129 01	4/11/08	JH	R*INSULATION INSPECTION VRU #: 001591897
	4/11/08	AP	
H824 01	6/18/08	JW	✓ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001629187
	6/18/08	AP	

ADDRESS : 184 SONORA DR SUBDIV: WOODSHIRE PH 5
 CONTRACTOR : CAVINESS BAND DEVELOPMENT PHONE : (919) 481-0503
 OWNER : WOODSHIRE PARTNERS LLC #229 PHONE :
 PARCEL : 01-0536-06- -0028- -69-
 APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)
 DIRECTIONS : WOODSHIRE #229-27W TO NURSERY RD TO
 LEMUEL BLACK S/D ON LEFT.JD

STRUCTURE: 000 000 56X34 3BR W/GARAGE (02)
 FLOOD ZONE : FLOOD ZONE X
 # BEDROOMS : 3.00 PROPOSED USE : SFD
 SEPTIC - EXISTING? : NEW

PERMIT: CPSF 00 CP * SFD

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
B101 01	2/15/08	JH	R*BLDG FOOTING / TEMP SVC POLE VRU #: 001563971
	2/15/08	AP	t-pole passed
B103 01	2/22/08	TI	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567138
	2/21/08	CA	VOICE MESSAGE LEFT
B103 02	2/26/08	JH	R*BLDG FOUND & TEMP SVC POLE VRU #: 001567931
	2/26/08	AP	
P309 01	3/03/08	JH	R*PLUMBS UNDER SLAB VRU #: 001570909
	3/03/08	AP	
A814 01	3/04/08	TI	ADDRESS CONFIRMATION TIME: 17:00 VRU #: 001569145
	2/28/08	AP	✓ 184 SONORA DR LOT 229
B105 01	3/05/08	TI	R*OPEN FLOOR VRU #: 001571884
	3/04/08	CA	This Will Be A Slab Inspection.
B111 01	3/05/08	DT	R*BLDG SLAB INSP TIME: 17:00 VRU #: 001572445
	3/05/08	DA	1. No building plans on site.
B111 02	3/07/08	DT	R*BLDG SLAB INSP VRU #: 001573203
	3/07/08	AP	
R425 01	3/31/08	JH	FOUR TRADE ROUGH IN VRU #: 001585216
	3/31/08	DP	1)Missing nails in floor truss hangers in garage. 2)Missing 1 lvl in garage @ floor truss. 3)Need @ least 2 jack studs under ends of lvls in back left corner of garage. 4)Fire caulk @ top plate behind water heater . 5)roof boots need to be on . 6)Missing studs behind all tubs & showers upstairs. 7)Nail all roof girder truss per drawings. 8)All hanger nails in 45degree angle holes need to be nail with @ least a 10D common nail. 9)Missing uplift clips on E1 truss. 10)Need 2 2x12 for headers over triple windows with 2 jack studs.
R425 02	4/07/08	DT	FOUR TRADE ROUGH IN VRU #: 001588892
	4/07/08	DP	LVL's still missing jack studs. No truss documents in box
R427 01	4/09/08	MR	FOUR TRADE ROUGH IN >2500 VRU #: 001590439
	4/09/08	AP	
I129 01	4/11/08	JH	R*INSULATION INSPECTION VRU #: 001591897
	4/11/08	AP	
H824 01	6/18/08	JW	✓ ENVIR. OPERATIONS PERMIT TIME: 17:00 VRU #: 001629187
	6/18/08	AP	

ADDRESS . . : 184 SONORA DR
CONTRACTOR : CAVINESS LAND DEVELOPMENT
OWNER . . . : WOODSHIRE PARTNERS LLC #229
PARCEL . . . : 01-0536-06- -0028- -69-
APPL NUMBER: 07-50019047 CP NEW RESIDENTIAL (SFD)

SUBDIV: WOODSHIRE PH 5
PHONE : (919) 481-0503
PHONE :

TYP/SQ	REQUESTED COMPLETED	INSP RESULT	DESCRIPTION RESULTS/COMMENTS
R429 01	9/03/08 9/03/08	JH DP	FOUR TRADE FINAL VRU #: 001671060 1) Exhaust fan in half bath not wired. 2) Missing light & switch in closet in front left bedroom upstairs. 3) window in stairway not tempered. 4) Outside faucet on front of house not attached to house. 5) Breaker for condensing unit on side of house to big.
R431 01	9/04/08 9/04/08	DT CA	FOUR TRADE FINAL >2500 VRU #: 001671874
R429 02	9/10/08 9/10/08	MR DP	FOUR TRADE FINAL VRU #: 001674904 still need tempered window
R431 02	9/11/08 <u>9/11/08</u>	TI <u>AP DT</u>	FOUR TRADE FINAL >2500 VRU #: 001675586

----- COMMENTS AND NOTES -----

**COUNTY OF HARNETT
DEPARTMENT OF BUILDING INSPECTION
AND PLANNING/DEVELOPMENT
CERTIFICATE OF OCCUPANCY**

This certificate issued pursuant to the requirements of Section 105 of the North Carolina State Building Code and the Harnett County Zoning Ordinance certifies at the time of issuance this structure was in compliance with the various ordinances of the County of Harnett regulating development and building construction or use. For the following:

Use Classification: Residential

Owner: Woodshire Partners

911 Address: 184 Soora

State: NC Zip Code: _____

Date: 9/11/08

D. E. T. E.
Building Official

PERMIT NUMBERS

Building Permit No.: _____

Electrical Permit No.: _____

Insulation Permit No.: _____

Plumbing Permit No.: _____

Mech. Permit No.: 07-50019047

MFG. Home: _____